



**FAY, SPOFFORD &
THORNDIKE**
5 Burlington Woods
Burlington, MA 01803
Toll Free: 800.835.8666
T: 781.221.1000
F: 781.229.1115
www.fstinc.com

October 14, 2010

Office of Community Development
Homer Municipal Building
19 Moore Street
Belmont, Massachusetts 02478
Attn: Mr. Glenn Clancy, Director

Subject: Belmont, Massachusetts
Evaluation of Sewers and Storm Drains to Identify Illicit
Connections in Areas Tributary to Outfalls 1, 2 & 10
Report of Findings

Dear Mr. Clancy:

This Report of Findings (ROF) outlines Fay, Spofford & Thorndike's (FST) sewer and storm drain investigations to identify illicit connections in areas tributary to Unity Ave. (Outfall 1), Huron Ave. (Outfall 2) and Winn's Brook (Outfall 10). Various neighborhoods in these areas have undergone sewer and storm drain rehabilitation including lining, service and mainline replacements, point repairs and manhole replacements. However, as described in the "2008 Storm Water Sampling and Analysis Program", December 2008 report, contamination levels at these outfalls have improved but are still above the DEP threshold (235 E. Coli Colonies per 100 mL Sample). This ROF includes a summary of investigations performed in each tributary area and provides recommendations for rehabilitation and/or further investigations.

METHODOLOGY

In accordance with the recommendations of the 2008 report, areas that consistently exceeded 5,000 E. Coli colonies per 100mL (E. Coli) were the targets of these investigations. Building inspections, dyed-water testing and CCTV inspection were used to identify direct (sewer service connected to storm drain) and indirect (defect in sewer service or mainline exfiltrating to the storm drain) illicit connections.

In areas that have undergone previous rehabilitation, inspections and dyed-water testing were conducted in buildings originally flagged as direct or indirect sources during the 2001/2002 dyed-water testing program. CCTV inspection was not conducted in these areas. In new areas (i.e. no previous rehabilitation), inspection and dyed-water testing was attempted at all of the buildings. Sewers and storm drains in new areas were CCTV inspected, including with dyed-water flooding were applicable (i.e. sewer located above drain).

Building Inspections & Dyed-Water Testing

Building inspections consist of a thorough inspection of basement sewer plumbing to identify all discharge locations from the house. The dyed-water test involves introducing dyed-water into a plumbing fixture, typically a sink or toilet. An inspector then monitors the downstream sewer and storm drain manholes in the vicinity of the building to determine the discharge location. For buildings with multiple sewer stacks, a separate dyed-water test was conducted for each stack.

CCTV Inspection and Dyed-water Flooding

CCTV inspection establishes the condition of the pipe section and identifies exact locations of exfiltration point sources in the sewer (i.e. holes or cracks). Dyed-water flooding involves introducing large quantities of dyed-water into an upstream sewer manhole to simulate a surcharged or heavy flow condition. During CCTV inspection, the dyed-water may be observed leaking into the storm drain if an exfiltration source is present in the above sewer.

RESULTS AND RECOMMENDATIONS

Dyed-water testing and CCTV inspection results are provided in Tables 1 and 2, respectively, and illustrated in Figures 1-4. In the figures, target areas are identified by sample numbers, which are provided along with the highest sample result recorded (E. Coli). For each individual sanitary sewer and storm drain section, Table 2 provides a detailed description of the recommended rehabilitation. Table 3 summarizes the complete sampling data for each location.

Figure 5 displays a graphical summary of all sewer and storm drain replacement and lining completed to date, inclusive of current Contract 1 - Sewer and Storm Drain Rehabilitation Wellington Brook Tributary Area. The results and recommendations for each tributary area are discussed below.

OUTFALL AREA 1 (Figure 1)

18 - Houses Targeted for Dyed-Water Testing

17 - Negative (to sewer)

1 - Positive (indirect)

Payson Road at Fairview Avenue (Sample OF1E2B)

Approximately 300' of sewer and 690' of storm drain were CCTV inspected upstream of Sample OF1E2B. CCTV inspection showed both the sewer and the storm drain to be in fair to good condition. One sewer exfiltration point source was identified at a moderate/severe crack. However, with the sewer installed below the storm drain, the mainline does not appear to be a contributor of contamination. Sewer services from the targeted buildings were successfully dyed-water tested and showed no contamination to the storm drain. Table 3 shows that only the first of 5 samples returned a high E. Coli number (>15,000).

As a result of these investigations, we do not believe a significant illicit connection exists in this area. To maintain structural integrity, we recommend two sewer point repairs and the lining of one section (172'). Refer to Table 2 for details.

Fairview Avenue between Payson Road and Lewis Road (Sample OF1E3D)

Dyed-water tracing identified 58 Van Ness Rd. (service to Van Ness Rd.) as an indirect source upstream of Sample OF1E3D. Sewer section 03S022-03S007 on Van Ness Rd. was televised and dyed-water flooded. However, the CCTV inspection was incomplete due to access limitations and broken service connection and did not reach the service from 58 Van Ness Rd. Dyed-water flooding identified no contamination to the storm drain, indicating the contamination emanates from the sewer service at 58 Van Ness Rd. House 58 was dyed-water tested in 2001/2002 with no dye observed in the storm drain. Both the sewer and storm drain mainlines on Fairview Ave. have been lined to Payson Rd. A 10" VCP drain that tees into the mainline, approximately 290 ft from 03D008, has steady flow but its origin is unknown.

We recommend replacement of the broken service connection to complete CCTV inspection of section 03S022-03S007 and the sewer service at 58 Van Ness Rd. The Town may also consider installation of a manhole on the 10" VCP drain to allow CCTV inspection.

OUTFALL AREA 2 (Figure 2)

- 113 - Houses Targeted for Dyed-Water Testing
- 88 - Negative (to sewer)
- 2 - Positive (direct)
- 9 - Positive (indirect)
- 3 - Undetermined (not in sewer or storm drain)
- 11 - No Inspection

All streets tributary to Dalton Rd. including Washington St., Sharpe Rd., Shaw Rd., Livermore Rd., Betts Rd., Grosvenor Rd. and Sargent Rd. exhibited dry weather storm drain samples greater than 15,000 E. Coli colonies per 100 mL. All but two tributaries along Dalton Rd. had dyed-water identified in the storm drain from either a direct or indirect source. The sewer in this area is generally located above the storm drain, allowing sewage exfiltration to easily infiltrate the storm drain below. With the exception of Sharpe Rd. and one section on Grosvenor Rd., the sewer mainlines in this area have been either replaced or lined based on previous illicit connection investigations.

Sharpe Road (Sample 10A)

Approximately 655' of sewer and 670' of storm drain were CCTV inspected upstream of Sample 10A. The sewer is located above the storm drain and is in poor condition. Many exfiltration sources were identified including moderate cracks and severely broken pipe sections at the invert. Sewer services from the targeted houses were successfully dyed-water tested and showed no contamination to the storm drain. Strangely, at 22 Sharpe Rd., dye was not identified in either the sewer or the storm drain, possibly due to a blockage.

We recommend lining of sewer sections 20S037-20S034 (510') on Sharpe Rd. and CCTV inspection of the service from house 22. One point repair and four service replacements are required prior to lining. One storm drain point repair is also required. Refer to Table 2 for details.

Washington Street (Sample 11A)

Upstream of Sample 11A all sewer mainlines have been lined. Dyed-water testing showed three buildings to be indirect sources (186, 187, 192 Washington). One building at 215 Washington St produced an inconclusive dyed-water test due to the slope of the service (standing dyed-water was present in a service manhole in the yard). One building was not dyed-water tested.

We recommend CCTV inspection of the sewer services from house numbers 186, 187 and 192 Washington St.

Shaw Road (Sample 18D & 19A)

Two indirect sources were identified upstream of Sample 18D. Dyed-water testing revealed one source to be the sewer service at 35 Shaw Rd. House 35 was dyed-water tested in 2001/2002 with no dye observed in the storm drain. The other source was a short section of non-rehabilitated sewer (09S064-09S032) that connects the sewer service at 12 Shaw Rd. to the mainline. CCTV inspection shows exfiltration sources evident by intruding roots at the joints. Two buildings were not dyed-water tested.

Upstream of Sample 19A, dyed-water testing showed sewer services at 56 and 63 Shaw Rd. to be indirect sources. Houses 56 and 63 were dyed-water tested in 2001/2002 with no dye observed in the storm drain.

We recommend replacement of section 09S064-09S032 (16') and CCTV inspection of the sewer services from house numbers 35, 56 and 63 Shaw Rd.

Livermore Road (Sample 7B & 8B)

Dyed-water testing showed all but three buildings upstream of Sample 7B connected to the sewer. 106 & 109 Shaw Rd. were not inspected or dyed-water tested. At 21 Livermore Rd., dyed-water was not identified in either the sewer or the storm drain. The 2001/2002 dyed-water testing program determined 109 to be an indirect source while no dye was observed in the storm drain from 106 and 21.

Investigations upstream of Sample 8B identified a direct connection from 69 Livermore Rd. and an indirect connection from 64 Livermore Rd. The 2001/2002 dyed-water testing program also determined 64 to be an indirect source, but no dye was observed in the storm drain from 69. According to the owner of 69 Livermore, the house has undergone significant renovations since the 2001/2002 investigations, including modifications to the main plumbing stack. The owner maintains that all work was done with proper permitting. However, we believe the plumbing stack may have been relocated and inadvertently connect to the drain service. One building was not dyed-water tested.

We recommend the Town verify that the plumbing in house number 69 Livermore Rd. has been installed in accordance with the plumbing code and direct the owner to correct any deficiencies. We also recommend CCTV inspection of the sewer services from house numbers 109 Shaw and 21 & 64 Livermore and continued efforts to dyed-water test 106 & 109 Shaw.

Betts Road (Sample 5B & 6B)

Upstream of Sample 5B, one indirect source was found at 22 Betts Rd. 22 Betts was categorized as a direct connection during the 2001/2002 dyed-water testing program and, consequently, the service was replaced to 37' in 2004. One building was not dyed-water tested.

A direct source was found from 64 Betts Rd., upstream of Sample 6B. Dyed-water placed in the sewer service was observed coming back into the house through a perimeter drain and then entering the storm drain service (cover photo). No dye was observed in the sewer main. It appears the sewer service is significantly damaged. 64 Betts was categorized as an indirect connection during the 2001/2002 dyed-water testing program.

We recommend CCTV inspection of the sewer services from house numbers 22 and 64 Betts Rd. At 22 Betts, it is possible that the cast iron portion of the service, close to and under the house, has developed a leak. Replacement of at least a portion of the sewer service at 64 Betts Rd. appears likely.

Grosvenor Road (Sample 3B2)

Approximately 227' of sewer and 241' of storm drain were CCTV inspected upstream of Sample 3B2. The sewer is located above the storm drain and has two potential exfiltration point sources of moderate and severe broken pipe. Downstream sewer manhole 09S004 is potentially exfiltrating from the pipe connections.

We recommend lining of section sewer 09S010-09S004 (227') and rehabilitation of manhole 09S004.

Sargent Road (Sample 3B1)

All houses upstream of Sample 3B1 were inspected and dyed-water tested with no dye observed entering the storm drain. The entire sewer on Sargent Rd. (2 sections) has been replaced or lined.

We recommend rehabilitation of manholes 09S005 and 09S006 as a final mitigation measure in this area.

Dalton Road

House 253 Washington St. is determined to be an indirect source. This house has three separate plumbing stacks installed below the floor slab. Each stack was separately dyed-water tested with two showing 100% dyed-water to the storm drain on Dalton Rd. and one showing dyed-water to both the sewer and the storm drain on Dalton Rd. The sewer on Dalton was lined in 2006.

Review of CCTV video from 2006 project shows no storm drain connections in the vicinity of 253 Washington, and therefore no direct connection. The sewer video shows two services in the

vicinity of 253, although, it is unclear from the video if both services were active (both were reinstated after lining). The sewer service(s) from 253 crosses over the storm drain.

We recommend CCTV inspection of the sewer service(s) from house number 253 Washington St. Given that two of the dyed-water tests went 100% to the storm drain, we suspect a service break close to the storm drain in the street. Replacement of at least a portion of the sewer service(s) at 253 Washington St. appears likely.

OUTFALL AREA 10 (Figures 3 & 4)

75 - Houses Targeted for Dyed-Water Testing

64 - Negative (to sewer)

1 - Positive (direct)

5 - Positive (indirect)

5 - No Inspection

Clafin Street (Sample 13E)

Approximately 720' of sewer and 790' of storm drain were CCTV inspected upstream of Sample 13E. The sewer was in fair to poor condition and the storm drain good to fair condition. In general, the storm drain is installed above and offset from the sewer. At the intersection of Clafin St. and Alexander Ave., the storm drain crosses under the sewer. This section of sewer on Alexander Ave. (34S035.1-34S035) was dye flooded during televising of the storm drain with no dye observed in the storm drain. This procedure was also performed in sewer sections 34S032 to 34S030 with similar negative results. All buildings dyed-water tested were connected to the sewer.

As a result of these investigations, we do not believe a significant illicit connection exists in this area. To maintain structural integrity, we recommend the lining of three 8-inch sewer sections (510') and one 15-inch storm drain section (276'). One point repair and one service replacement are also required. Refer to Table 2 for details. Sewer section 34S035.1-34S035 on Alexander is scheduled for lining in 2011 as part of the Winn's Brook Sewer Overflow Mitigation project.

Pleasant Street to Munroe Street (Sample 9E3)

Approximately 418' of sewer and 688' of storm drain were CCTV inspected upstream of Sample 9E3. The sewer was in fair condition with some minor/moderate cracks, intruding roots at some joints and one collapsing pipe section. The storm drain was in good condition with only some minor cracks. Sewer section 47S018-47S017 was dye flooded during the televising of the storm drain with no dye observed in the storm drain. Dyed-water testing identified no sources, with two buildings not inspected.

We recommend lining of sewer sections 47S018-47S017 and 43S006-43S008 (418' total). One point repair and two service replacements are required prior to lining.

Chilton Street to Cowdin Street (Sample 9B6)

Approximately 524' of sewer and 510' of storm drain were CCTV inspected upstream of Sample 9B6. Both the sewer and storm drain were in overall fair to poor condition. Sewer section 44S006-44S007 had offset joints with roots intruding along with a minor sag and some cracks exhibiting potential exfiltration sources. Dyed-water testing identified two indirect sources upstream of Sample 9B6. Both indirect sources, house nos. 22 and 23 Chilton St., are connected to deteriorated section 44S006-44S007 described above.

We recommend the lining of sewer sections 44S006-44S009 and storm drain sections 44D005-44D015 (925' total) and three service replacements. We also recommend CCTV inspection of the sewer services from house numbers 22 and 23 Chilton St.

Sherman Street (Sample 5B)

Approximately 524' of sewer and 510' of storm drain were CCTV inspected in the vicinity of sample 5B. The sewer and storm drain appeared to be in overall good condition. The sewer was dye flooded from manhole 37S022 during televising of the storm drain with no dye observed in the storm drain. Dyed-water testing identified two indirect sources upstream of Sample 5B from house 99 Sherman St. and 70 Waterhouse Rd. Both houses identified as an indirect source have sewer and storm drain services in close proximity to each other, with the storm drain located below the sewer.

We recommend CCTV inspection of the sewer and storm drain services from house numbers 99 Sherman St. and 70 Waterhouse Rd. One structural storm drain point repair is also required.

Westlund Road (Sample 3B)

All buildings upstream of Sample 3B were inspected and dyed-water tested with no sources identified. The entire sewer on Westlund Rd. (3 sections) has been replaced or lined. However, flow in the sewer is sluggish and standing sewage is evident in sewer manhole 37S030. The storm drain under manhole 37S030 (37D050-37D053) has not been rehabilitated. It is plausible that sewage is slowly exfiltrating from manhole 37S030 and not observed in the dyed-water testing.

We recommend rehabilitation of manholes 37S029, 37S030 and 37S031 as a final mitigation measure in this area.

Waterhouse Road to Hoitt Road (Sample 4H)

Dyed-water testing identified two sources upstream of Sample 4H. A direct connection was found at 67 Hoitt Rd. and an indirect connection from 55 Hoitt Rd. House 67 was dyed-water tested in 2001/2002 with no dye observed in the storm drain. House 55 was not dyed-water tested in 2001/2002. House no. 45 Waterhouse Rd. was not dyed-water tested during these or the 2001/2002 investigations. All sewer sections upstream of Sample 4H have been lined.

We recommend the sewer service be disconnected from the storm drain and reconnected to the sewer. The sewer is approximately 1'-6" above the storm drain so that complete relaying of the

service and internal plumbing modifications may be necessary for a gravity service to be maintained. We also recommend CCTV inspection of the sewer service from house number 55. Entry to 45 Waterhouse is required for 100% complete dyed-water testing in this area.

CONTINUED SAMPLING PROGRAM

The sampling program continued in areas below 5,000 E. Coli to establish a more complete database. The results and recommendations of the continued sampling program are discussed below. Sampling results are presented in Table 3.

OUTFALL AREA 2

Continued sampling at locations 12A (Elm/Foster) and 17A1 (Washington/Jackson) showed consistent low concentrations of E. Coli. *As a result of these investigations, we do not believe a significant illicit connection exists in these areas.*

Location 6H1 (Betts/Audrey) showed mixed results with some samples exceeding 5,000 E. Coli. The sewer in Audrey road has been lined and all houses confirmed connected to the sewer by the 2001 dyed-water testing program. However, as demonstrated by the case of 69 Livermore and 67 Hoitt, conditions may have changed following the 2001/2002 dyed-water tests. *Therefore, we recommend the eleven (11) houses tributary to 6H1 be dyed-water tested again.*

Similarly, location 4H (Dalton/Grosvenor) showed mixed results. The sewer on Dalton, Bacon (to Woods) and Woods has been lined and all houses confirmed connected to the sewer by the 2001/2002 dyed-water testing program. To date, no investigations have been conducted upstream on Bacon (past Woods) due the storm drain being dry (i.e. no samples collected). However, during this program, one sample was collected and showed greater than 30,000 E. Coli. *We recommend the thirteen (13) houses upstream of Bacon/Woods be dyed-water tested. We also recommend CCTV inspection of the sewer and storm drain in this area (approximately 1,025').*

OUTFALL AREA 10

Continued sampling at locations 7B (Sherman/Dean), 9C2 (Munroe), 10A (Chilton/Dean) and 13B3 (Claflin from Leonard) showed consistent low concentrations of E. Coli. *As a result of these investigations, we do not believe a significant illicit connection exists in these areas.*

Locations 1E (Brighton/Hoitt) and 1F1 (Brighton/Cross) showed mixed results with 5 of 8 samples exceeding 5,000 E. Coli. *We recommend the twenty-one (21) houses along this storm drain be dyed-water tested. We also recommend CCTV inspection of the sewer and storm drain in this area (approximately 2,020').*

Almost all of the sewer mains and service connections in the area tributary to sample location 2D (Statler/Newcastle) are being replaced as part of the Winn's Brook Sewer Overflow Mitigation project. The project is anticipated to be complete by July 2011. *We recommend location 2 be resampled in July 2011 upon completion of the ongoing project.*

Locations 9C and 9A1 are downstream of confirmed illicit sources in the vicinity of Cowdin St. *We recommend locations 9C and 9A1 be resampled in upon completion of the rehabilitation work on Cowdin St.*

SUMP PUMPS

Building inspections identified numerous sump pumps illegally connected to the sewer system as noted in Table 4. Fifteen (15) of the illicit sump pumps identified are not currently included in recommended SSES work. FST recommends these locations be added to any future sump pump removal program conducted by the Town.

SUMMARY OF RECOMMENDED WORK & OPINION OF PROBABLE COST

FST's opinion of probable cost (OPC) to implement the recommended scope of additional investigations is **\$75,100**. A detailed breakdown is presented in Table 5 and summarized below:

- 3,045 ft sewer and storm drain CCTV inspection
- 48 house inspections/dyed-water tests (includes unsuccessful attempts from these investigations)
- 19 sewer service CCTV inspections

The design and construction OPC is based on inclusion of the recommended work into a larger sewer rehabilitation contract. Including contractor's overhead & profit, engineering services, contingencies and police details, the OPC is approximately **\$752,000**. A detailed breakdown is presented in Table 6 and summarized below:

- 2,360 ft sewer lining
- 680 ft storm drain lining
- 16 ft sewer replacement
- 7 point repairs
- 11 service replacements (main to edge of roadway)
- 1 service replacements (main to house)
- 19 probable service lining or replacements (CCTV required)
- 6 manhole rehabilitations

The recommended additional investigations can commence at any time. CCTV inspection of the 19 suspect services is required to complete design of the rehabilitation work. As previously mentioned, we recommend combining the illicit connection rehabilitation work into one construction contract with I/I removal related sewer rehabilitation.

We are available to meet with you to discuss the findings of this report at any time upon your request.

Very truly yours,
FAY, SPOFFORD & THORNDIKE, LLC.
By


Justin D. Gould, P.E.
Senior Principal Engineer

cc: Mr. Kevin Brander, MADEP

S:\JB-235 Belmont 2009 Illicit\Report\Draft Follow up Report Outfalls 1-2-10.doc

BELMONT, MASSACHUSETTS
OUTFALL AREAS 1, 2 & 10

TABLE 1
RESULTS OF DYED - WATER TESTING
MAY / JUNE 2009

Outfall No.	Address		No. of Tests Conducted	Dye Test Entry	% Sewer	% Storm Drain	Dye Discharge		Sump Pumps	Sump Pump Discharge	Other Pipes	Sump Pit	Flow in Storm Drain
	No.	Street					Direct/Indirect Connection	Contaminate Source					
1	267	Payson Road	1	Basement Sink	100	0							
1	269	Payson Road	1	Basement Sink	100	0							Minimal
1	271	Payson Road	1	Basement Sink	100	0						1	Yes
1	275	Payson Road	1	Basement Sink	100	0							No
1	302	Payson Road	1	Basement Sink	100	0							No
1	308	Payson Road	2	Basement Toilet, First Floor Sink	100	0							Yes
1	314	Payson Road	1	Basement Toilet	100	0							Yes
1	324	Payson Road	1	Basement Sink	100	0							Yes
1	50	Pequossette Road	1	Basement Sink	100	0							Yes
1	53	Pequossette Road	1	Basement Sink	100	0					Open Pipe	1	Yes
1	146	Fairview Ave	1	Basement Sink	100	0					Separate Drain Pipe		No
1	157	Fairview Ave	1	First Floor Toilet	100	0							Yes
1	160	Fairview Ave	1	Basement Sink	100	0							Yes
1	165	Fairview Ave	2	Basement Sink, First Floor Toilet	100	0					Separate Drain Pipe		Yes
1	179	Fairview Ave	1	Basement Sink	100	0							Yes
1	58	Van Ness Road	1	First Floor Toilet	80	20	Indirect	Adjacent Drain Service	1	Ground Surface			Yes
1	55	Van Ness Road	1	First Floor Sink	100	0			1	Ground Surface	Open Pipe	1	Yes
1	75	Stults Road	1	Basement Sink	100	0						1	Yes
2	22	Sharpe Road	2	Basement Toilet (2)	0	0	Inconclusive	Defective Sewer Service					Yes
2	10	Sharpe Road	2	Basement Toilet, First Floor Toilet	100	0							Yes
2	11	Sharpe Road	1	Basement Toilet	100	0							Yes
2	16	Sharpe Road	1	Basement Toilet	100	0						1	Yes
2	19	Sharpe Road	1	Basement Toilet	100	0							Yes
2	23	Sharpe Road	2	Basement Toilet, First Floor Toilet	100	0							Yes
2	192	Washington Street	1	Basement Sink	70	30	Indirect	Defective Sewer Service					Yes
2	186	Washington Street	1	Basement Sink	80	20	Indirect	Defective Sewer Service	1	Ground Surface			Yes
2	187	Washington Street	2	Basement Sink, First Floor Toilet	98	2	Indirect	Defective Sewer Service				1	Yes
2	215	Washington Street	2	Basement Toilet, First Floor Toilet	0	0	Inconclusive	Defective Sewer Service					Yes
2	181	Washington Street	1	First Floor Sink	100	0			1	Sanitary Sewer		1	Minimal
2	182	Washington Street	1	Basement Sink	100	0			1	Ground Surface		1	Yes
2	198	Washington Street	1	Basement Sink	100	0			2	Into Ground		2	Yes
2	219	Washington Street	1	Basement Sink	100	0							Yes
2	228	Washington Street	1	Basement Sink	100	0							Yes
2	231	Washington Street	1	Basement Sink	100	0			2	Ground Surface		2	Yes
2	232	Washington Street	1	Basement Sink	100	0					Separate Drain Pipe	1	Yes
2	237	Washington Street	1	Basement Sink	100	0					Separate Drain Pipe	2	Yes
2	240	Washington Street	1	Basement Sink	100	0							Yes
2	245	Washington Street	1	Basement Toilet	100	0							Yes
2	248	Washington Street	1	Basement Sink	100	0							Yes
2	254	Washington Street	1	Basement Sink	100	0							Yes
2	275	Washington Street	1	Basement Sink	100	0							Yes
2	303	School Street	1	Basement Sink	100	0							Yes
2	316	School Street	2	Basement Sink, First Floor Toilet	100	0			1	Ground Surface		1	Yes
2	56	Shaw Road	1	Basement Toilet	95	5	Indirect						Yes
2	63	Shaw Road	2	Basement Sink, First Floor Toilet	85	15	Indirect	Defective Sewer Service	1	Ground Surface		1	Yes
2	62	Shaw Road	2	Basement Sink, First Floor Toilet	100	0						1	Yes
2	35	Shaw Road	1	First Floor Toilet	85	15	Indirect	Defective Sewer Service					Yes
2	12	Shaw Road	3	Basement Sink (2), First Floor Toilet	90	10	Indirect	Defective Sewer Service (09S064-09S032)	1	Storm Drain MH		1	Yes
2	9	Shaw Road	2	Basement Sink, Second Floor Tub	100	0							Yes
2	19	Shaw Road	2	Basement Sink, Second Floor Shower	100	0					Basement Drain		Minimal
2	24	Shaw Road	1	Basement Sink	100	0							Yes
2	25	Shaw Road	1	Basement Sink	100	0							Yes
2	36	Shaw Road	1	Basement Sink	100	0			1	Ground Surface		1	Minimal
2	42	Shaw Road	2	Basement Sink (2)	100	0							Yes
2	43	Shaw Road	2	Basement Sink, Second Floor Tub	100	0			1	Ground Surface		1	Yes

BELMONT, MASSACHUSETTS
OUTFALL AREAS 1, 2 & 10

TABLE 1
RESULTS OF DYED - WATER TESTING
MAY / JUNE 2009

Outfall No.	Address		No. of Tests Conducted	Dye Test Entry	% Sewer	% Storm Drain	Dye Discharge			Sump Pumps	Sump Pump Discharge	Other Pipes	Sump Pit	Flow in Storm Drain
	No.	Street					Direct/Indirect Connection	Contaminate Source						
2	21	Livernmore Road	2	Basement Toilet, First Floor Toilet	0	0	Inconclusive	Defective Sewer Service		2	Ground Surface		2	No
2	9	Livernmore Road	2	First Floor Toilet (2)	100	0								No
2	20	Livernmore Road	1	Basement Sink	100	0				1	Ground Surface		1	No
2	26	Livernmore Road	1	Basement Sink	100	0								No
2	29	Livernmore Road	1	Basement Sink	100	0								No
2	32	Livernmore Road	1	Basement Sink	100	0								No
2	38	Livernmore Road	2	Basement Sink, Basement Toilet	100	0				1	Ground Surface		1	No
2	39	Livernmore Road	2	Basement Sink, First Floor Toilet	100	0								Yes
2	44	Livernmore Road	1	Basement Sink	100	0								Yes
2	47	Livernmore Road	2	Basement Sink, Basement Toilet	100	0				2	Sanitary Sewer, Ground Surface	Separate Drain Pipe	2	Yes
2	50	Livernmore Road	1	Basement Sink	100	0				1			Ground Surface	1
2	9	Houghton Road	3	Basement Sink (2), Basement Toilet	100	0								Yes
2	10	Houghton Road	1	Basement Sink	100	0								Standing Water
2	16	Houghton Road	2	Basement Toilet, First Floor Toilet	100	0								Standing Water
2	92	Shaw Road	2	Basement Toilet, First Floor Toilet	100	0								Standing Water
2	97	Shaw Road	1	Basement Sink	100	0								Yes
2	98	Shaw Road	2	Basement Sink, Basement Toilet	100	0								Yes
2	103	Shaw Road	2	Basement Sink, Basement Toilet	100	0								Minimal
2	112	Shaw Road	2	Basement Sink, First Floor Sink	100	0								Yes
2	64	Livernmore Road	2	Basement Sink, Basement Sink	80	20	Indirect	Defective Sewer Service		1	Ground Surface	Basement Drain		Yes
2	69	Livernmore Road	2	Basment Sink, Second Floor Tub	0	100							Direct to Strom Drain	1
2	54	Livernmore Road	1	Basement Sink	100	0							1	Yes
2	55	Livernmore Road	1	First Floor Sink	100	0								Yes
2	60	Livernmore Road	3	Basement Sink, First Floor Sink, Second Floor Sink	100	0								Yes
2	70	Livernmore Road	1	Basement Sink	100	0								Yes
2	79	Livernmore Road	1	Basement Sink	100	0								Standing Water
2	84	Livernmore Road	1	Basement Sink	100	0				1	Ground Surface			Standing Water
2	10	Hartley Road	1	Basement Sink	100	0				1	Ground Surface			Standing Water
2	15	Hartley Road	2	Basement Sink, First Floor Toilet	100	0				1	Sanitary Sewer	Separate Drain Pipe	1	No
2	22	Hartley Road	1	Basement Sink	100	0				1	Ground Surface		1	No
2	9	Herbert Road	1	Basement Sink	100	0								No
2	10	Herbert Road	1	Basement Sink	100	0								No
2	14	Herbert Road	1	Basement Sink	100	0						Open Pipe		No
2	64	Betts Road	1	Basement Sink	0	100	Direct/Indirect	Adjacent Drain Service				Open Pipe, Basement Drain	1	No
2	61	Betts Road	3	Basement Sink, First Floor Toilet, Second Floor Sink	100	0								
2	91	Betts Road	1	Basement Sink	100	0								Yes
2	22	Betts Road	1	Basement Sink	90	10	Indirect	Defective Sewer Service						Yes
2	27	Betts Road	1	Basement Sink	100	0								
2	28	Betts Road	2	Basement Sink, First Floor Toilet	100	0				1	Dry Well	Basement Drain	1	Yes
2	33	Betts Road	1	Basement Sink	100	0				2	Sanitary Sewer		2	Yes
2	39	Betts Road	1	Basement Sink	100	0				1			Ground Surface	
2	40	Betts Road	2	Basement Toilet, First Floor Toilet	100	0						Open Pipe		Yes
2	45	Betts Road	1	Basement Sink	100	0								Yes
2	49	Betts Road	1	First Floor Sink	100	0				1	Ground Surface		1	Yes
2	45	Grosvenor Road	1	Basement Sink	100	0								Yes
2	3	Sargent Road	1	Basement Sink	95	5	Indirect (mainline)	Defective Manhole-Pipe Conn.		1	Ground Surface		1	Yes
2	8	Sargent Road	1	First Floor Sewer Stack	90	10							Indirect (mainline)	Defective Manhole-Pipe Conn.
2	14	Sargent Road	2	Basement Sink	90	10	Indirect (mainline)	Defective Manhole-Pipe Conn.		1	Ground Surface		1	Yes
2	21	Sargent Road	1	Basement Sink	90	10							Indirect (mainline)	Defective Manhole-Pipe Conn.
2	2	Sargent Road	1	Basement Sink	100	0								Yes
2	9	Sargent Road	1	Basement Toilet	100	0				1	Sanitary Sewer		1	Yes
2	15	Sargent Road	1	Basement Sink	100	0								Yes
2	20	Sargent Road	1	Basement Sink	100	0								Yes
2	26	Sargent Road	1	Basement Sink	100	0								Yes

BELMONT, MASSACHUSETTS
OUTFALL AREAS 1, 2 & 10

TABLE 1
RESULTS OF DYED - WATER TESTING
MAY / JUNE 2009

Outfall No.	Address		No. of Tests Conducted	Dye Test Entry	% Sewer	% Storm Drain	Dye Discharge		Sump Pumps	Sump Pump Discharge	Other Pipes	Sump Pit	Flow in Storm Drain
	No.	Street					Direct/Indirect Connection	Contaminate Source					
2	253	Washington Street	3	Basement Sink, First Floor Sink, First Floor Toilet	50(100)	50(0)	Direct (2) & Indirect	2 - Direct to Storm Drain & 1 - Indirect to Storm Drain					Yes
2	127	Dalton Road	1	Basement Sink	100	0							Yes
2	134	Dalton Road	2	Basement Toilet, First Floor Toilet	100	0			1	Into Ground			Yes
2	145	Dalton Road	1	Basement Sink	100	0						1	Yes
2	146	Dalton Road	1	Basement Sink	100	0							Yes
2	151	Dalton Road	1	Basement Sink	100	0							Yes
2	188	Dalton Road	2	Basement Toilet, First Floor Toilet	100	0							Yes
2	193	Dalton Road	2	Basement Sink, First Floor Toilet	100	0			1	Ground Surface		1	Yes
2	195	Dalton Road	1	Basement Sink	100	0			2	Sanitary Sewer	Basement Drain	2	Yes
2	215	Dalton Road	1	Basement Sink	100	0							Yes
10	56	Ciaflin Street	2	Basement Sink, First Floor Toilet	100	0			2	Sanitary Sewer, Septic Tank		2	Yes
10	60	Ciaflin Street	2	Basement Sink, First Floor Toilet	100	0			1	Ground Surface		1	Yes
10	68	Ciaflin Street	2	Basement Toilet, First Floor Toilet	100	0			1	Unknown		1	Yes
10	73	Ciaflin Street	2	Basement Toilet, First Floor Toilet	100	0							Yes
10		Leonard Street Fire Station	1	Basement Toilet	100	0							Yes
10		Leonard Street Verizon Bldg.	2	Basement Toilet (2)	100	0							Yes
10		Locatelli Properties	2	Basement Toilet (2)	100	0							Yes
10		Intersection of Ciaflin St & Alexander Ave	1	SMH 34S035.1	100	0							Yes
10	51	Alexander Avenue		No Test Conducted									Yes
10	52	Alexander Avenue		No Test Conducted									
10	15	Munroe Street	2	Basement Sink, Basement Toilet	100	0			1	Ground Surface	Basement Drain	1	Yes
10	421	Pleasant Street	1	Basement Sink	100	0							Yes
10	422	Pleasant Street	2	Basement Sink, Basement Toilet	100	0							No
10	425	Pleasant Street	1	Basement Sink	100	0							Yes
10	432	Pleasant Street	2	Basement Sink, First Floor Toilet	100	0							No
10	193	Ciaflin Street	1	Basement Sink	100	0							Yes
10	22	Chilton Street	3	Basement Sink and Toilet, First Floor Sink	80	20	Indirect		1	Unknown		1	No
10	23	Chilton Street	2	Basement Sink, First Floor Toilet	80	20	Indirect						Yes
10	9	Chilton Street	2	Basement Toilet, First Floor Sink	100	0	Indirect						Yes
10	10	Chilton Street	3	Basement Sink, Basement Toilet, First Floor Toilet	100	0							Yes
10	15	Chilton Street	3	Basement Toilet, First Floor Sink, Kitchen Sink	100	0							Yes
10	16	Chilton Street	2	Basement Sink, Basement Toilet	100	0							Yes
10	11	Cowdin Street	1	Basement Sink	100	0					Separate Drain Pipe		Yes
10	12	Cowdin Street	3	Basement Sink, Basement toilet, First Floor Sink	100	0							Yes
10	17	Cowdin Street	1	First Floor Toilet	100	0							Yes
10	18	Cowdin Street	2	Basement Sink, First Floor Toilet	100	0							Yes
10	23	Cowdin Street	1	Basement Toilet	100	0					Seperate Drain Pipe		Yes
10	24	Cowdin Street	2	Basement Sink, Basement Toilet	100	0							Yes
10	30	Cowdin Street	2	Basement Sink, Basement Toilet	100	0							Yes
10	99	Sherman Street	1	Basement Sink	70	30	Indirect	Adjacent Drain Service	1	Ground Surface		1	Yes
10	70	Waterhouse Road	2	First Floor Toilet (2)	95	5	Indirect	Adjacent Drain Service					Yes
10	67	Sherman Street	1	Basement Sink	100	0							Yes
10	75	Sherman Street	1	Basement Sink	100	0							Yes
10	81	Sherman Street	1	Basement Sink	100	0							Yes
10	87	Sherman Street	1	Basement Sink	100	0							Yes
10	93	Sherman Street	2	Basement Sink, Second Floor Toilet	100	0			2	Ground Surface		2	No
10	105	Sherman Street	1	Basement Sink	100	0			1	Sanitary Sewer		1	No
10	111	Sherman Street	1	Basement Sink	100	0							Yes
10		Winn's Brook School	3	First Floor Toilet (3)	100	0						1	No

BELMONT, MASSACHUSETTS
OUTFALL AREAS 1, 2 & 10

TABLE 1
RESULTS OF DYED - WATER TESTING
MAY / JUNE 2009

Outfall No.	Address		No. of Tests Conducted	Dye Test Entry	Dye Discharge			Sump			Other Pipes	Sump Pit	Flow in Storm Drain
	No.	Street			% Sewer	% Storm Drain	Direct/Indirect Connection	Contaminate Source	Sump Pumps	Sump Pump Discharge			
10	3	Westlund Road	1	First Floor Sink	100	0							No
10	4	Westlund Road	1	First Floor Toilet	100	0			1	Ground Surface		1	Minimal
10	9	Westlund Road	1	Basement Sink	100	0							Minimal
10	10	Westlund Road	1	First Floor Toilet	100	0							Minimal
10	15	Westlund Road	1	Basement Sink	100	0					Separate Drain Pipe		Minimal
10	16	Westlund Road	1	Basement Sink	100	0			1	Ground Surface		1	Yes
10	21	Westlund Road	1	Basement Sink	100	0			2	Sanitary Sewer, Winn's Brook		2	No
10	22	Westlund Road	1	First Floor	100	0							No
10	27	Westlund Road	1	Basement Sink	100	0			1	Other		1	No
10	28	Westlund Road	1	Basement Toilet	100	0					Separate Drain Pipe		No
10	34	Westlund Road	1	First Floor Toilet	100	0			1	Unknown	Separate Drain Pipe	1	No
10	35	Westlund Road	1	First Floor Toilet	100	0					Separate Drain Pipe		No
10	40	Westlund Road	1	First Floor Toilet	100	0							No
10	44	Westlund Road	1	First Floor Toilet	100	0			1	Sanitary Sewer	Separate Drain Pipe	1	No
10	48	Westlund Road	1	First Floor Sink	100	0							No
10	39	Waterhouse Road	2	Basement Sink	100	0			1	Ground Surface		1	Minimal
10	54	Waterhouse Road	2	Basement Sink, Basement Toilet	100	0							Yes
10	57	Waterhouse Road	2	Basement Sink, Basement Toilet	100	0			1	Ground Surface		1	Yes
10	67	Hoitt Road	1	Basement Sink	0	100	Direct	Direct to Storm Drain					
10	55	Hoitt Road	2	Basement Toilet, First Floor Sink	95	5	Indirect	Defective Sewer Service	2	Ground Surface		2	No
10	32	Hoitt Road	2	Basement Sink, First Floor Toilet	100	0			1	Into Ground		1	Minimal
10	37	Hoitt Road	2	Basement Sink, First Floor Toilet	100	0							Minimal
10	43	Hoitt Road	1	Basement Sink	100	0							Minimal
10	49	Hoitt Road	2	Basement Sink, First Floor Toilet	100	0							Minimal
10	52	Hoitt Road	1	Basement Sink	100	0							Minimal
10	58	Hoitt Road	1	Basement Sink	100	0							Minimal
10	61	Hoitt Road	2	Basement Toilet, First Floor Toilet	100	0							Minimal
10	64	Hoitt Road	1	Basement Sink	100	0							No
10	70	Hoitt Road	1	First Floor Toilet	100	0			1	Sanitary Sewer		1	Minimal
10	73	Hoitt Road	1	Basement Sink	100	0			1	Sanitary Sewer		1	Minimal
10	76	Hoitt Road	1	Basement Sink	100	0				Ground Surface			No
10	79	Hoitt Road	2	Basement Toilet, First Floor Toilet	100	0						1	No
10	85	Hoitt Road	1	First Floor Toilet	100	0							No
Other	280	Blanchard Road	1		0	100	Direct	Direct to Storm Drain					Yes

BELMONT, MASSACHUSETTS
OUTFALL AREAS 1, 2 & 10

TABLE 2
CCTV INSPECTION RESULTS & RECOMMENDED REHABILITATION

SANITARY SEWER / STORM DRAIN

Street	Outfall Area	Disk No.	Priority*	Manhole No.		Pipe Diameter (inches)	Distance (feet)	Joint Spacing (feet)	No. of Point Repairs	Point Repair Locations **	Recommended Rehabilitation		No. of Service Connections	No. of Service Connections Replaced	Location of Services Replaced **	NEW MH	Notes
				Direction	Start End						Line	Replace					
Payson Rd	1	1	2	Upstream	04S018 04S017	8	130	3	0		NRR	NRR	4	0			Pipe in ok condition some minor cracks and 1 moderate crack, one service appears not active
Payson Rd	1	1	3	Downstream	04S018 04S008	8	172	3	1	166'-172'	172	NRR	4	0			Severe broken pipe and sag at 166'-172'; one service appears not active
Payson Rd	1	3	2	Upstream	04D010 08D026	15	519	3	1	261'-266'	NRR	NRR	3	0			Pipe in ok condition, 1 point repair with moderate to severe longitudinal cracks and broken pipe
Van Ness Rd	1	3	2	Downstream	04D010 03D008	15	168	3	0		NRR	NRR	2	0			Some minor/moderate cracks no rehab immediately necessary.
Shupe Rd	2	1	1	Downstream	03S022 03S007	6	39	3	0		NRR	NRR	1	1	36'		Inspection Incomplete Total length: 153'; broken pipe at service at 36'; no reverse setup camera can fit in downstream pipe
Shupe Rd	2	2	1	Upstream	20S038 20S039	8	89	3	0		NRR	NRR	2	0			Pipe in good condition.
Shupe Rd	2	2	2	Downstream	20S038 20S037	8	57	3	0		NRR	NRR	0	0			Pipe in good shape. Minor cracking. Little to no flow
Shupe Rd	2	2	2	Upstream	20D044 20D045	8	146	3	0		NRR	NRR	1	0			Pipe in good condition. Minor longitudinal cracking
Shupe Rd	2	2	2	Downstream	20D044 20D043	8	272	3	0		NRR	NRR	8	0			Inspection Complete, setups 31732. Pipe in good condition with only minor to moderate cracking.
Shupe Rd	2	2	4	Downstream	20S037 20S036	8	147	3	1	44'	147	NRR	5	1	10.4'		Pipe in poor condition, must be lined; service at 79.2'(#22) appears not active correlating with the dye-tracing(not in sewer or drain)
Shupe Rd	2	3	4	Downstream	20S036 20S035	8	243	3	0		243.4	NRR	6	2	39.6', 79.2'		Inspection Complete, setups 41745; pipe in ok condition one moderate longitudinal crack at 220' possible spot liner/point repair; several locations infiltrating w/ sewer above storm drain, spot liner at 245-252'
Shupe Rd	2	3	4	Downstream	20S035 20S034	8	118	3	0		118	NRR	2	1	56.4'		Inspection Complete, setups 41745; pipe in ok condition one moderate longitudinal crack at 220' possible spot liner/point repair; several locations infiltrating w/ sewer above storm drain, spot liner at 245-252'
Shupe Rd	2	3	2	Downstream	20D043 09D108	8	252	3	1	245'-252'	NRR	NRR	5	0			Storm drain under sewer. Infiltrating sewer possible at bend at206'. Some minor/moderate cracks no rehab immediately necessary.
Grosvenor Rd	2	5	4	Downstream	08S010 09S004	8	227	3	0		226.5	NRR	0	0			Storm drain under sewer. Pipe has several severe broken pipe and several minor cracks.
Grosvenor Rd	2	5	2	Downstream	08D019 09D011	12	241	3	0		NRR	NRR	4	0			Storm drain under sewer. Pipe has several severe broken pipe and several minor cracks.
Shaw Rd	2	5	4	Downstream	09S084 09S032	6	16	2	0		NRR	16	0	0			Storm drain under sewer. Pipe has several severe broken pipe and several minor cracks.
Chaffin St	10	1	3	Upstream	34S031 34S032	8	92	3	0		92.2	NRR	2	0			Root control needed; line section
Chaffin St	10	1	4	Downstream	34S031 34S030	8	217	3	0		217.4	NRR	5	0			Moderate multiple cracks at 13.6' if not LINED then point repair necessary
Chaffin St	10	2	2	Downstream	34D087 34D093	18	62	3	0		NRR	NRR	0	0			Pipe has several severe broken pipe sections but must and can be lined some offset joints several services appear not active
Chaffin St	10	2	2	Downstream	34D091 34D087	18	452	3	0		NRR	NRR	6	0			Inspection Complete, setups 28729. Pipe in fair condition. Minor to moderate cracking throughout with minor root intrusion.
Chaffin St	10	2	4	Downstream	34S037 34S033	8	201	3	0		201	NRR	4	1	116.7'		Several points of infiltration throughout; standing sewage in pipe possible sag in line
Chaffin St	10	2	4	Upstream	34S037 34S036	8	150	3	1	42.2'	NRR	NRR	4	0			Pipe in good shape other than potential collapse at 42.2' to be point repaired
Chaffin St	10	2	4	Downstream	34S037 34D074	15	276	3	0		276.6	NRR	3	0			Spikes through pipe, some cracked areas seem ready to collapse
Alexander Ave	10	5	3	Downstream	34S035.1 34S035	8	60	3	0		60	NRR	0	0			Sewer above storm drain. Pipe in ok condition 1 moderate crack at 42'
Pleasant St	10	2	1	Downstream	47D008 47D040	24	23	3	0		NRR	NRR	0	0			Pipe in excellent condition. No defects
Pleasant St	10	3	3	Downstream	47S018 47S017	8	187	3	0		186.7	NRR	3	2	34.3', 165.6'		Minor/moderate cracks throughout; fire/moderate roots throughout root control needed.
Munroe St	10	1	3	Upstream	47D008 47D008.1	24	406	3	0		NRR	NRR	3	0			Pipe in good condition few minor/moderate cracks; 2 sections were CCTVed 47D008-47D008.1 and 47D008.1-47D013; 47D008.1 in to mainline
Munroe St	10	1	3	Downstream	43S007 43S006	8	91	3	0		91.3	NRR	2	0			Slight collapsed pipe 5% (slight egg shape @27', concrete at joints throughout at inverts causing minor blockage
Chillon St	10	2	2	Downstream	47D040 43D020	30	259	3	1	32'-45'	140	NRR	3	0			Severe broken/collapsed pipe at 32'-45'; minor/moderate cracks throughout; one service appears inactive
Chillon St	10	5	2	Upstream	44D005 44S007	10	109	3	0		NRR	NRR	1	2	107', 109'		Sag in line with minor cracking found throughout. Pipe in fair condition. Incorrectly labeled 47D040 to 47D020
Chillon St ROW	10	1	4	Downstream	44D005 44S006	8	111	3	0		111	NRR	1	0			Sewer is above storm drain; Roots at joints throughout, poor connection at 107' and heavy roots at 109'; cap end of pipe if service at 109' is not active
Cowdin St	10	1	3	Upstream	44S008 44S008	8	266	3	0		266.2	NRR	4	1	42'		Minor to moderate longitudinal cracks at 12.00 for 200' of the pipe. Fine roots at joints through and infiltration. Sewer is above drain
Sherman St	10	1	4	Downstream	44D011 44D015	15	147	3	0		147	NRR	2	0			Inspection Complete, setups 517 combined, moderate crack/broken pipe at 81' liner can fix to avoid PR
Sherman St	10	1	1	Upstream	37S022 Dead End	8	5	3	0		144.8	NRR	4	0			Pipe in poor shape, moderate to severe longitudinal cracks at 12.00 for 120' of the pipe section
Sherman St	10	1	2	Downstream	37S022 37S020.1	8	46	5	0		NRR	NRR	1	0			Service for 70 Waltherhouse Rd; roots at 6" to 4" transition at service
Sherman St	10	1	1	Downstream	37S020.1 37S020	8	128	5	0		NRR	NRR	0	0			Pipe in ok condition 1 moderate crack at 44'; storm drain under sewer.
Sherman St	10	1	1	Downstream	37S020 37S019	8	205	5	0		NRR	NRR	2	0			Pipe in good shape but storm drain under sewer.
Sherman St	10	1	2	Downstream	37S019 37S018	8	204	5	0		NRR	NRR	3	0			Pipe in good shape but storm drain under sewer.
Sherman St	10	1	2	Upstream	37S017 37S018	8	16	5	0		NRR	NRR	0	0			Pipe in good shape. Minor cracks, standing water in services and offset joints, storm drain under sewer
Sherman St	10	1	3	Downstream	37S017 27S016	8	69	5	0		69	NRR	0	0			Pipe in good shape. 2 minor sags, standing water in services and offset joints, storm drain under sewer
Sherman St	10	2	2	Upstream	37D029 37D031	12	269	2	1	33'-44'	NRR	NRR	5	0			Cast iron pipe section is corroded/leaking
Sherman St	10	2	2	Downstream	37D029 37D026	12	405	3	0		NRR	NRR	5	0			Inspection Complete, setups 28738. Pipe in good condition with minor to moderate cracking
TOTALS							7,205		7		3,165	16	116	11		0	

Incomplete Inspection

* 1 (Excellent Condition) - 5 (Severe Deterioration)
** Distance from Starting Manhole in feet

BELMONT, MASSACHUSETTS OUTFALL AREAS 1, 2 & 10

TABLE 3
DRY WEATHER STORM WATER SAMPLING RESULTS

[illegible]

OUTFALL 2	Outfall Area 2 - Huron Ave/Grove St	OF2E/OF2E2/OF2E3/OF2E4/OF2E5/OF2E6	2,100	11,050	>30,000	16,900	21,700	8,700	DYE TESTED	1,600	400
19D002	Washington St at School St	17/17A/17C/17D		7,850	>30,000		>30,000	13,500	DYE TESTED		
19D004	Jackson Rd at Washington St	17A/17C/17D/17E/17F/17H/1			2,300		100	400	600		
09D108	From Sharpe Rd at Washington St	10/10A		>15,000	>30,000						
09D108	From Washington at Sharpe Rd	11/11A		3,900	26,600						
09D046	Shaw Rd at Dalton Rd	18/18A/18D		5,600	15,100			17,600	DYE TESTED		
09D054	Shaw Rd at Herbert Rd	18A/18H/1			2,600			DRY	DRY		
09D046	Shaw Rd at Dalton Rd	19/19A		>15,000	>30,000						
10D005	Elm St at Foster Rd	12A/12B/12C/12D/12G/12H			2900	<100	200	<100			
10D046	Elm ST at Dalton Rd	12A1			210						
09D009	Grosvenor Rd at Dalton Rd	3A/3B			>30,000						
09D011	Sargent Rd at Grosvenor Rd	3B1/3E1/3F1/3H1			>30,000						
09D011	Grosvenor Rd at Sargent Rd	3B2			30,000			DYE TESTED	>30,000	15,000	>20,000
09D009	Dalton Rd at Grosvenor Rd	4A/4B/4D/4E/4F/4H			530	3600		6,600	4,900	400	6,700
09D086	Bacon Rd at Woods Rd(from Bacon Rd - ADDED SAMPLE)	4E2/4F2							>30,000 (first Identified)	ND	DRY
09D003	Betts Rd at Dalton Rd	5B									
09D003	Betts Rd at Dalton Rd	6B/6D				>30,000			DYE TESTED		
09D074	Audrey Rd at Betts Rd	6B1/6D1/6E1/6F2/6H1				>30,000		900	400	1,100	9,700
09D041	Livemore Rd at Dalton Rd	7B/7D				>30,000		300	DYE TESTED		
09D029	Shaw Rd at Livemore Rd	7B1/7D1/7E1/7G1/7H1				10,100		900	<100		
09D042	Livemore Rd at Dalton Rd	8B/8D				>30,000		26,000	DYE TESTED		
09D064	Livemore Rd from Easement across from Hartley Rd	8B1									
09D009	Dalton Rd at Grosvenor Rd	OF2E3A			>30,000						
09D009	Dalton Rd at Grosvenor Rd (8" possible service - ADDED SAMPLE)	20F						DRY	DRY	500	DRY

* Sample Numbers are in order of Date Sampled
ND - None Detected (<100)

BELMONT, MASSACHUSETTS
OUTFALL AREAS 1, 2 & 10

TABLE 3
DRY WEATHER STORM WATER SAMPLING RESULTS

MH No.	Location	Sample No.*	E. Coll. Colonies per 100 ml - Date Sampled										FIRST QUARTER		SECOND QUARTER		THRID QUARTER		FOURTH QUARTER	
			7/8/08	7/9/08	7/14/08	7/18/08	10/21/08	11/3/08	11/4/08	11/5/08	11/20/08	5/21/2009	5/22/2009	8/18/2009	8/28/2009	5/18/2010	7/2/2010	8/30/2010		
OUTFALL 10	Outfall Area 10 - Little Pond	OF10E1OF10E2Z-OF10E3/OF10E4/OF10E5/OF10E6/OF10E7																		
37D036	Intersection of Holt Rd and Brighton St		2,040	1,200	750	970			8,600	19,500	5,000		300							
41D046	Brighton Rd. at Cross St	11A1/B1/D1/E1/F1/H1	2,740		700				3,800				6,000	8,800						
44D047	Albert Ave at Brighton St	1A11B11D11E11F11H1			610				7,000				200	6,200		3,000	6,100			
44D047	Albert Ave at Brighton St	1A21B2			100				<100							16,000	700			
45D009	Albert Ave	1A31B3			90				<100											
45D009	Albert Ave	1A4			100															
38D006	Intersection of Statler Rd. and Newcastle Rd.	1A5			80															
38D002	Eliot Rd at Newcastle Rd	2D2/2E	2,000										14,000	1,800						
37D055	Intersection of Westland Rd. and Waterhouse Rd.; flow from Westland Rd.	2D1/2E1											>30,000	100						
37D055	Intersection of Westland Rd. and Waterhouse Rd.; flow from Waterhouse Rd.	33A/3B/3C/3E/3G/3H	2,440		10				>30,000		>30,000		DYE-TESTED	28,400			>20,000	7,200		
37D042	Holt Rd. at Waterhouse Rd	4/4A/4B/4C	830		No Sample/Trickle				>30,000		>30,000				DYE TESTED - CONTAMINATE FOUND					
37D042	Holt Rd. at Waterhouse Rd	4A1/4B1/4C1			160				>30,000		6,200									
37D028	Sherman St	4A2/4B2/4C2			120				700		<100									
37D013	Intersection of Holt Rd and Dean St	5/5B/5C	2,550		No Sample				>30,000		>30,000									
37D009	Dean St at Holt Rd	6/6A	370		50															
34D009	Intersection of Sherman St and Dean St	6A1			10															
42D019	MH-42D019 (WINN'S BROOK SCHOOL FIELD)	7/7B/7H	580						2,100				DRY		No Sample/Trickle			ND		
42D016	Cross St between Munroe St and Broad St	8	220	1,500																
43D014	Munroe St. at Cross St.	9/9A/9B/9C/9D							>3,000		7,200		200	CONTAMINATED UPSTREAM						
43D014	Munroe St. at Cross St.	9A1/9B1/9C1/9D1							>3,000		1,000		<100	CONTAMINATED UPSTREAM						
43D020	Intersection of Munroe and Claflin	9A2/9B2/9C2/9D2/9E2/9F2							470		600		<100		100	ND				
47D008	Pleasant St. at Munroe St.	9A3/9B3/9C3/9E3/9F3/9H3							>3,000		6,900				>30,000	ND	800			
44D042	Frost St	9A4/9B4							2,280				DYE-TESTED		DRY	No Sample/Trickle	DRY			
44D024	Middlecott St. at Hurley	9A8							100						DRY		DRY			
44D015	Cowdin St. coming from Brighton St.	9A5/9B5/9D5							800				DRY		DRY		DRY			
44D005	Chilton St. close to Brighton St.	9A6/9B6/9C6							3,200				200	CONTAMINATED UPSTREAM						
43D002	Intersection of Chilton St and Dean St	9A7/9B7							>30,000		2,000			CONTAMINATED UPSTREAM						
43D001	Claflin St. at Dean St - Catch Basin	10/10A/10B/10D1/0E1/0G/10H							>30,000					CONTAMINATED UPSTREAM						
43D022	Claflin St. MH-43D022	10A1	460						300				100	<100			250	ND		
34D082	Intersection of Claflin St and Winn St	10A2/10B2/10D2/10E2/10G2/10H2																		
34D082	Intersection of Claflin St and Winn St	11	30						400				<100	100			700	200		
CB	Dead end of Claflin St from Alexander Ave. middle catch basin	12	160																	
34D093	Claflin St. at Alexander Ave	13/13A/13B/13C/13E/13F/13H	2,710						2,850											
34D087	Claflin St. at Alexander Ave	13A1/13B1							<10		3,000						100	700		
34D091	Claflin St. from Channing St	13A2/13B2/13C2/13D2/13E2/13F2/13H2							1,000		3,000						200	1,200		
48D024	Clifton St at Fletcher Rd	13A3/13B3/13C3/13E3/13H3							70		<100						200	ND		
48D011	Prospect St at Clifton St	14	30																	
48D011	Prospect St at Clifton St	15	20																	
54D025	Belmont Hill School parking lot	16	230																	
		17	70																	

* Sample Numbers are in order of Date Sampled
ND - None Detected (<100)

BELMONT, MASSACHUSETTS
OUTFALL AREAS 1, 2 & 10

TABLE 4
ILLICIT SUMP PUMP CONNECTIONS

Address		No. of Sump Pumps	Sump Pump Discharge	Other Pipes	Sump Pits	Comments
No.	Street					
33	Betts Road	2	Sanitary Sewer		2	All plumbing is correct to main sewer stack; Access to cleanout on sewer stack
56	Claffin Street	2	Sanitary Sewer, Septic Tank		2	Toilet, shower, and sump pump are connected to sewer; Kitchen sink, dish washer, and second sump pump discharge to septic tank in back yard; Only pays half of sewer bill due to septic tank and leaching field in backyard
195	Dalton Road	2	Sanitary Sewer		2	Homeowner was upset when told about the sump pumps connecting to the sewer
10	Hartley Road	1	Sanitary Sewer	Separate Drain Pipe	1	All plumbing is correct other than sump pump to sewer stack; Separate drain pipe in cleanout pit
64	Hoitt Road	1	Sanitary Sewer		1	All plumbing is correct except for sump pump discharging to sewer
70	Hoitt Road	1	Sanitary Sewer		1	All plumbing to one sewer stack including sump pump; No access to cleanout
44	Livermore Road	2	Sanitary Sewer, Ground Surface	Separate Drain Pipe	2	Sump pump discharges into basement sink - all other plumbing is correct; Access to Cleanout on stack
2	Sargent Road	1	Sanitary Sewer		1	Sump pump discharges into basement sink - pump rarely turns on; Garden hose discharges to sink as well; Cleanout is located in sump pit along with sump pump
93	Sherman Street	1	Sanitary Sewer		1	IN SSES REPORT No access to storm drain until conduit; Sump pump discharges to sink; Access to cleanout on sewer stack
175	Washington Street	1	Sanitary Sewer		1	All plumbing is correct to main sewer stack; Access to cleanout in front of house
232	Washington Street	2	Sanitary Sewer		2	Both sump pumps are piped to SMH in yard - saw flow from 2" pipe
16	Westlund Road	2	Sanitary Sewer, Winn's Brook		2	Sewer plumbing is correct; French drain around perimeter and first sump pump discharge to Winn's Brook; Second sump pump is only for emergency - discharge into sink
40	Westlund Road	1	Sanitary Sewer	Separate Drain Pipe	1	All plumbing is correct except for sump pump to sewer; Separate drain pipe drains out back
TOTAL		16				
UNDETERMINED DISCHARGE LOCATIONS - SUMP PUMPS						
68	Claffin Street	1	Unknown		1	All plumbing in walls - Could not identify; Sump pump most likely drains outside of house to a dry well; Sewer main crosses Winn's Brook conduit - probably under conduit
193	Claffin Street	1	Unknown		1	All Plumbing is correct, Access to cleanout in back of house; Portable sump pump used when necessary
8	Sargent Road	1	Unknown	Foundation Drain to New Sump Pits	2	Reconstructing house - Sewer stack was accessed; Contamination of storm drain similar to other houses on Sargent Rd (Defect in invert in downstream SMH)
TOTAL		3				

**BELMONT, MASSACHUSETTS
OUTFALL AREAS 1, 2 & 10**

**TABLE 5
RECOMMENDED ADDITIONAL INVESTIGATIONS
OPINION OF PROBABLE COST**

PROJECT MANAGEMENT	\$1,200
CCTV INSPECTION (MAIN LINE)	\$12,800
CCTV INSPECTION (SERVICES)	\$27,300
HOUSE INSPECTION & DYED-WATER TRACING	\$14,200
FOLLOW-UP DRY WEATHER SAMPLING	\$4,600
PRELIMINARY DESIGN REPORT	\$12,300
MEETING WITH TOWN OFFICIALS	\$1,800
TOTAL	\$74,200

**BELMONT, MASSACHUSETTS
OUTFALL AREAS 1, 2 & 10**

**TABLE 6
RECOMMENDED REHABILITATION
OPINION OF PROBABLE COST**

ITEM NO.	ITEM OF WORK	ESTIMATED QUANTITIES	UNITS	UNIT COST	AMOUNTS
1	8-INCH SEWER - FULL LENGTH REPLACEMENT	16	LS	\$7,500	\$7,500
2	8-INCH SEWER - FULL LENGTH LINING	2,360	LF	\$45	\$106,187
3	10-INCH DRAIN - FULL LENGTH LINING	256	LF	\$55	\$14,080
4	15-INCH DRAIN - FULL LENGTH LINING	420	LF	\$65	\$27,326
5	REINSTATEMENT OF SERVICE CONNECTIONS	54	EACH	\$150	\$8,100
6	SEWER OR DRAIN POINT REPAIR REPLACEMENT (6-10 INCH)	5	EACH	\$5,000	\$25,000
7	12" DRAIN POINT REPAIR REPLACEMENT	1	EACH	\$6,000	\$6,000
8	15" DRAIN POINT REPAIR REPLACEMENT	1	EACH	\$7,000	\$7,000
9	SERVICE REPLACEMENT (main to edge of roadway)	11	EACH	\$5,000	\$55,000
10	SERVICE REPLACEMENT (main to house, 67 Hoitt)	1	EACH	\$10,000	\$10,000
11	PROBABLE SERVICE LINING/REPLACEMENT (CCTV required)	19	EACH	\$7,500	\$142,500
12	CCTV INSPECTION OF SEWER	165	LF	\$4	\$660
13	MANHOLE REHABILITATION	6	EACH	\$3,000	\$18,000
14	TEMPORARY PAVING (trench)	225	SY	\$15	\$3,380
15	PERMANENT PAVING (trench)	273	SY	\$40	\$10,929
16	MOBILIZATION		LS	5% of Total	\$22,083
SUBTOTAL					\$463,744
CONTRACTOR OVERHEAD & PROFIT @		20%			\$92,749
ENGINEERING & CONTINGENCIES @		40%			\$185,498
TRAFFIC POLICE		240 HOURS @		\$40	\$9,600
TOTAL					\$751,591



**BELMONT, MA
UNITY AVE TRIBUTARY AREA**


FIGURE 1

**BUILDING INSPECTION/DYED-WATER TESTING
& CCTV INSPECTION RESULTS
OUTFALL 1**

OCTOBER 2010

1 inch = 40 feet

ENGINEERS
FST
Since 1914



BELMONT, MA
HURON AVE TRIBUTARY AREA
FIGURE 2
BUILDING INSPECTION/DYED-WATER TESTING
& CCTV INSPECTION RESULTS
OUTFALL 2

OCTOBER 2010
1 inch = 120 feet



**BELMONT, MA
WINN'S BROOK TRIBUTARY AREA**

FIGURE 3

**BUILDING INSPECTION/DYED-WATER TESTING
& CCTV INSPECTION RESULTS
OUTFALL 10**

OCTOBER 2010

1 inch = 50 feet



**BELMONT, MA
WINN'S BROOK TRIBUTARY AREA**

FIGURE 4

**BUILDING INSPECTION/DYED-WATER TESTING
& CCTV INSPECTION RESULTS
OUTFALL 10**

OCTOBER 2010

1 inch = 120 feet

