



TOWN OF BELMONT, MA

ILLICIT DISCHARGE DETECTION AND ELIMINATION




1 inch = 100 feet



LEGEND

- Sampling Date
- ★ 2016 - 2017 Sampling Locations
- Belmont Drainage System
- Drain Mainline - No Rehab or CCTV
- Drain Mainline - CCTV and No Rehab Required
- Drain Mainline - Rehabbed, Replaced, or New
- Drain Manhole
- ★ Outfall Points
- Outfall 15A Subcatchment
- Catch Basin
- Catch Basin Outlet Drain
- Belmont Sewer System
- Sewer Mainline - No Rehab or CCTV
- Sewer Mainline - CCTV and No Rehab Required
- Sewer Mainline - Rehabbed, Replaced, or New
- Sewer Manhole
- House/Building
- House/Building with Replaced/Lined Sewer Service
- House/Building with Grouted Sewer Service



Index Map

The information on this map has been compiled by Stantec staff from a variety of sources and is subject to change without notice. Stantec makes no representations or warranties, express or implied, as to accuracy, completeness, timeliness, or origin of the use of such information.

Figure 10
Outfall 15A Subcatchment
January 2018



Stantec Consulting Services, Inc.
5 Burlington Woods Drive
Burlington, MA 01803-4542

