SELECT BOARD BELMONT, MA

Community Preservation Committee Town of Belmont

CPA Funding - Preliminary Application

A printed copy of the completed Preliminary Application must be submitted to the Following address by no later than 7:00 pm on Monday, October 2, 2023:

Community Preservation Committee c/o Matthew Haskell, CPA Administrator Office of the Select Board Belmont Town Hall 455 Concord Avenue Belmont, MA 02478

Unless an applicant can demonstrate that a significant opportunity would otherwise be lost, preliminary applications will not be accepted after the submission deadline.

Project Title	School Administration Building Repairs		
Project Locatio	n 644 Pleasant St, Belmont, MA		
Applicant/Cont	act Person Carl Solander, Co-Chair	ir, Belmont Historic District Commission	
Organization_B	elmont Historic District Commission on be	behalf of the Town of Belmont	
Mailing Addres	S Gabriel S. Distler, Town of Belmont Planni	ning Division, 19 Moore Street, 2nd Floor, Belmont, MA 02478	
Telephone 617-	993-2666	E-mail carl_belmonthdc@reversearchitecture.com, gdistler@belmont-	ma.gov
Signature	CLASOS	Date 10/02/2023	
CPA Category (<i>i</i>		page and check all that apply):	
		□ Recreation	
Amount Requ	ested\$160,000		
Total Project (Cost \$160,000		

Applicants will present their projects at the CPC Public Meeting on November 8, 2023 and address questions from Belmont residents. It is required that information about the project be in writing and copied for distribution and review at the Public Meeting. This is also an opportunity for project sponsors to ask the CPC any questions regarding the application process.

Chart 1 COMMUNITY PRESERVATION FUND ALLOWABLE SPENDING PURPOSES (G.L. C. 44B, § 5)

	Lo see state	ALCOHOLD CIRCLES	CHAS LANCE ARCOLD	ONIGHTON OF PRINCIPALITY
DEFINITIONS (G.L.c. +1B, § 2)	OPERS SPACE. Land to protect recluting and inture well fields, aquiffers and rechange area, water shed fand, agicultura land, grawdand, agicultura land, grawdand, water narribas and other water narribas and other lasts and point frontings. Deschies, lasts and point frontings. Deschies, lands to protect secul visita land intuits to protect secul visita land and land for recreational nee and land for recreational nee	The J CALL RESOURCES Building, structure, vereal read properly decument or attled literal on the star register of literal of the star register of literal read in preservation commission to be significant in the history, archefore, architecture or culture of the city or town	TECHEN INCLUDE LAND Land for active or passive Land for active or passive reactive and are defineding but not limited to the use of land for encommerful youthen and abut sport, and for use of hand an sport, and for use of hand an sport, and the use of hand an sport, and the use of hand an sport, and the use of hand an starting purposed or a miletir field Dees agai bridget horse or dee starting or the use of land for a starting or the use of land for a	Common in Processor Honoring for the wan moderate microme individuals and families, including for or moderate income seators metalors and beare the come is less than 100 %, and how mooner, is less than 100 %, and how mooner, is less than 80%, of US HUD Area Wide Medlan income
ACQUISITION Obtain property inters by gift purchase, derise, grant, cental renal purchase, lease or otherwise. Only includes renition domain taking as provided by GL. c. 44B.	Yes) tes	Yes	Yes
CREATION To bring into being or cause to exist. Suldenwar v. City of Newton, 452 Muss 472 (2008)	Ves		Yes	Yes
PRESERVATION Protect persons or real property from mjury, ham or destruction	Yes	Yes) es	Ves
SUPPORT Profile grants, home, tenial assistance, recurity deposits, inferest-infe write downs or other former or sessaints directly to infesticals and function by tenighted from the control or only that on one of the former operates or manages such howing, for the purpose of making alroyable.				v.v.s. Includes funding for communally's affectable housing trust
RESTORATION AND RESTORATION AND MEETINGS AND A MEET	Yes II acquired or created with CP hinds	Yes	Yes	Yes! acquired or created with CP finds

Source: Department of Revenue (DOR) 10-5-2012 conference, "Recent Developments in Municipal Law," Workshop B - Local Finances

Brief Description of Project Include the address/location and current owner of the property, as well as any critical dates. Please attach supplemental information (photographs, drawings, documents, etc.) as desired
The project is to design and construct repairs to the roof of the Belmont School Administration Building to stop active leaks and ongoing water damage. The building is located at 644 Pleasant St and is owned by the Town of Belmont. See detailed project description, photos, drawings and estimate
_attached.

Brief Description of Benefit

How does the project fulfill the General and Specific Criteria of the Community Preservation Committee Guidelines?

The Belmont Historic District Commission has identified the School Administration Building as one of Belmont's most important town-owned historic assets. This classical revival building, constructed in 1902, was originally the Underwood Library and now houses administrative offices for the Belmont public schools. It is part of the historic town hall complex which comprises a number of important town-owned historic buildings which together are a character-defining feature of the town. The building also lies within the Pleasant Street Historic District and is surrounded by historic homes. Using CPA grant funds, the town commissioned a conditions assessment study of three important town-owned buildings in the town hall complex, including the School Administration Building, Town Hall and Town Hall Annex. The leaking roof of the School Administration Building has been identified as the most urgent repair work among these three buildings.

This project fulfills the specific requirements of preserving, rehabilitating and restoring an important historic resource for the Town of Belmont. This building is an essential part of the civic core of Belmont and its continued deterioration may lead to larger and more difficult to repair problems if not addressed soon.



Town of Belmont School Administration Building: Proposed CPA Project September 28, 2023

Scope Narrative:

Preservation architects, the Spencer Preservation Group, were engaged to provide the Town of Belmont with a conditions assessment report of three historic buildings that form an administrative collective for the Town. Namely, these are the Town Hall, the Homer Building (a Town Hall annex), and the School Administration Building. As part of this assessment, the architects interviewed facilities staff to learn of known building deficiencies and maintenance history of the buildings. Through this process, it was found that the School Administration Building suffers from chronic roof and wall leaks that are active and apparent in the southwest quadrant of the building. This area of roof was modified with the addition of a hipped roof structure to accommodate the override and shaft ventilation when the elevator was added to the building. It is reported that multiple attempts at repairs have not contained the leaks, and the facilities staff relies on buckets to capture the water.

As part of the assessment process, the team inspected the building envelope via an aerial lift and found numerous areas where water infiltration is likely to occur:

- The elevator override has a hipped slate roof that is pitched directly to an existing brick chimney. With no cricket flashing provided at the chimney, the chimney accepts a good amount of water and snow accumulation, which has led to mortar joint deterioration and open mortar joints.
- This same chimney has a number of structural cracks near the top.
- A number of existing copper counterflashings are poorly detailed and rely on sealant joints that are reaching the end of their life expectancy.
- There are a considerable number of open reglets at flashing terminations that required new sealant.
- There are a number of copper flashing transitions that appear vulnerable to water infiltration by nature of their design and require reconfiguration/replacement.
- Eroded mortar joints and efflorescence visible at areas of brick masonry adjacent to the downspout and collector box suggest that there is likely solder joint failure, or the system is undersized for water volume.
- Brick masonry and mortar deterioration below the through-wall downspout detail at the parapet suggest that this area is vulnerable to water infiltration as a result of this detail and will likely cause significant structural issues at the parapet wall in the future.
- There is a deteriorated wood fascia and soffit at the override structure that requires repair.

Recommendations for repair include:

- Modification at the roof edge of the elevator override to provide space at the chimney to direct runoff away from the chimney. While working on the roof edge there, replace deteriorated wood fascia and soffit.
- Rebuild the top portion of the chimney where bricks are cracked and loose. Repoint deteriorated mortar joints at the remainder of that chimney. Provide new copper flashing and add sealant.
- Replace sealants (caulking) in numerous locations at flashing reglets.
- Re-design and refabricate some of the flashing details that are either open to the weather or do not allow positive drainage.
- Inspect solder joints in flat seamed copper roofing, gutters and downspouts in the problem area and clean and re-solder cracked or defective joints, replacing some of the copper elements where necessary.
- Cut back brick parapet wall at the chimney to eliminate vulnerable through-wall downspout detail.



Town of Belmont School Administration Building: Proposed CPA Project South Chimney and Limited Copper Roof Repair – Cost Estimate September 28, 2023

WORK ITEM:	ESTIMATED COST:	
General Conditions, Staging, Access, etc.	\$ 20,000	
Rebuild/ Repoint South Chimney: - including new capstone, flashing, & mortar wash	\$ 16,000	
Replace Flat Seam Copper Roofs: - including new blocking, sheathing, flashing, etc.	\$ 40,000	
Cut Back Parapet Wall:	\$ 6,000	
Limited Wood Eave and Trim Repair:	\$ 4,000	
Limited Slate Roof Repair:	\$ 8,000	
Limited Copper Gutters/Downspouts Replacement:	\$ 6,000	
Construction Sub-Total:	\$ 100,000	
Contractor Overhead and Profit (15%):	\$ 15,000	
CONSTRUCTION COSTS:	\$ 115,000	
Inflation Adjustment (5% per year):	\$ 5,750	
Construction Contingency (15%):	\$ 18,115	
Soft Costs: Architectural/Engineering Fees, Permitting, etc. (15%):	\$ 20,830	
TOTAL PROJECT COST:	\$ 159,695	
















PROPOSED CPA SCOPE - SOUTH ELEVATION

 $\frac{1}{8}$ " = 1'-0"



Spenc

Spencer Preservation Group
PRESERVATION ARCHITECTS
WWW.

41 Valley Road | Suite 211B
Nahant, MA 01908
(617) 227-2675
www.SpencerPreservationGroup.com

CLIE

TOWN OF BELMONT 455 CONCORD AVE BELMONT, MA 02478 PROJECT:

#2312-R


BELMONT CIVIC COMPLEX
MULTI-BUILDING CONDITIONS ASSESSMENT

TITLE:

PROPOSED CPA SCOPE: CHIMNEY AND ROOF REPAIR SOUTH ELEVATION OCT. 02 2023

A-1

OF



PROPOSED CPA SCOPE - WEST ELEVATION

Spencer Preservation Group PRESERVATION ARCHITECTS

(617) 227-2675 www.SpencerPreservationGroup.com

TOWN OF BELMONT 455 CONCORD AVE BELMONT, MA 02478

PROJECT:

#2312-R

BELMONT CIVIC COMPLEX MULTI-BUILDING CONDITIONS ASSESSMENT

PROPOSED CPA SCOPE: CHIMNEY AND ROOF REPAIR WEST ELEVATION

OCT. 02 2023

OF








AERIAL VIEW OF SCHOOL ADMINISTRATION BUILDING LOOKING NORTHWEST. PROPOSED CPA SCOPE AREA OUTLINED IN RED.



AREA OF INTERIOR WATER DAMAGE AT SOUTHWEST STAIRWELL.




AREA OF INTERIOR WATER DAMAGE AT S.E. CORNER OF SUPERINTENDENT'S OFFICE.



AREA OF INTERIOR WATER DAMAGE AT ATTIC EAST OF ELEVATOR DORMER. EVIDENCE OF STAINING ON ROOF STRUCTURE AND PRESENCE OF ACTIVE LEAK.



SOUTHWEST CORNER OF SCHOOL ADMIN. BUILDING. EFFLORESCENCE AND BRICK DAMAGE VISIBLE AT SECOND LEVEL BY CHIMNEY WALL AND DOWNSPOUT.



OVERALL VIEW OF DETERIORATED CHIMNEY, FLAT SEAM COPPER, AND INTERSECTING ROOF PLANES.



VIEW OF IMPROPER FLASHING DETAIL AT ROOF INTERSECTION. BROKEN SOLDER SEAMS, MORTAR DETERIORATION, AND CRACKED CAULKING VISIBLE.



DAMAGED AND DETERIORATED WOOD TRIM AND FASCIA BOARDS REQUIRE REPLACEMENT.



VIEW OF CRACKED BRICKS, DETERIORATED MORTAR, AND DAMAGED CAPSTONE AT SOUTH CHIMNEY.

Spencer Preservation Group

PRESERVATION ARCHITECTS

41 Valley Road | Suite 211B Nahant, MA 01908 (617) 227-2675 www.SpencerPreservationGroup.com TOWN OF BELMONT 455 CONCORD AVE BELMONT, MA 02478 PROJECT:

BELMONT CIVIC COMPLEX
MULTI-BUILDING CONDITIONS ASSESSMENT

#2312-R

PROPOSED CPA SCOPE:
CHIMNEY AND ROOF REPAIR
SITE PHOTOS

1-3

A-3

OF

OCT. 02 2023










POOR FLASHING DETAIL AT INTERSECTION OF FLAT SEAM COPPER ROOF AND CHIMNEY. CRACKED CAULKING AT REGLET, PUNCTURED COUNTER-FLASHING, AND PRESENCE OF BLACK MASTIC.



OPEN MASONRY JOINTS WHERE ELEVATOR DORMER ROOF MEETS NORTH FACE OF CHIMNEY.



OPEN MASONRY JOINTS WHERE ELEVATOR DORMER ROOF MEETS NORTH FACE OF CHIMNEY.



POOR FLASHING DETAIL AT INTERSECTION OF CHIMNEY AND BRICK PARAPET (RIGHT). CRACKED CAULKING AND SEALANT VISIBLE AT REGLET AND BROKEN SOLDER SEAMS THROUGHOUT.



THROUGH WALL DRAIN/DOWNSPOUT DETAIL AT PARAPET. COMBINATION OF BROKEN SOLDER SEAMS AND POOR FLASHING CAUSING MASONRY DAMAGE BELOW.

Spencer Preservation Group PRESERVATION ARCHITECTS

Nahant, MA 01908 (617) 227-2675 www.SpencerPreservationGroup.com

TOWN OF BELMONT 455 CONCORD AVE BELMONT, MA 02478

CLIENT:

PROJECT:

BELMONT CIVIC COMPLEX MULTI-BUILDING CONDITIONS ASSESSMENT PROPOSED CPA SCOPE: CHIMNEY AND ROOF REPAIR SITE PHOTOS

OCT. 02 2023