Town Belmont	OFFICE USE
Historic District Commission	Case Number: HDC –
Homer Municipal Building, 2nd Floor	
19 Moore Street	
Belmont, MA 02478	
APPLICATION	
In accordance with the Historic Districts Act, MGL Ch 40C, and the Town of Belmont General Bylaws,	
§40-315, the undersigned applies to the Belmont Historic District Commission for a Certificate of: Appropriateness In Non-Applicability	
Appropriateness Non-Applicability Hardship	
1. PRELIMINARY INFORMATION:	
Address of Property: 11 PLENSANT ST BECMONI MY 0247B - FORCADE RESIGRATION	
Property Owner's Name: CARL GTOPA FOR HUTCH 571 Pay An	
Address: <u>YU PLEAGOANT GREET, BELMONT, ANT OZA</u> TO Email: <u>duriser ipmanlighting, com</u> Phone: <u>617-968-5027</u>	
Email: dwiseripmanlighting.com Phone: 617-96B-5027	
Agent Name: NA	
Address:	
Email: Phone:	
I am the : K Property Owner Agent	
Mr Property is Owned by a Corporation, LLC, or Trust (Submit authorization to sign as owner)	
MAP Property is a Condominium or Cooperative Association (submit authorization to sign as trustee)	
If applicable: Architect: Contractor: CHORS VACSTYN/PINNACUE	
2. BRIEF DESCRIPTION OF PROPOSED WORK:	
REPLACE IN KIND PART TO MATCH VARIOUS EXTENIOR ROTTED WOOD:	
FLONT PORCH (GREET 1200F), SIDING (GAST FACADE) + TREM (LINNIFED)	
ANEA, REAR aUTTERS + TREM VBOARDS, BASEMENT DOBN + WINDOW,	
TRANG NON DECK, SEE SCAPE PROTOS, DOCS + SUTE POIN	
ATTAOLOD,	
3. <u>SIGNATURES</u> :	
As Owner, I make the following representations:	
A. I hereby certify that I am the Owner of the Property at: 711 PCEASAN 5, BECMON, MA OUTPE	
B. I hereby certify that if an Agent is listed on this Application, this Agent has been authorized to represent this	
Application before the Belmont Historic District Commission.	24 11 40 22
Owner:	Date: 24 MARZ3
As Applicant/Agent, I make the following representations:	
1. The information supplied on and in this Application is accurate to the best of my knowledge;	
2. I will make no changes to the approved plans without prior approval from the Belmont Historic District	
Commission.	
Applicant/Agent:	Date:
* Incomplete explications and tractfining t	
* Incomplete applications and Insufficient documentation will not be accepted. *	
	Approved March 23, 2017

RIPMAN LIGHTING CONSULTANTS

711 PLEASANT STREET BELMONT, MASSACHUSETTS 02478

> www.ripmanlighting.com 617-489-3366

24 March 2023 Re: 711 Pleasant Street – HDC Application 1 – Façade Restoration

BELMONT HISTORIC COMMISSION

Applicant Statement

Façade restoration project (deferred maintenance). Replace in kind / paint to match various existing rotted wood: front porch (except roof); replace siding and trim (northeast façade, limited area at tool porch first floor); rear wood gutters and trim boards; basement door and window; trellis over deck. See scope photos, plot plan, site section attached.

I walked the property and the proposed work with Carl Solander and he had no objections to the proposed work.

Reason for the Proposed Changes

Deterioration of existing wood due to age of structure. Routine maintenance.

Will This Affect Abuttors?

No. See communications from abuttors attached.

HDC Objectives and Standards

The project will restore the property to its former condition which is consistent with the objectives and standards of the Historic District Commission.

Photographs

See photographs attached.


Manufacturers' Product Literature


See product specs for basement door attached as requested by Carl.


Sincerely yours,


Christopher Hugh Ripman AIA President **RIPMAN LIGHTING CONSULTANTS**


C:\Users\Chris\Desktop\0 Desktop Shells\HDC1 Applicant Statement 24MAR23.doc 3/24/2023 4:08 PM




























SCOPE

All work will be to match existing, in terms of materials and finish. Spring work (some could be done in the fall). Working hours 8-5. Dispose of demo'd materials offsite. Onsite storage of material only as permitted by owner, at contractor's risk. Provide insurance certificates and references. Do not block 721's use of driveway and access to their parking (shared drive). See photos attached for budget pricing.

Scope 1 - Rebuild front porch, replace all treads with fir, new stair trim, new lattice, replace any rotted posts and stringers, replace section of eave molding to match existing. Prime including back painting all new wood before installation, two coats of paint, all to match existing (typical for all new wood in all scopes).

Scope 2 – relamp Christmas lights at eaves and chimney. Sweep chimney, pull wood stove and shop vac out soot, reconnect wood stove. Paint two new struts holding wisteria trellis at brick patio. Install new Plexiglas shield at head of skylight to match others, caulk skylight and secure new shield with roofing pitch at head of all three linear skylights in master bath (minor leak).Repair drywall in bathroom (two skylight heads).

Scope 3 - remove and replace to match existing cedar bevel siding and trim at east wall of tool porch. Replace damaged sheathing under with waterproof ply. New flashing as required. Replace damaged window sill locations (2) at bedroom above with new cedar or fir sills to match.

Scope 4 - remove and replace to match four rear gutters and backer boards, one trim board rotted at triangular bathroom wall above skylight. New roof flashing as required. Remove and replace existing cedar trellis over deck. Prop up trellis while replacing gutters, protect wisteria vine and reattach to new trellis.

Scope 5 - reglaze large thermopane window at brick patio with new thermopane, replace basement door with new thermopane. Reglaze existing triangular bathroom window with new thermopane. Replace existing storm door with screen and window inserts at rear (uphill) door.



SCOPE 1 - REBUILD FRONT PORCH TO MATCH EXISTING. FIR TREADS, PT STRINGERS, LATTICE, PINE TRIM, RAILINGS + POSTS. REPLACE SECTION OF MISSING ROOF TRIM. PRIME AND TWO COATS OF




FINISH PAINT ON ALL NEW WOOD.

(INCLUDING BACKPAINT), TO MATCH

EXISTING. TYPICAL FOR ALL NEW SIDING













ma.







SCOPE 2 - RELAMP EXISTING CHRISTMAS LIGHTS

STRUTS HOLDING WISTERIA AT BRICK PATIO WEST SIDE. INSTALL NEW PLEXIGLAS SHIELDS AT THREE

Chris Ripma

711 Scopes

Scope 1 - 1


TO SUDJert.

EXISTING SKYLIGHTS IN MASTER BATHROOM,

CAULK IN WITH ROOFING MASTIC.
















SCOPE 2 - RELAMP EXISTING CHRISTMAS LIGHTS UNDER EAVES.









- Care



SCOPE 2 - PAINT 2 NEW STRUTS HOLDING WISTERIA AT BRICK PATIO EAST SIDE.





SCOPE 2 - PAINT 2 NEW STRUTS HOLDING WISTERIA AT BRICK PATIO EAST SIDE.





75

SCOPE 2 - INSTALL NEW PLEXIGLAS SHIELDS AT THREE EXISTING SKYLIGHTS IN MASTER



BATHROOM, CAULK IN WITH ROOFING MASTIC.



SCOPE 2 - INSTALL NEW PLEXIGLAS SHIELDS AT THREE EXISTING SKYLIGHTS IN MASTER



BATHROOM, CAULK IN WITH ROOFING MASTIC.



ROTTED TRIM AT TOOL PORCH. REPLACE

A DE LE MARKEN

DAMAGED AND MISSING WINDOW SILL

BOARDS AT SECOND FLOOR PORCH

BEDROOM WINDOWS



SCOPE 3 REMOVE + REPLACE TO MATCH BEVEL SIDING, SHEATHING, FLASHING AND

ROTTED TRIM AT TOOL PORCH.







ROTTED TRIM AT TOOL PORCH. REPLACE

DAMAGED AND MISSING WINDOW SILL

BOARDS AT SECOND FLOOR PORCH

BEDROOM WINDOWS



SCOPE 3 REPLACE DAMAGED AND MISSING WINDOW SILL BOARDS AT

SECOND FLOOR PORCH BEDROOM WINDOWS







15

SCOPE 3 REPLACE DAMAGED AND MISSING WINDOW SILL BOARDS AT

and the second

12.4

SECOND FLOOR PORCH BEDROOM

WINDOWS







SCOPE 3 REPLACE DAMAGED AND MISSING WINDOW SILLS AT SECOND

FLOOR PORCH BEDROOM WINDOWS







SCOPE 4 REMOVE AND REPLACE IN KIND THREE REAR GUTTERS AND BACKER BOARDS, PLUS ONE ROTTED TRIM BOARD AT TRIANGULAR WINDOW IN MASTER BATHROOM





SCOPE 4 REMOVE AND REPLACE IN KIND THREE REAR GUTTERS AND BACKER BOARDS, PLUS ONE ROTTED TRIM BOARD AT TRIANGULAR WINDOW IN MASTER BATHROOM

ABOVE SKYLIGHT. NEW ROOF FLASHING AS REQUIRED.





ABOVE SKYLIGHT. NEW ROOF FLASHING AS REQUIRED.

CHIC



Con griller

SCOPE 4 REMOVE AND REPLACE IN KIND THREE REAR GUTTERS AND BACKER BOARDS, PLUS ONE ROTTED TRIM BOARD AT TRIANGULAR WINDOW IN MASTER BATHROOM







T





ABOVE SKYLIGHT. NEW ROOF FLASHING AS REQUIRED.

-















annite


ILEANA COM

SCOPE 4 REPLACE EXISTING TRELLIS OVER DECK . PROTECT WISTERIA VINE AND REATTACH TO NEW TRELLIS.





SCOPE 4 REMOVE AND REPLACE IN KIND ONE ROTTED TRIM BOARD AT TRIANGULAR WINDOW IN MASTER BATHROOM ABOVE TRAPEZOIDAL WINDOW.













TO NEW TRELLIS.





SCOPE 4 REMOVE AND REPLACE EXISTING TRELLIS OVER DECK. PROTECT WISTERIA VINE AND REATTACH TO NEW TRELLIS.





SCOPE 4 REMOVE AND REPLACE EXISTING TRELLIS OVER DECK PROTECT WISTERIA VINE AND REATTACH TO NEW TRELLIS.

100





SCOPE 5 REGLAZE LARGE EXISTING THERMOPANE WINDOW TO BASEMENT (OUTER LIGHT BROKEN) TO MATCH EXISTING REPLACE THERMOPANE DOOR TO BASEMENT (OUTER LIGHT BROKEN, NOT

REPLACEABLE(), TO MATCH EXISTING.



SCOPE 5 REGLAZE LARGE EXISTING THERMOPANE WINDOW TO BASEMENT (OUTER LIGHT BROKEN) 46.5" X 76.5", TO MATCH EXISTING REPLACE THERMOPANE DOOR TO BASEMENT (OUTER LIGHT BROKEN, NOT




REPLACEABLE) 32" X 6'-5", WITH FIR DOOR TO MATCH



SCOPE 5 REPLACE THERMOPANE DOOR TO BASEMENT (OUTER LIGHT BROKEN, NOT REPLACEABLE(), TO MATCH EXISTING.

2





SCOPE 5 REPLACE EXISTING STORM DOOR AT REAR ENTRANCE (ROTTED) WITH NEW TO MATCH EXISTING, WITH STORM AND SCREEN INSERTS.

-


The l

NO.





SCOPE 5 REGLAZE EXISTING TRAPEZOIDAL WINDOW IN MASTER BATHROOM (CRACKED).







SCOPE 5 REGLAZE EXISTING TRAPEZOIDAL WINDOW IN MASTER BATHROOM (CRACKED).









PROPOSAL



The Roofing Specialists

Name:	Chris Ripman
Address:	Pleasant Street Belmont, MA 02478

Email: chris@ripmanlighting.com

Chris Valstyn Pinnacle Exteriors Inc. 34A Olcott St, Apt 1 Watertown, MA 02472

Office: (617) 237-2855 **Cell:** (617) 548-3157 **Email:** chris@pinnacleroofingma.com

CSL# 064930 **HIC**# 182365

Date Prepared: March 1, 2023

Terms: We hereby submit specifications and estimates for:

FRONT PORCH

- 1. Support existing roof over front porch. Demolish existing front porch only (roof system to remain).
- 2. Frame porch to exact dimension using P.T. 2 x 8 for joists and P.T 2 x 12 for stringers.
- 3. Dig footing for 12" concrete sonar tubes 4'feet deep. Fill with 3500 psi concrete.
- 4. The decking will consist of 1 x 4 fir or equal. Post will consist of 4 x 4 # 1 fir. Railing system will consist of 1 ¼ balusters, 5" inches on center. The top and bottom rails will consist of fir. The trim will consist of 1 x 10 and 1 x 12 Centurion solid gold P.T, non-finger jointed prime trim boards. All other wood will be back primed with oil based exterior primer, all cut ends to be primed.
- 5. Paint all wood with 2 coats of Benjamin Moore or equivalent.

Total Cost\$14,850.00

WALL REPAIR

- 1. Remove, replace to match cedar clapboard siding (east wall). Replace the sheathing as needed with P.T. plywood. Replace all rotted trim with Centurion solid gold trim boards.
- 2. Replace rotted, damaged sills with new cedar of composite sills to match. Install all proper flashing.
- 3. Prime and paint two (2) coats. Additional unforeseen damage will be billed time and material (\$95 hr/ carpenters & \$65 hr/laborers.

Total Cost \$3,600.00

GUTTERS AND TRIM (REAR)

- 1. Remove all wood gutter and fascia and replace with (solid gold) trim and 4 x 5 fir gutter. Apply two (2) flood coats of linseed oil to trough.
- 2. Rebuild trellis (protect vine) using fir 2 x 6. Back prime all wood and cut with oil-based primer.

Total Cost \$7,200.00

DOOR / WINDOW

- 1. Re-glaze 42" x 78" thermopane window, driveway side.
- 2. Replace full light basement door with a new full light 32" x 80" door. Replace interior and exterior trim.
- 3. Prime and paint all wood.
- 4. Replace existing storm door at rear of house (labor only).

Total Cost \$3,200.00

CHRISTMAS LIGHT

1. Remove or secure Christmas lights (driveway side gable).

Total Cost \$700.00

WE PROPOSE hereby to furnish material and labor - complete in accordance with the above specification, for the sum of (\$).

Payments to be made as follows: 1/3 down, 1/3 at halfway point, 1/3 upon completion

All material is guaranteed to be specified. All work to be completed in a workmanlike manner according to standard practices or in accordance with the drawings and specifications submitted for the above work. Our workers are fully covered by Workman's Compensation Insurance.

ACCEPTANCE OF PROPOSAL - The above prices, specifications and conditions are satisfactory and are hereby accepted. You are authorized to do the work as specified Authorized Signature

Note: This proposal may be withdrawn by us if not Accepted within 30 days.

Signature____

Signature ____

Date of Acceptance _____

Chris Ripman

From:	Romain Aubanel <romainaubanel@gmail.com></romainaubanel@gmail.com>
Sent:	Friday, March 24, 2023 2:08 PM
То:	Chris Ripman; Julie Battilana
Subject:	Re: 711 Pleasant Street - Repair Projects Submitted to the Historic District Commission

Hello Chris,

That sounds great ! We have no objection of course

Thanks for the heads up

Have a great weekend

Le ven. 24 mars 2023 à 13:58, Chris Ripman <<u>Chris@ripmanlighting.com</u>> a écrit :

Greetings!

My house is sorely in need of façade repairs, all replace in kind and paint to patch. No changes in design. Major scope is to replace the front porch, which is rotting, and replace rotted or missing trim around the house, replace some siding on the east façade which has rotted, replace existing gutters and trellis which have rotted, and replace the basement door and adjacent window which have lost their outer pane of thermopane glass. This is one project I am submitting.

The second project has to do with replacing the majority if not all of the existing railroad tie retaining walls with either railroad ties (6x8) or pressure treated timber (also 6x8). This project is not urgent, so it may take place in the fall so as to minimize damage to the landscape, but I am going for review and approval from the Historic District Commission in advance.

I met with a representative of the HDC on site and walked him through it, and it was his opinion that as long as all work proposed was a "replace to match existing / paint to match" the HDC would approve the projects.

If you would like to get together to walk through the proposed work I am happy to do that at your convenience. The HDC meets the evening of the 11th of April. If you have no objections, let me know and I will pass that on to the HDC.

With best regards

Chris Ripman

711 Pleasant St Belmont, MA 02478

--Romain Hi Chris,

Of course. We have no objections to maintenance!

Best wishes, Rachel

> On Mar 25, 2023, at 9:46 AM, Chris Ripman < Chris@ripmanlighting.com> wrote:

>

> Good morning!

>

> I am working to put together applications for two repair projects at 711. The applications are due to the HDC by end of day Monday. One is for deferred facade maintenance, replacing limited rotted trim and siding and most of the front porch and the trellis over the deck and the rear gutters, in kind, and paint to match. No design changes. The second is to replace the railroad tie walls on the property which are also deteriorating, with either railroad ties (getting harder to get) or similar 6x8 landscape timbers.

> If you have no objections, I think it would help expedite review by the HDC if you could send me an email to that effect in time to include it with the applications Monday. I have one to that effect from Romain and Julie.

>

>

> Happy to meet this weekend and walk you through the proposed work if that would be helpful.

>

> Please give me a call at your convenience if you have questions or would like to review the proposed work.

>

> Best regards and thanks!

>

> Chris

>

> Sent from my iPhone. Please forgive creative interventions by Siri.

>





MAHOGANY • FIR • OAK

Since 1890, BROSCO has been the leader in Wood Entry Door Systems in the Northeast. Carrying a longstanding tradition of quality workmanship and innovative designs, we are proud to offer the following selection of Mahogany, Fir, Oak and Knotty Alder doors as well as sidelights, designed for our rugged Northeast weather.



Simpson Nantucket[®]



Simpson Custom



Simpson Bungalow®



Simpson WaterBarrier*



Simpson Traditional

Have your next door unit Built by BROSCO!

Jeld-Wen IWP® Custom

When you have an exterior door unit Built by BROSCO this will give you peace of mind that the certified door unit was built by professional craftsman and the unit will not warp, bow, leak or crack.







STANDARD FEATURES

- 49/16" Primed Wood Frame Inswing
- Limited Lifetime Warranty
- Brickmould Exterior Casing Primed
- · Compression Type Weatherstripping and Corner Seals
- Bulb and Fin Door Bottom
- Aluminum Sill (mill finish) with Thermal Break, Hardwood Adjustable Threshold and Interior Strip (Inswing) with protective "Construction Cover."
- 4" x 4" Zinc Dichromate Hinges (dull brass color)
- Single Bore 2³/₈" Backset (2¹/₈" Facebore)
- Double Door Units White Aluminum Ultimate Flip Astragal included (w/Flush Bolts)

POPULAR OPTIONS

- Jambs Clear Pine, Clear Fir, Clear Oak and Clear Mahogany various widths
 Vinyl Clad Wood Frame
 - Composite; Primed, White Cap & Mahogany-Grained
- Casing Primed or Clear Pine Flat (1¹/₁₆" x 3¹/₂"), Primed Cape Cod Flat (¹¹/₁₆" x 4¹/₂") or Clear Cedar (1¹/₁₆" x 3¹/₂")
 - Clear Pine, Oak and Mahogany Brickmould
 - Composite Brickmould; Primed, White Cap & Mahogany-Grained
 - Low-Maintenance PVC Trim
 - Decorative PVC Entrance Trim
- Sill Oak or Mahogany, Bronze, Satin Nickel or Brass Aluminum (Anodized Finish), Composite or Public Access (aluminum)
 - Sill Pan for Installation of 4-9/16" and 6-9/16" Walls WeatherOut Flashing
- Hinges Solid Brass, Bright Brass, Satin Brass, Antique Brass, Antique Bronze Lacquered, Colonial Bronze, Dark Bronze, Antique Nickel, Satin Nickel, Satin Chrome, Polished Chrome,Black, Primed and Stainless Steel
- Hardware Door Viewer, Brass Ball Tips, Mailslot, Kickplates and Door Closers
 Multi-point Lock System

• Deadbolt Prep – 2¹/₈" Facebore located 5¹/₂" on center above Lockset. Lockguard Security Plate included with deadbolt prep (see below)

• Storm Door Adapter (for Sidelight Units) - Primed, Clear Pine and Clad Plus II.



BROSCO's Lockguard Security Plate adds the strength of steel to the wood jamb, at the critical location of the latchbolt and deadbolt. Forced entry results in pressure at the latchbolt. A wood frame will usually splinter in this area before the hardware fails.

The Lockguard Security Plate, when attached to a wood frame along with a deadbolt, provides the best resistance to forced entry next to a steel frame.

This is a standard feature with the deadbolt prep option on BROSCO Single Wood Entry Units.

Basement Door (to match existing)



Exterior Wood Doors



WATERBARRIER[®] DOORS

WaterBarrier technology features a medium density overlay over the exterior surface of the door with PVC bars and glazing beads, providing a beautiful surface for paint. And all with the beauty of Douglas Fir on the inside of the door. Simpson doors with WaterBarrier offer protection in tough exposures.

No Overhang Required for Warranty

- 1-7/16" Innerbond[®] Double **Hip-Raised Panels**
- · Fir Interior
- UltraBlock[®] Technology
- 5-Year Warranty
- Performance Series





F-37015U-W 2'-6". 2'-8". 3'-0" x 6'-8" 3'-0" x 7'-0"

F-7082U-W 2'-6", 2'-8", 3'-0" x 6'-8"

F-7130U-W 2'-8". 3'-0" x 6'-8"




F-37705U-W F-37663U-W 1'-2" x 6'-8" 1'-2" x 6'-8" 1'-2" x 7'-0"

WATERBARRIER® TECHNOLOGY (PATENT PENDING)

F-7002U-W


2'-6". 2'-8".

3'-0" x 6'-8"



Entire stile-and-rail joints coated and bonded to decrease the possibility of water infiltration

Composite block material finger-jointed into the bottom of the stiles



Custom sizes available. Ask your BROSCO Dealer.