TABLE 3

BUILDING INSPECTION AND DYED-WATER TRACING RESULTS WELLINGTON BROOK & WINN'S BROOK TRIBUTARY AREAS BELMONT, MASSACHUSETTS

Address	Sub-Catchmer	nt No. of Tests	Date	Dye Test Entry	Sewer Connection	Dye I	Discharge	Sump	Suma Buma Disaharaa	Other Pines	Comments
No. Street	Area	Conducted	Date	Dye lest chiry	Contamination Source	% Sewer	% Storm Drain	Pumps	Sump Pump Discharge	Other Pipes	Comments
30 Bow Roa	d 8-1	3	10/24/2017	Basement Toilet, Basement Sink, First Floor Sink		Inconclusive	Inconclusive	1	Two (2) sumps pumps. Both do not appear to tie into sewer stack.	None	Could not see dye in either SMH or DMH across from house. Moved to SMH at Bow/School intersection and believed to see traces of dye (rapid flows due to pipe slope). Flow was also diluted by incoming flow from Lincoln street. No dye seen in DMH at Bow/School intersection after 35 minute wait.
38 Bow Roa	d 8-1	1	11/6/2017	Basement Sink		100	0	1	Unsure of connectivity.		Spoke with homeowner, who is also a civil engineer. Has all runoff leaded to dry well in abck yard. No trace of dye in drain manhole.
41 Bow Roa	1-8 E	1	10/24/2017	Basement Sink		100	0	0	N/A	None	Dye was seen 100% in SMH at Bow/Lincoln intersection. No dye seen in DMH after 15 minute wait.
44 Bow Roa	d 8-1	3	12/1/2017	Basement Sink; Basement Toilet; 1st Floor Sink		100	0	1	Believed to be sewer. No rising outlet - see photo.	None	Completely finishged basement- no stacks seen. Conducted 3 tests, No trace of dye was seen in the DMH at Bow/Lincoln.
51 Bow Roa	d 8-1	1	10/24/2017	Basement Sink		100	0	0	N/A	Open Cleanout	Open cleanout in basement floor. Dye was seen 100% in SMH at Bow/Lincoln intersection rapidly after test. No dye seen in DMH at Bow/Lincoln intersection for 10-15 minutes after test was conducted.
53 Bow Roa	d 8-1	1	11/6/2017	Basement Sink		100	0	1	Ground		Only could see trace amounts in dye depsite 7 minutes between dye entry and SMH opening. No trace of dye seen in DMH after 30 minute wait.
150 Common St	reet 8-2	1	11/15/2017	Basement Sink		100	0		Ground		New sewer stack - all branches (ex: upstairs bedroom) labeled. Observed manholes on Orchard St by school. Bright dye seen in SMH after 10 minutes.
9 Brettwood R	oad 8-5	1	11/21/2017	Basement Sink		100	0	1	Ground		Dye in SMH (Homer @ Brettwood) seen after 8 minutes. No trace seen in DMH (Homer @ Brettwood)
12 Brettwood R	oad 8-5	2	12/1/2017	Basement Sink; 1st Floor Sink	Indirect	80	20	0	N/A	Small trench drain by basement door.	2 Sewer stacks were seen - outlet from basement sink does not visually tie in to stack. May tie in under slab? Dye was relatively strong in DMH at Brettwood/Pierce. House ties in to sewer on Homer Road. See photos.
17 Brettwood R	oad 8-5	1	11/3/2017	Basement Sink		100	0	1	Ground		3 sewer stacks that all merge together. Can visually see the mortar patch in basement sllab (recently redone).
22 Brettwood R	oad 8-5	1	11/21/2017	Basement Sink		100	0		N/A		Took 20 minutes to see dye at Brettwood/Pierce intersection. No trace seen after 35 minute wait. Dye seen in SMH (Pierce @ Brettwood) aftern 20 minutes.
25 Brettwood R		1	11/3/2017	Basement Sink		100	0	1	Possibly sewer - see photo.		One sewer stack seen. Sump Pump may tie into the sewer service line. 100% Dye seen in the SMH after 20 minute wait. No dye seen in DMH after 35 minutes.
28 Brettwood R		1	11/15/2017	Basement Toilet		100	0	UNK	Did not check.		Took roughly 35 minutes to see dye in SMH at Pierce/Brettwood intersection. No trace in DMH after 50 minutes.
31 Brettwood R		1	11/10/2017	Basement Sink		100	0	1	Ground Surface		Dve seen in SMH after 23 minutes: no trace seen in DMH.
36 Brettwood R		1	11/3/2017	Basement Sink		100	0	0	N/A		Dye seen in SMH after 10 minute wait. No trace seen in the DMH.
		,				100	0	2			Dye seen in SMH after 12 minutes. No trace seen in the DMH.
37 Brettwood R		'	11/13/2017	Basement Sink			-	2	Unknown		
43 Brettwood R		!	11/10/2017	1st Floor Toilet		100	0	0	N/A		Dye seen in SMH after 23 minutes. No trace seen in DMH.
48 Brettwood R											Appt scheduled Thurs 12/7 @ 8:00; No acess obtained.
51 Brettwood R		1	11/21/2017	Basement Sink		Inconclusive	Inconclusive	1	Ground		Observed DMH & SMH at Pierce@Brettwood for an hour; no dye seen. SMH appears to have slight blockage at inlet - see photo.
57 Brettwood R	oad 8-5	2	11/6/2017	Basement Sink, First Floor Sink		100	0	1	Ground		Dye bright in SMH. Did not see any trace of dye in the DMH after a 30 minute wait.
63 Brettwood R	oad 8-5	1	11/21/2017	Basement Sink		100	0	0	N/A		Saw dye in SMH (Brettwood @ Hastings) after 10 min. Believed to have seen a trace while in field, but photos do not confirm.
69 Brettwood R	oad 8-5	1	11/28/2017	Basement Sink		Inconclusive	Inconclusive	0	N/A		Did not see dye in Manholes by Hastings after 30 minute wait. Property owner mentioned the sewer service pipe was going to be fixed (see photos). This may have effected the result.
10 Homer Ro	ad 8-5	0	10/24/2017	Not Conducted		Not tested	Not tested	1	One (1) sump pump seen. Does not connect to sewer stack.	None	Visually apparent that house ties into Homer Road sewer (not Pierce Road sewer) based on sewer stack positioning.
22 Homer Ro	ad 8-5	2	10/13/2017	Basement Sink and First Floor Toilet		100	0	2	One (1) sump to sewer; One (1) to back yard dry well	Yes - Perimeter french drain to sump pumps	Dye tested all identifiable stacks / sources; finished basement; sewer to Homer Rd
8 Pierce Roo	ıd 8-5	2		Basement Sink and First Floor Toilet		100	0	0	N/A		Dye seen in SMH after 10 minutes; no trace in DMH after 30 minutes.
11 Pierce Roo	id 8-5	1	10/19/2017	Basement Sink	Indirect	90	10	0	N/A	Basement Drain (Connects to sewer stack)	Sump pit with drain to sewer stack. Traces of dye visible in Drain Manhole. Appears to be an indirect connection.
14 Pierce Roo	ıd 8-5	1	11/15/2017	Basement Sink		100	0	0	N/A		Bright dye seen in SMH at Pierce/Brettwood intersection after 6 minutes. No trace in DMH after 30 minutes,
17 Pierce Roo	ıd 8-5	3	12/1//17	Basement Sink; 1st Floor Sink; 1st Floor Toilet		100	0	1	Sump pump is not hooked up yet. Pit is installed.	Yes - drain pit and outlet. Unsure of connectivity.	Conducted 3 tests. No trace was seen in DMH at Brettwood/Pierce after a 30+ minute wait.
22 Pierce Roo	ıd 8-5	3	12/6/2017	Basement Sink; First Floor Toilet; Upstairs Toilet		100	0	1	Ground (Front Yard)		Two sewer stacks in basement. No trace of dye seen in the DMH after 30 minutes.
28 Pierce Roo	id 8-5	1	11/6/2017	Basement Sink		100	0	0	N/A	French drain around property	Dye bright green in SMH. Did not see any trace of dye in the DMH after a 30 minute wait.
112 - 114 Bartlett Av	e 8-6	1	11/17/2017	First Floor Toilet		100	0	0	N/A	Cleanout for sewer stack in a pit.	Dye was seen in SMH at Bartlett/Jonathan intersection. No trace seen in DMH by park after 30 minute wait.
117 Bartlett Av	e 8-6	1	11/17/2017	Basement Sink		100	0	1	Connects to sewer stack (homeowner says its never used)		Dye seen in SMH at Bartlett/Jonathan intersection after 10 minutes; no trace in DMH after 30 minute wait.
116 - 118 Bartlett Av	e 8-6	1	11/20/2017	1st Floor Toilet		100	0	0	N/A		Dye dropped in at 10:05. Observed SMH at Bartlett/Jonathan at 10:18, 10:32; no trace. Observed again at 10:50 and finally saw a trace in the SMH. No trace seen in DMH by park,
121 - 123 Bartlett Av	re 8-6	1	11/17/2017	Basement Sink		100	0	1	Ground	Drain Pipe leaving basement 6" above floor slab.	House connects to sewer on King Street. Checked SMH at King/Banks and saw dye.
3 - 5 Jonathan St	reet 8-6										Dye Test to be conducted. Visit to property to be made on 11/15.
115 - 121 Maple Stre		1	11/8/2017	First Floor Toilet		100	0	2	Ground		Conducted test at #121 (upstairs) toilet. No dye seen at DMH for 20 minutes after test. Saw dye in SMH at Maple / Bartlett intersection.
37 Hoitt Roa		1	10/24/2017	(upstairs - #121) Basement Sink, First Floor Toilet (2	Indirect	80	20	0	N/A	2 stack pipes seen in separate rooms in basement.	Performed dye test on sink, then on two separate toilets . Constant stream of dye in SMH at Waterhouse/Hoitt intersection. Constant trace of dye
43 Hoitt Roa		1	10/14/2017	Toilets) First Floor Toilet		100	0	1	Cleanout Pit	Could not verify conenctivity to other plumbing. Could not confirm; Cleanout pit inaccessible	in DMH (somewhat faint) at Waterhouse/Hoitt intersection approx 20 minutes after dye tests had been performed. Appears to be a indirect connection. Sump pit under carpet by stairs. Inaccessible. Confirmed 2nd 2" pipe connected to 4" sewer stack by flushing sound test.
49 Hoitt Roa		1	10/14/2017	Basement Sink,		100	0	0	N/A	None - Could not find a cleanout.	Strong stream of dye in the Waterhouse/Hoitt intersection approximately 10 minutes after tests had been conducted.
		1	11/17/2017	First Floor Toilet		100	0	0	N/A	None - Coold Not lind a cleanout.	Waited another 15 minutes for dye in DMH at Waterhouse/Hoitt intersection, but no traces.
		1		Basement Sink						Basement is finished;	Dye was seen about 15 minutes in SMH after it was poured in basement sink. No trace seen in DMH after 30 minutes.
55 Hoitt Roa		1	10/20/2017	Basement Toilet		100	0	0	N/A One (1) sump pump connecting	Could not locate any structures	Could not locate anything visible. Sewer stack is in a wall, but the cleanout is accessible. No traces of dye seen in DMH. Discovered during dye test that the DMH across from #55 was bone dry. This manhole was apparently also bone dry during the 2008 investigations.
76 Hoitt Roa		1	10/18/2017	First Floor Toilet First Floor Bathroom Toilet,		100	0	1	to sewer stack.	None	Should have inspected this MH previously before conducting dye test.
54 Waterhouse	Rd 10-2	1	10/14/2017	Basement Sump Sink		100	0	1	Backyard buried drywells with perimeter french drain (new)	Perimeter French Drain	Sump pump pit new. Chronic root problems in service, according to homeowner.