

CHA

1. TOTAL PROJECT COST SUMMARY

Through December 31, 2022, Pro Pay 57

Description of Work	MSBA PFA Approved Nov. 2018	Current Project Budget (subject to MSBA BRR approval)	Committed Amount (approved/under contract)	Amount Paid to Date	Current Projected Final Cost, To Be Updated Monthly	Delta (Budget vs Projected)	Eligible Costs	Ineligible Costs	Balance to Finish (Current Project Budget vs. Paid to Date)
Feasibility Study Agreement									
OPM Feasibility Study	\$375,000	\$375,000	\$375,000	\$375,000			\$375,000	\$0	\$
A&E Feasibility Study	\$1,150,000	\$1,150,000	\$1,150,000	\$1,150,000	_	_	\$1,150,000	\$0	
Environmental & Site	\$46,000	\$46,000	\$46,000	\$45,955	_		\$46,000	\$0	
Other	\$179,000	\$179,000	\$179,082	\$179,082	_	-	\$116,932	\$62,068	
Feasibility Study Agreement Subtotal	\$1,750,000	\$1,750,000	\$1,750,082	\$1,750,037	\$1,750,037	-\$37	\$1,687,932	\$62,068	
Administration									
Legal Fees	\$100,000	\$100,000	\$61,984	\$75,112	\$80,000	\$20,000	\$0	\$100,000	\$24,88
Owners Project Manager	\$7,192,000		\$7,414,486	\$5,903,881	\$7,414,486	\$20,000	\$6,195,528	\$996,472	\$1,510,60
Advertising	\$10,000	\$10,000	\$258	\$683	\$1,000	\$9,000	\$10,000	\$330,472	
Permitting	\$200,000	\$200,000	\$0	\$0		\$200,000	\$0	\$200,000	
Owners Insurance	\$900,000	\$900,000	\$629,636	\$635,403		\$250,000	\$900,000	\$0	
Other Administration Costs	\$350,000	\$350,000	\$62,730	\$40,733	\$60,000	\$290,000	\$350,000	\$0	
Administration Subtotal	\$8,752,000	\$8,974,486	\$8,169,094	\$6,655,812	\$8,205,486	\$769,000	\$7,455,528	\$1,296,472	
Auditoria de Contractorio									
Architecture & Engineering Basic Services	¢20,800,000	\$20,800,000	¢21 276 40E	\$19,811,921	\$21,276,495	¢476 405	¢17.914.900	\$2,985,200	\$988,07
	\$20,800,000		\$21,276,495			-\$476,495	\$17,814,800		
Printing (over minimum) Other Reimburgable Costs	\$60,000	\$60,000	\$45,000	\$54,505 \$34,940	\$55,000 \$30,000	\$5,000	\$60,000	\$0 \$19,940	
Other Reimbursable Costs Hazardous Materials	\$275,000	\$46,646 \$275,000	\$27,906 \$275,000	\$177,987	\$175,000	\$16,646 \$100,000	\$275,000	\$19,940	
GeoTech & GeoEnvironmental	\$400,000		\$418,600	\$438,254		-\$21,400	\$418,000	\$0	
Site Survey	\$400,000		\$418,600	\$438,254		-\$21,400	\$418,000	\$0	
Traffic Study	\$0		\$106,328	\$90,623		\$0	\$86,828	\$0	
Architecture & Engineering Subtotal	\$21,535,000	\$21,695,599	\$22,165,741	\$20,616,755	\$22,071,848	-\$376,249	\$18,654,628	\$3,005,140	
Construction									
Pre-Construction Budget	\$446,582	\$446,582	\$550,494	\$446,582	See Summary	See Summary	\$446,582	\$0	\$
Construction Budget (Thru PCCO # 41)	\$236,647,607	\$239,790,691	\$254,159,081	\$226,037,414		See Summary	\$157,303,407	\$79,344,200	
Construction Subtotal	\$237,094,189	\$240,237,273	\$254,709,575	\$226,483,996	\$256,150,487	\$0	\$157,749,989	\$79,344,200	
Miscellaneous Project Costs									
Utility Company Fees	\$400,000	\$400,000	\$151,712	\$151,712	\$151,712	\$248,288	\$400,000	\$0	
Testing Services	\$500,000	\$500,000	\$490,877	\$435,001	\$425,000	\$75,000	\$500,000	\$0	
Swing Space	\$1,000,000	\$0	\$0	\$0	-	-	\$0	\$1,000,000	\$
Other Project Costs	\$840,000	\$840,000	\$167,285	\$255,003		\$615,000	\$0	\$840,000	
Miscellaneous Project Costs Subtotal	\$2,740,000	\$1,740,000	\$809,874	\$841,716	\$801,712	\$938,288	\$900,000	\$1,840,000	\$898,28
Furniture & Equipment									
Furniture, Fixtures, and Equipment	\$3,765,500		\$3,671,995	\$2,358,832		\$78,825	\$2,658,000	\$1,107,500	
Technology Furniture & Equipment Subtotal	\$3,322,500 \$7,088,000	\$3,322,500 \$7,088,000	\$1,503,864 \$5,175,859	\$1,692,189 \$4,051,021	\$2,430,000 \$6,116,675	\$892,500 \$971,325	\$2,658,000 \$5,316,000	\$664,500 \$1,772,000	\$1,630,31 \$3,036,97
i di inture di Equipment Subtotal	¥1,000,000	\$7,000,000	چوورد <i>۱</i> ۱,دچ	,4,031,021		<i>\$31</i> 1,323	73,310,000	γ1,772,000	, J5,050,57
Contingency									
Owners Contingency	\$2,000,000	\$2,000,000			\$1,214,423	\$785,577	\$0	\$0	\$
Construction Contingency (Thru PCCO # 35)	\$14,200,000				\$15,304,653	-\$3,247,737	-\$9,467,048	\$9,467,048	
Contingency Subtotal	\$16,200,000	\$14,056,916			\$16,519,076	-\$2,462,160	-\$9,467,048	\$9,467,048	\$
TOTAL BUDGET	\$295,159,189	\$295,542,274	\$292,780,225	\$260,399,337	\$295,096,245	\$2,302,327	\$182,297,029	\$96,786,928	\$21,086,02
Amount Daimhurand by MCDA there has been 52				604 705 777		eductions on Allowance	& Contingency Summa	ary Page	
Amount Reimbursed by MSBA thru Pro Pay 52 ProPay # 53 to 57 Submitted				\$64,795,523 \$9.444.808	•	· - pay amount to Tow	n is less		
, 55 10 57 5000000000				73,777,000	amount	pay amount to 10W			
					Covid Reimburse				Spent to Date
Taxpayer money spent to date after reimbursement:	\$260,399,337	-	\$64,795,523	-	\$331,473			\longrightarrow	\$195,272,341

(Initial MSBA Commitment)





2. CONTINGENCY EXPENDITURE LOG

Through December 31, 2022

A. Approved Owners Cost Contingency Utilization

Original Amount, Pre GMP	\$2,000,000
xfer to OPM (DPI)(Amend #6) for Steel Peer Review	-\$23,650
xfer to P&W Other Reimbursable Services -(Amend #3 partial) Soil Testing and Ice Rink Study	-\$18,740
xfer to P&W Reimbursable Services -(Amend. #3 partial) Geothermal Test Wells	-\$84,700
xfer to P&W Reimbursable Services -(Amend. #3 partial) Traffic Impact Study	-\$36,878
xfer to P&W Reimbursable Services -(Amend. #4) Concord Ave Signalization Study/Design BSC Group	-\$49,950
xfer to P&W Reimbursable Services(Amend. #4) -Other Reimbursable Services LEED Registration	-\$1,200
xfer to OPM (DPI)(Amend #8) for Automation Consultant	-\$180,180
xfer to OPM (DPI)(Amend #9) for Geothermal Oversite	-\$141,000
xfer to OPM (DPI)(Amend #10) for Geothermal Well Inspections	-\$58,000
xfer to OPM (DPI) (Amend #11) for Exterior Testing Services - BVH	-\$42,306
xfer to P&W additional Services -(Amend. #5) LEED Design Submission & Misc. Surveying	-\$35,231
xfer to P&W additional Services - (Amend. #6) IAQ Study / Structure & Final Design of Orchestra Pit	-\$89,550
xfer to P&W additional Services - (Amend. #7) Loading Dock Canopy & Slab Heat Rejection / Additional	-\$219,605
xfer to P&W additional Services- (Amend. #8) Additional Staff	-\$108,800
xfer to P&W additional Services - (Amend. #9) COVID Air Quality Sequence of Operations Rev	-\$4,950
xfer to P&W additional Services - (Amend. #10) Sidewalk connecting to Bike Path	-\$13,190
xfer to P&W additional Services - (Amend. #11) Traffic Signal Power, Striping, Drainage, Fiber	-\$19,050
xfer to P&W additional Services - (Amend. #12) Traffic Signal Coordination, Property Line	-\$8,337
xfer to P&W additional Services - (Amend. #13) WOHF Study	-\$34,850
xfer to P&W additional Services - (Amend. #14) Raise Grades Playing Fields & BSC Added Services	-\$19,256
xfer to CHA additional Geotech Services, Pond Irrig (Amend. #12) - VOID \$43,818 10/10/22, NOT RQD	\$0
xfer to P&W, Add Services (Amend # 15), Pond Irrigation Option, plus Playing Field Revisions, Amend	44665
	-\$16,065
	-\$8,195
· · · · · · · · · · · · · · · · · · ·	xfer to OPM (DPI)(Amend #6) for Steel Peer Review xfer to P&W Other Reimbursable Services -(Amend #3 partial) Soil Testing and Ice Rink Study xfer to P&W Reimbursable Services -(Amend. #3 partial) Geothermal Test Wells xfer to P&W Reimbursable Services -(Amend. #3 partial) Traffic Impact Study xfer to P&W Reimbursable Services -(Amend. #4) Concord Ave Signalization Study/Design BSC Group xfer to P&W Reimbursable Services(Amend. #4) -Other Reimbursable Services LEED Registration xfer to OPM (DPI)(Amend #8) for Automation Consultant xfer to OPM (DPI)(Amend #9) for Geothermal Oversite xfer to OPM (DPI)(Amend #10) for Geothermal Well Inspections xfer to OPM (DPI) (Amend #11) for Exterior Testing Services - BVH xfer to P&W additional Services - (Amend. #5) LEED Design Submission & Misc. Surveying xfer to P&W additional Services - (Amend. #6) IAQ Study / Structure & Final Design of Orchestra Pit xfer to P&W additional Services - (Amend. #7) Loading Dock Canopy & Slab Heat Rejection / Additional xfer to P&W additional Services - (Amend. #8) Additional Staff xfer to P&W additional Services - (Amend. #9) COVID Air Quality Sequence of Operations Rev xfer to P&W additional Services - (Amend. #10) Sidewalk connecting to Bike Path xfer to P&W additional Services - (Amend. #11) Traffic Signal Power, Striping, Drainage, Fiber xfer to P&W additional Services - (Amend. #12) Traffic Signal Coordination, Property Line xfer to P&W additional Services - (Amend. #13) WOHF Study xfer to P&W additional Services - (Amend. #14) Raise Grades Playing Fields & BSC Added Services xfer to CHA additional Geotech Services, Pond Irrig (Amend. #12) - VOID \$43,818 10/10/22, NOT RQD

Remaining Owners Contingency Balance

\$786,317

Committed:

\$1,213,683

\$2,000,000

B. Approved Construction Contingency

Original Amount, Pre GMP \$14,200,000

PRE GMP PCCO's

04/13/19	xfer Swing Space Budget to Construction Contingency	-\$1,000,000
04/13/19	xfer to Construction Budget (at 60% CD's)	\$1,000,000
08/14/19	xfer to Skanska Amendment # 9 - PCCO #1	-\$114,281
09/10/19	xfer to Skanska Amendment # 11 - T.S Removal	-\$144,887
01/13/20	xfer to Skanska Amendment # 14 - T.S Removal	-\$162,581
06/17/20	xter to Skanska Amendment #18 - Establish GMP	-\$1,721,335

Construction Contingency Balance at GMP \$12,056,916

POST GMP PCCO's

	FOST GIVIF FCCO'S	
07/20/20	PCCO #4	\$362,945
08/05/20	PCCO #5	-\$259,500
09/02/20	PCCO #6	-\$164,120
10/09/20	PCCO #7	\$0
10/09/20	PCCO #8	-\$881,684
11/17/20	PCCO #9	-\$737,748
12/16/20	PCCO #10	-\$201,003
01/18/21	PCCO #11	-\$730,506
01/18/21	PCCO #12	-\$125,000





2. CONTINGENCY EXPENDITURE LOG

Through December 31, 2022

/11/21 PCCO #13	-\$768,306
/11/21 PCCO #14	-\$941,369
/11/21 PCCO #15	-\$1,325,236
/17/21 PCCO #16	-\$117,796
/17/21 PCCO #17	-\$140,000
/17/21 PCCO #18	-\$428,563
/10/21 PCCO #19	-\$930,362
/09/21 PCCO #20	-\$667,202
/09/21 PCCO #21	\$0
/09/21 PCCO #22	-\$1,266,280
/09/21 PCCO #23	-\$652,878
/21/21 PCCO # 24	\$0
/25/21 PCCO # 25	-\$600,407
/13/21 PCCO # 26	\$0
/10/21 PCCO # 27	-\$225,000
/10/21 PCCO # 28	-\$141,688
/10/21 PCCO # 29	-\$1,350,426
/14/22 PCCO # 30	-\$54,674
/16/22 PCCO # 31	-\$183,553
/09/22 PCCO # 32	-\$412,878
/13/22 PCCO # 33	-\$1,168,218
/13/22 PCCO # 34	-\$49,068
/13/22 PCCO # 35	-\$207,870
/13/22 PCCO # 36	-\$1,083,823
/14/22 PCCO # 37	-\$223,785
/14/22 PCCO # 38	\$2,377,280
/18/22 PCCO # 39	-\$504,230
/10/22 PCCO # 40	-\$454,417
/03/22 PCCO # 41	-\$255,883
/31/22 PCCO # 42	-\$250,021
/17/22 PCCO # 43	-\$375,291
/05/22 PCCO # 44	-\$166,093

Owner's Construction Contingency Balance (\$3,247,737)

Committed thru PCCO # 44: \$15,304,653





3. PCCO's, PCO's and Other Cost Exposures

Through December 31, 2022

Pre-GMP			
Approved Pr	ime Contract Change Orders (PCCO)		
08/14/19	PCCO #1 - See Amendment #9 (Incl'd in GN	1P)	-
09/10/19	PCCO #2 - See Amendment #11 (Incl'd in G		-
01/13/20	PCCO #3 - See Amendment #14 (Incl'd in G		-
06/08/20	Approved GMP Agreement (Amendment #		\$240,341,185
Post-GMP	in Control Character (DCCO)		
	rime Contract Change Orders (PCCO)		\$262.045
07/08/20	PCCO #4		-\$362,945
08/05/20	PCCO #5		\$259,500
09/02/20	PCCO #6		\$164,120 \$0
10/09/20	PCCO #7		\$881,684
10/09/20	PCCO #8 PCCO #9		\$737,748
11/17/20	PCCO #9 PCCO #10		\$201,003
12/16/20	PCCO #10 PCCO #11		\$730,506
01/14/21 01/14/21	PCCO #11 PCCO #12		\$125,000
01/14/21 02/11/21			\$768,306
02/11/21	PCCO #13 PCCO #14		\$941,369
03/11/21	PCCO #14 PCCO #15		\$1,325,236
04/14/21	PCCO #15		\$1,323,230
05/17/21	PCCO #16 PCCO #17		\$140,000
05/17/21	PCCO #17 PCCO #18		\$428,563
05/17/21	PCCO #18		\$930,362
07/09/21	PCCO #19		\$667,202
07/09/21	PCCO #20		\$007,202
08/10/21	PCCO #21		\$1,266,280
09/09/21	PCCO #22 PCCO #23		\$652,878
10/09/21	PCCO #24		\$032,878
10/09/21	PCCO #25		\$600,407
10/03/21	PCCO #25		\$0
11/11/21	PCCO #27		\$225,000
11/11/21	PCCO #28		\$141,688
12/10/21	PCCO #29		\$1,350,426
01/16/22	PCCO #30		\$54,674
02/16/22	PCCO #31		\$183,553
03/09/22	PCCO #32		\$412,878
04/13/22	PCCO #33		\$1,168,218
05/13/22	PCCO # 34		\$49,068
05/13/22	PCCO # 35		\$207,870
06/13/22	PCCO # 36		\$1,083,823
07/14/22	PCCO # 37		\$223,785
07/14/22	PCCO # 38		-\$2,377,280
08/18/22	PCCO # 39		\$504,230
09/12/22	PCCO # 40		\$454,417
10/03/22	PCCO # 41		\$255,883
10/33/22	PCCO # 42		\$250,021
10/03/22	PCCO # 43		\$375,291
12/05/22	PCCO # 44		\$166,093
,,			\$247,204
	Sub Total - Post G	MP Approved, Prime Contract Change Orders (PCCO's #4 through #44)	\$15,551,857
		., , , , , , , , , , , , , , , , , , ,	

3. PCCO's, PCO's and Other Cost Exposures

Through December 31, 2022



Additional Anticipated & Potential Costs to the GMP	For 12/31/22
Pending PCCO # 45 for Building Committee Approval	\$247,204
Total of PCO's Submitted & Currently under review (See SKA Cost Exposure Log, 1/1/23)	\$385,439
Total of Outstanding Cost Events (See SKA Cost Exposure Log, 1/1/23)	\$129,413
Total of Pending Revisions (See SKA Cost Exposure Log, 1/1/23)	\$ (28,684)
Total of Potential Exposure Costs (See SKA Cost Exposure Log, 1/1/23)	\$193,237
Subtotal of Further Added Cost Exposure	\$926,609
GMP Projection (Combind Total of Current GMP Value, Pending PCCO, PCO's Submitted, & Anticipated Estimated Costs)	\$256,819,651





4. Allowance and Contingency Summary Through December 31, 2022

	Original Value	Current Value	Projected Value
Total Project Budget	\$295,542,274	\$295,542,274	\$295,542,274

Skanska GMP (Projected with ALL Potential Costs)	\$240,341,185	\$255,893,042	\$256,819,651

Alternate Funding Sources

		<u> </u>	
Covid Reimburse (Cares Act)	\$331,473	7	\$331,473
Covid Reimburse (ARPA - per Select Board Mtng 2/14/22)		\sum	\$1,000,000
Subtotal of Alternative Funding Sources	\$331,473	-	\$1,331,473

Project Reimbursement

Builder's Risk Insurance Claim - Skanska incurred cost

\$407,200

Revised Projected GMP after Alternate Funding and Insur Rebate

\$255,561,569

\$255,080,978

Allowances & Contingencies

Owner's Contingency	\$2,000,000	\$786,317	\$786,317
Owner's Construction Contingency	\$14,200,000	(\$3,247,737)	(\$4,174,346)
Owner's Allowances	\$4,613,467	\$498,991	\$0
Skanska's CM Contingency	\$4,038,818	\$158,458	\$0
Soft Cost Contingency	\$590,000	\$2,302,327	\$2,302,327
Alternate Funding Sources		\$331,473	\$1,331,473

Soft Cost, Allowance & Contingency Totals	\$25,442,285	\$829,829	\$245,771
Allowance & Contingency %'s - Current Values vs GMP	10.6%	0.3%	0.1%
Allowance & Contingency %'s - Original Values vs GMP		3.3%	1.0%
	Project	Phase 1	Phase 2
Construction Complete	92%	100%	77%
Construction Remaining	8%	0%	23%

Assume 2/3 project Ph1, 1/3 project Ph 2

Const %'s

Total Billed thru 12/31/22 235,689,393 Adjusted Contract Amount at 12/31/22 \$ 255,645,836 Total Project % complete 92.2% Phase 1 Const Total (100% Invoiced) \$ 170,515,773 Phase 2 Const Cost \$ 85,130,063 Phase 2 % Complete 76.6%

Total Project Conti	ngency History	
To 2/28/22	\$441,244	
To 3/31/22	\$501,727	
To 4/30/22	\$521,291	
To 5/31/22	\$501,238	
To 6/30/22	\$528,892	
To 7/31/22	\$428,100	
To 8/31/22	\$495,147	
To 9/30/22	\$476,909	
To 10/31/22	\$455,979	
To 11/17/22, PV Adjustment	\$312,855	
To 11/30/22	\$300,266	
To 12/31/22	\$245.771	

APPLICATION	AND CF	RTIFICATE	FOR P	AYMENT

Page 1 of 814

To(Owner):	Town of Belmont	Via(Architect):	Perkin	s & Will, Inc.	Application No:	48	Distribution	on to:	-
From/Contractor):	455 Concord Ave	Desired New		anklin St, Boston, MA 02110	Period:	12/31/2022		Owner	
From(Contractor):	Skanska USA Building Inc.	Project No:	13180		Architect's Project No:	1318017-000		Architect	
	101 Seaport Boulevard Suite 200	Project Name:	Belmo	nt Middle and High School	Contract Date:	7/7/2018		Contractor	
				The undersigned Contractor partific	Contract For:	Owner Contract	wine and ballacute	Wednesday	-):
Application is made for	'S APPLICATION FOR PAYMEN Payment, as shown below, in connection with the Sheet, AIA Document G703, is attached.			The undersigned Contractor certific Application for Payment has been of Contractor for Work for which prev payment shown herein is now due.	completed in accordance with the vious Certificates for Payment was	he Contract Documents, t	hat all amounts have	been paid by the	
ORIGINAL CONTRA	ACT SUM	\$	240,341,183	CONTRACTOR: Skanska USA	Building Inc.			. /: /= -	
Net change by Chan	ge Orders	\$	15,304,653	By: Mile Mile	ruse		Date:	1/6/23	
CONTRACT SUM T	O DATE	\$	255,645,836	State of: Massachuisetts	County of: Suffolk				
				Subscribed and sworn to, before	e me, this 💪 day of 🗧	January 2	1023		
TOTAL COMPLETE	D & STORED TO DATE	\$	235,689,393	1.00	n Jutran				SUSAN T. LAFRAZIA Notary Public COMMONWEALTH OF MASSACHUSETIS My Commission 15
Previous Retainage.	\$	5,670,145			1.0				My Commission Expires On January 20, 2028
				My Commission expires: 1/2020					
Current Retainage	\$	130,819		ARCHITECT'S CERTIFIC	CATE FOR PAYMENT				
	E TO DATE	\$	5,800,964 229,888,429	In accordance with the Contract Do certifies to the Owner that to the be quality of the work is in accordance	est of the Architect's knowledge	, information, and belief,	the Work has progre	essed as indicated, the	
LESS PREVIOUS C	ERTIFICATES FOR PAYMENT	\$	226,709,821	AMOUNT CERTIFIED			\$		
CURRENT PAYMEN	NT DUE	\$	3,178,608	(Attach explanations if amount differ changed to conform to the amount o		nitial all figures on this app	lication and on the C	ontinuation Sheet that are	
BALANCE TO FINIS	SH	\$	25,757,407						
BALANCE TO FINIS	SH, including retainage	\$	19,956,443	ARCHITECT: Perkins & Will, Inc	c.				
CHANGE ORDER S	SUMMARY		1						
				Ву:			Date:		
Total changes approprevious months:		ditions 0.00	Deductions 0.00	4000045 WILL 10 90000 000					
Change Orders appr	roved this month	0.00	0.00	This certificate is not negotiable. To f payment are without prejudice to				e, payment, and acceptance	ž.
Previous & Current (Change Orders:	0.00	0.00						
		-100	0,50	Wa	ming:				
Net Change by Char	nge Orders:	0.00		85 50	n effort to protect our clients from uctions, all requests to modify pa uspicious. Prior to re-directing you prilled with Zingy Cartagens at Zi	fraudulent attempts to cha yment instructions to Skan ur payments, the legitimacy	nge payment ska should be viewed of the request should from or (973) 752 250	d	

AIA Document G703, APPLICATION AND CERTIFICATE FOR PAYMENT, containing Contractor's signed Certification is attached.

PROJECT NO:

1318017

PROJECT NAME: Belmont Middle and High School APPLICATION NUMBER: 48

PERIOD FROM: 12/01/2022 PERIOD TO: 12/31/2022

A			В	С	D	F	G	н	I (NOT IN G OR H)	J=G+H+I	K=J/F	L=F-J	м	N	O=J-M
				ORIGINAL	BUDGET	SCHEDULED	'								
ITEM NO	MSBA	CE	DESCRIPTION OF WORK	CONTRACT	TRANSFER	VALUE	FROM PREVIOUS	OMPLETED THIS	MATERIALS PRESENTLY STORED	TOTAL COMPLETE	%	BALANCE TO	RETAINAGE TO DATE	RETAINAGE THIS PERIOD	NET AMOUNT BILLED TO
			PRECONSTRUCTION SERVICES TOTAL	550,494	0	550,494	APPLICATION 550,494	PERIOD 0	0	TO DATE	COMP 100%	FINISH			DATE 0 550,49
			PRECONSTRUCTION SERVICES TOTAL	,	-	,						-			1
0502-0010			GMP - FEE	4,579,936	130,565	4,710,501	4,185,239	58,041	0	4,243,280	90%	467,222	0	(0 4,243,28
0502-0020			BONDS AND INSURANCE TOTAL	9,355,309	12,113	9,367,422	8,626,029	0	0	8,626,029	92%	741,393	0	(0 8,626,02
0502-0030			GMP - CONTINGENCY	4,038,818	(114,062)	3,924,756	2,720,775	0	0	2,720,775	69%	1,203,981	65,529	(0 2,655,24
0502-0100			DIVISION 1 - GENERAL CONDITIONS TOTAL	24,919,575	425,553	25,345,128	21,577,065	472,843	0	22,049,908	87%	3,295,220	531,705	11,681	1 21,518,20
0502-0200			DIVISION 2 - EXISTING CONDITIONS TOTAL	7,670,994	(189,754)	7,481,240	7,318,736	11,748	0	7,330,484	98%	150,757	171,807	614	4 7,158,67
0502-0300			DIVISION 3 - CONCRETE TOTAL	14,331,076	(131,085)	14,199,991	13,183,880	27,390			93%	988,722		1,369	1
0502-0400			DIVISION 4 - MASONRY TOTAL	5,012,513	252,086	5,264,599	5,227,345	37,254		5,264,599	100%	1	152,504	1,412	2 5,112,09
0502-0500			DIVISION 5 - METALS TOTAL	16,422,211	78,782	16,500,993	15,892,092	8,275		15,900,367	96%	600,626		414	
0502-0600			DIVISION 6 - WOOD & PLASTICS TOTAL	4,264,874	194,792	4,459,666	3,726,113	71,750	0	3,797,863	85%	661,803	93,480	1,423	
0502-0700			DIVISION 7 - THERMAL & MOISTURE PROTECTION TOTAL	8,017,239	(147,061)	7,870,178	7,841,534	20,390	0		100%	8,254		717	
0502-0800			DIVISION 8 - DOORS & WINDOWS TOTAL	15,025,245	(35,483)	14,989,762	13,660,728	376,696		7	94%	952,338	414,773	17,364	
0502-0900			DIVISION 9 - FINISHES TOTAL	27,476,606	123,849	27,600,455	25,221,358	625,192	0	25,846,550	94%	1,753,905	811,723	27,820	
0502-1000			DIVISION 10 - SPECIALTIES TOTAL	2,537,381	(269,237)	2,268,144	1,474,934	152,676	0	1,627,610	72%	640,535	62,918	1,244	1
0502-1100			DIVISION 11 - EQUIPMENT TOTAL	2,671,774	(236,606)	2,435,168	2,066,836	2,705			85%	365,627	64,447	135	1 1
0502-1200			DIVISION 12 - FURNISHINGS TOTAL	4,492,931	216,764	4,709,695	3,066,251	616,550	0	3,682,801	78%	1,026,894	109,057	30,453	1
0502-1300			DIVISION 13 - SPECIAL CONSTRUCTION	861,500	(54,405)	807,095	794,631	0	0	794,631	98%	12,464	0	(0 794,63
0502-1400			DIVISION 14 - ELEVATORS TOTAL	596,675	(5,169)	591,506	561,851	0	0	,	95%	29,655		(0 559,23
0502-2100			DIVISION 21 - FIRE PROTECTION TOTAL	2,140,625	9,288	2,149,913	2,043,209	17,175	0	2,060,384	96%	89,529		859	
0502-2200			DIVISION 22 - PLUMBING TOTAL	6,501,028	85,542	6,586,570	6,168,398	66,855	0	6,235,253	95%	351,317	191,049	3,343	
0502-2300			DIVISION 23 - HVAC TOTAL	28,607,633	(100,607)	28,507,026	27,801,332	99,866	0	27,901,198	98%	605,828	634,614	4,593	3 27,266,58
0502-2500			DIVISION 25 - INTEGRATED AUTOMATION TOTAL	0	0	0	0	0	0	0	0%	0	0	(3
0502-2600			DIVISION 26 - ELECTRICAL TOTAL	21,151,795	(53,165)	21,098,630	18,361,036	258,117	0	18,619,153	88%	2,479,477	514,672	11,575	5 18,104,48
0502-2700			DIVISION 27 - COMMUNICATIONS TOTAL		0	0			0	0	0%	0	0	(2 (
0502-2800			DIVISION 28 - ELEC. SAFETY & SECURITY TOTAL		0	0			0	0	0%	0	0	() (
0502-3100			DIVISION 31 - EARTHWORK TOTAL	21,032,343	(168,407)	20,863,936	18,968,750	66,900	0	19,035,649	91%	1,828,287	435,525	3,345	1
0502-3200			DIVISION 32 - EXTERIOR IMPROVEMENTS	8,072,608	(20,000)	8,052,608	3,158,898	44,100	0	3,202,998	40%	4,849,610	160,150	2,205	5 3,042,848
0502-3300	_		DIVISION 33 - UTILITIES	10,000	(5,207)	4,793	0	0	0	0	0%	4,793	0) (
			BASE TOTAL	239,790,689	(914)	239,789,775	213,647,017	3,034,522	0	216,681,540	90%	23,108,235	5,318,267	120,566	6 211,363,273
		+	Owner Change Orders	15,304,653	0	15,304,653	18,182,455	274,904	0	18,457,359	121%	(3,152,706)	482,698	10,253	3 17,974,66
			GRAND TOTAL	255,645,836	(914)	255,644,922	2 232,379,966	3,309,427	0	235,689,393	92%	19,955,529	5,800,965	130,819	9 229,888,428
															1
0004-0000 - Sch	ematic De	sign Preco	onstruction Services												
PRE.00000000.5010			Schematic Design Preconstruction Services	103,912	0	103,912	103,912	0	0	103,912	100%	0	0	(0 103,912
0004-0000: Sche	ematic Des	ign Preco	nstruction Services	103,912	0	103,912	103,912	0	0	103,912	100%	0	0	(0 103,912
0501-0000 - Pred	constructio	n Service:	S												
PRE.00000001.5010		1	Preconstruction Services	446,582	0	446,582	446,582	0	0	446,582	100%	0	0		0 446,582
0501-0000: Prec		Comileon		446,582	0	446,582		0	0	446,582	100%	0			0 446,58
		Services		410,002	, and the second	110,002	110,002			410,002	100%				110,00
0502-0010 - Fee 900.26500000.4400	•	_	F	4,579,936	130,565	4,710,501	4,185,239	58,041		4,243,280	90%	467,222			0 4,243,280
			Fee		·				0					,	
0502-0010: Fee				4,579,936	130,565	4,579,936	4,185,239	58,041	0	4,243,280	93%	467,222	0		0 4,243,28
0502-0020 - Insu	urance														
110.01912000.5040			SDI	1,720,378	2,499	1,722,877	1,722,877	0	0	1,722,877	100%	0	0	(0 1,722,87
110.01911000.5040			Skanska Bond	1,732,632	0	1,732,632	1,732,632	0	0	1,732,632	100%	0	0	(0 1,732,63
110.01922500.5040	MSBA	CE	CCIP	5,902,299	9,614	5,911,913		0	0	5,170,520	87%	741,393	0		0 5,170,52
0502-0020: Insur	rance			9,355,309	12,113	9,367,422	8,626,029	0	0	8,626,029	92%	741,393	0	(0 8,626,02
	D Continge	CV													
0502-0030 - GMF	Continge	,													
0502-0030 - GMF 800.23900200.5040	Continge	ĺ	GMP Contingency	4,038,818	(1,757,986)	2,280,832	2 0	0	0	0	0%	2,280,832	Page 8	of 12	0

Color Code VOID Moved sections or added from previous week
Consent letter status Approved or Not Applicable Consent letter pending

Consent letter rejected

Approved

\$435,784

SUBMITTED COST EVENTS - PCO's In and Under Review

			SUBMITTED COST EVENTS - PCO's In and Unde	r Review						Date of Origina Submitted 8		PCO/AE
CE Number	CE Reason	AR Number	Description	Status	Originally Budgeted Amount	Current Budgeted Amount	PCCO#	Amount from Previous BC Report (1/3/23)	Current Amount vs Last BC Report (1/3/23)	Sent	Returned	Date PCO Sent
1752	Owner Directive	677	Temp PA System	Submitted	\$0	\$21,000	0	\$35,151	-\$14,151	-	-	5/13/2022
1196	Architect/Consultant Directive	713	Defer Phase I plantings to Phase II - Spring 2023	Submitted	\$0	\$6,116	0	\$6,116	\$0	NA	NA	7/11/2022
1536	Architect/Consultant Directive	760	Air Quality Improvements for Middle School Art Wing (PR 091)	Submitted	\$70,680	\$119,736	0	\$119,736	\$0	3/30/2022	4/13/2022	9/6/2022
1539	Architect/Consultant Directive	771R002	Upsize Exhaust for Dark Room and Kiln (PR 123)	Submitted	\$95,502	\$135,206	0	\$135,206	\$0	3/21/2022	3/28/2022	10/6/2022
1543	Architect/Consultant Directive	796	PR 127 MS MOBILE TRASH CABINETS REVISIONS	Submitted	-\$1,573	-\$2,034	0	-\$2,034	\$0	2/25/2022	3/2/2022	11/3/2022
1931	Architect/Consultant Directive	817	Power Outlets at Phase 2 Athletic Fields (PR 169)	Submitted	\$11,009	\$0	0	\$42,065	-\$42,065	10/26/2022	11/4/2022	11/29/2022
1797	Architect/Consultant Directive	826	Sloped Backup Filler at D4 South for Waterproofing	Submitted	\$991	\$1,804	0	\$1,804	\$0	NA	NA	12/20/2022
1927	Architect/Consultant Directive	827	Enclose Exposed Exterior Column With Sheathing at F-North	Submitted	\$440	\$841	0	\$841	\$0	NA	NA	12/20/2022
1970	Design Error and Omission	828	Low Flashing Conditions at Area D East Roof (RFI 1721)	Submitted	\$10,356	\$11,628	0	\$11,628	\$0	10/6/2022	11/4/2022	12/20/2022
1658.0002	Architect/Consultant Directive	829	Media Center Millwork, Glazing and Shelving Revisions (CCD 421 & RFI 1613)	Submitted	\$19,266	\$26,551	0	\$26,551	\$0	NA	NA	12/21/2022
2072	Architect/Consultant Directive	830	Temp Water Check Valves to Chlorinate Middle School	Submitted	\$0	\$3,762	0	\$3,762	\$0	NA	NA	12/21/2022
1997	Architect/Consultant Directive	831	Stair 5 Steel Protrusion at Interior Finishes	Submitted	\$3,974	\$6,395	0	\$6,395	\$0	NA	NA	12/21/2022
1789.1	Owner Directive	832	Installation of Sports Netting Above Field House Storage Room	Submitted	\$771	\$2,339	0	\$2,339	\$0	NA	NA	12/22/2022
1749	Architect/Consultant Directive	833	Rework Existing Water Line to Avoid Drain Line	Submitted	\$7,926	\$7,606	0	\$7,606	\$0	NA	NA	12/22/2022
1766	Architect/Consultant Directive	834	Power and Auto. Operator for Door XF100D.2 (CCD 435)	Submitted	\$8,807	\$10,167	0	\$10,167	\$0	7/11/2022	7/29/2022	12/22/2022
2044	Architect/Consultant Directive	835	Power for PH2 Elevator Sump (RFI 1834)	Submitted	\$435	\$594	0	\$594	\$0	NA	NA	12/22/2022
2000	Field Condition	836	Brick Return on D4 NW Corner of 19-C Line (RFI 1632.1)	Submitted	\$3,741	\$3,277	0	\$3,277	\$0	11/7/2022	11/14/2022	12/23/2022
2078	Field Condition	837	HS Corridor Full Height Bookshelves Modifications	Submitted	\$0	\$7,326	0	\$7,326	\$0	-	-	1/3/2023
1851	Architect/Consultant Directive	0	PR 165 Softball Scoreboard Specification	Outstanding	\$11,009	\$11,009	0	\$11,009	\$0	8/23/2022		1/7/2023
1948	Architect/Consultant Directive	840	RFI 1689 Power Feed for ACCU 26	Submitted	\$0	\$5 , 943	0	\$5,943	\$0	NA	NA	1/7/2023
1922	Owner Directive	841	Added Horn Strobe and Exit Signs per BFD TCO walk August 2022	Submitted	\$6,091	\$6,314	0	\$6,069	\$245	NA	NA	1/7/2023
1767	Architect/Consultant Directive	842	CCD 441 Removal of Exit Sign in MS Media Center per RFI 1628	Submitted	-\$544	-\$141	0	-\$140	-\$1	6/2/2022	6/2/2022	1/7/2023
2070	Architect/Consultant Directive	843	Mobile Storage Shelving Revisions to Access HVAC-2 in E201 (RFI 1804)	Submitted	\$4,404	\$0	0	\$4,129	-\$4,129			1/9/2023
			TOTAL SUBMITTED COST EVENTS			\$385,439	-	\$445,540	-\$60,101		1	
						\$50,345	;	. 5,555	/			

			OUTSTANDING COST EVENTS					<u>, </u>		Date of Origina Submitted	al OME Amount & Returned	
CE Number	CE Reason	AR Number	Description	Status	Originally Budgeted Amount	Current Budgeted Amount	PCCO#	Amount from Previous BC Report (1/3/23)	Current Amount vs Last BC Report (1/3/23))	Sent	Returned	Date Change is Issued
390.0002	Architect/Consultant Directive	0	CCD 104 - CW Support Angles Priming Instead of Galvanizing	Outstanding	-\$1,049		0	-\$1,04	9 \$0		NA	3/11/2022
642	Architect/Consultant Directive	0	CCD 218 DECORATIVE STEEL PLATE EXP JOINTS	Outstanding	\$15,206		C	\$10,000		10/28/2020		10/15/2020
973	Architect/Consultant Directive	0	Misc. Metals Overhead Door Support Credits	Outstanding	\$0		C	-\$13,61			NA	3/25/2021
1158.0001	Architect/Consultant Directive	0	CCD 324 ART ROOMS SLIDING DOOR FLOOR TRACK REVISION - Millwork Cost Only	Outstanding	\$15,157		C	\$8,29		NA NA	NA	6/1/2021
1206	Architect/Consultant Directive	0	CCD 336 COORDINATION OF EXISTING CATCH BASIN IN NEW DRIVEWAY CUT AT CONCORD &	Outstanding	\$2,751		C	\$2,75	1 \$0	7/31/2021	8/20/2021	7/15/2021
1212.0001	Architect/Consultant Directive	0	CCD 347 CONCORD AVE INTERIM MARKINGS & SIGNAGE - POLICE DETAIL	Outstanding	\$27,674		C	\$27,67			NA	4/29/2022
1366	Architect/Consultant Directive	0	PR 103 Amended MS Exterior Signage & Uplighting Detail	Outstanding	\$11,559	\$11,559	C	\$11,55	9 \$0	10/6/2022	10/6/2022	9/22/2021
1374.0002	Architect/Consultant Directive	0	CCD 409 Amended Phase 2 Grading Revisions - Additional Trench Material	Outstanding	\$11,009		C	\$11,00	-	NA NA	NA	_
1382	Architect/Consultant Directive	0	CCD 371 AMENDED PHASE 2 WINDOW CHANNEL SUPPORT REVISIONS	Outstanding	-\$2,500		C	\$1	0 \$0	10/27/2021	11/2/2021	10/18/2021
1396.0001	Architect/Consultant Directive	0	CCD 372 ILLUMINATED EXIT SIGNAGE AT POOL LOCKER RM. SUITE AND BLACK BOX CATWAI	FOutstanding	\$2,718		C	\$2,71	8 \$0	NA NA	NA	4/11/2022
1403.0002	Field Condition	0	Team Locker Rooms Slab Prep for Floor Install	Outstanding	\$10,000		C	\$10,000		NA NA	NA	11/8/2021
1414.0001	Architect/Consultant Directive	0	CCD 362 POOL EMERGENCY LIGHTING & TEMP STAIR PULL STATIONS - Dandis T&M	Outstanding	\$2,175		C	\$2,17		11/29/2021	12/6/2021	11/15/2021
1420.0001	Architect/Consultant Directive	0	CCD 385 AUDITORIUM ILLUMINATED EXIT SIGN ADDITIONS - T&M Cost	Outstanding	\$7,705		C	\$7,70		11/29/2021	12/13/2021	11/17/2021
1424.0001	Owner Directive	0	Painting Aluminum Rail Caps in Lieu of Anodizing - Phase 2	Outstanding	\$2,000		C	\$2,000			NA	6/15/2022
1437	Owner Directive	0	Covid Recovery Tax Reconciliation	Outstanding	\$0	-\$1,096	C	-\$1,09	6 \$0) NA	NA	11/29/2021
1455	Architect/Consultant Directive	0	PR 117 EXISTING CMU WING WALL AT LOCKER E108B PER RFI 1481	Outstanding	\$3,632		C	\$1	0 \$0	12/23/2021	12/27/2021	12/13/2021
1460.0001	Architect/Consultant Directive	0	PR 118 REMOVAL OF COIN OPERATION FOR SANITARY NAPKIN DISPENSERS	Outstanding	\$5,437	\$5,437	C	\$5,43	7 \$0	NA NA	NA	12/16/2021
1473.0001	Architect/Consultant Directive	0	PR 116 Amended Vehicular Protection for Generator	Outstanding	\$5,505		C	\$16,610		3/1/2022	3/2/2022	1/28/2022
1480	Architect/Consultant Directive	0	CCD 380 MISC ARCH COORD WITH MEPFP	Outstanding	\$34,126	\$28,083	C	\$28,08	3 \$0	1/4/2022	1/5/2022	12/22/2021
1482	Architect/Consultant Directive	0	PR 121 Locker, FP & Light Fixture Shift at Existing 4" CMU Bumpout per RFI 150	Outstanding	\$3,855	\$1,355	C	\$1,35	5 \$0	1/18/2022	1/20/2022	1/5/2022
1535.0001	Allowance Adjustment	0	ASI 217 and ASI 240 BUILDING GRAPHICS ARTWORK - T&M Electrical	Outstanding	\$1,000		C	\$1		3/8/2022	3/14/2022	6/21/2022
1536.0001	Architect/Consultant Directive	0	Above Ceiling Rework for PR 091	Outstanding	\$11,559	\$0	C	\$11,55	9 -\$11,559	NA NA	NA	3/29/2022
1539.0001	Architect/Consultant Directive	0	PR 123 Darkroom Revisions - Painting and Unforeseen Electrical Cost	Outstanding	\$4,349		C	\$3,34	9 \$0	12/14/2022	1/4/2023	9/7/2022
1575	Architect/Consultant Directive	0	ASI 232 Area D L2 Floor Box Locations	Approved	\$0	\$0	С	\$1	0 \$0	NA NA	NA	1/25/2022
1582	Architect/Consultant Directive	0	CCD 402 Elimination of Fire Protection at Circ. SE1	Outstanding	-\$1,088	-\$1,088	C	-\$1,08	8 \$0	1/28/2022	2/2/2022	1/26/2022
1589.0001	Field Condition	0	RFI 1525 Remove Existing Plumbing Lines in Field House - FP T&M	Outstanding	\$4,349	\$949	C	\$94	9 \$0	NA NA	NA	7/11/2022
1593	Architect/Consultant Directive	0	CCD 405 Composite Roof Slab Clarification per RFI 1542	Outstanding	-\$5,245	-\$5,245	C	-\$5,24	5 \$0	2/4/2022	3/1/2022	2/2/2022
1601	Architect/Consultant Directive	0	ASI 233 Additional Radiant Topping Slab Dimensions	Outstanding	\$0	\$0	C	\$I	0 \$0	2/8/2022	Declined	2/7/2022
1608	Architect/Consultant Directive	0	CCD 412 Rated Partition & Fire Damper Revisions per RF1 1548	Outstanding	\$1,707	\$5,033	C	\$5,033	3 \$0	3/1/2022	3/7/2022	2/15/2022
1628	Architect/Consultant Directive	0	CCD 415 Elimination of Phase 2 Heat Rejection	Outstanding	-\$105,210	-\$100,210	C	-\$100,210	0 \$0) NA	NA	3/9/2022
1629.0001	Architect/Consultant Directive	0	CCD 416 Elimination of West of Harris Field work - Removal of Demolition Scope	Outstanding	-\$102,052	-\$102,052	C	-\$102,05	2 \$0	NA NA	NA	6/8/2022
1635.0005	Allowance Adjustment	0	Splice Enabling Scope - November 2022	Outstanding	\$4,020	\$11,547	C	\$11,54	7 \$0) NA	NA	10/26/2022
1637	Allowance Adjustment	0	Temp Stair Removal	Outstanding	\$0	\$0	C	şı	0 \$0	NA NA	NA	3/7/2022
1641	Architect/Consultant Directive	0	SKA Labor Required for Christmas 2021 and April 2022 Break Change Work	Outstanding	\$8,600	\$8,600	C	\$8,600	0 \$0) NA	NA	3/7/2022
1962.0001	Architect/Consultant Directive	0	Door Hardware Revisions at Locker Rooms (CCD 465) - Painting Cost	Outstanding	\$544	\$544	C	\$54	4 \$0	NA NA	NA	12/15/2022
1663.0004	Overtime	0	Summer 2022 Premium Time - Phasing November 2022	To be Submit	t \$2,400	\$2,191	C	\$2,19	1 \$0	NA NA	NA	10/26/2022
1667.0001	Architect/Consultant Directive	0	Wall Parging for Graphic Installation at F100B Corridor	Outstanding	\$15,000	\$0	C	\$15,000	-\$15,000	NA NA	NA	11/4/2022
1669	Contract/Cost Reconciliation	0	Transite Abatement Reconciliation - Select Demo	Outstanding	-\$53,250	-\$53,250	C	-\$53,250	0 \$0	NA NA	NA	3/28/2022
1678	Architect/Consultant Directive	0	PR 141 Increase Visibility of Exterior Lockdown Strobes	Outstanding	\$2,175	\$2,175	C	\$2,17	5 \$0	5/2/2022	5/3/2022	4/27/2022
1680	Architect/Consultant Directive	0	PR 146 Cove Fixture Lengths at Expansion Joints	Outstanding	\$10,109	\$10,109	C	\$10,10	9 \$0	4/25/2022	5/3/2022	4/13/2022
1680.0001	Architect/Consultant Directive	0	PR 146 Cove Fixture Lengths at Expansion Joints - T&M	Outstanding	\$1,100	\$600	C	\$600	0 \$0	NA NA	NA	6/17/2022

Page 9 of 12 Pretty Copy of SKA Exposure Log Amended Ver 2 from 1-11-23 Mtng

1.601 0001	Darbitant (Grandlant Dinetin	[0] [DD 147 WING W./sharras Gabasila (WDD Gash)	0	24 000	64 000	04 000	•	2 22		6 (17 (2022
1681.0001	Architect/Consultant Directive Field Condition	0 PR 147 HVAC Maintenance Catwalk (MEP Cost) 0 Slotted Channel Framing Credit - Phase 1 (VOID-SEE 2063)	Outstanding Void	\$4,000	\$4,000	0 \$4,000	\$0	0 NA 0 NA	NA NA	6/17/2022 4/7/2022
1701	Architect/Consultant Directive	0 Bearing Plate for CFMF Credit	Outstanding	-\$504	\$0	0 \$0			NA NA	4/13/2022
1703	Architect/Consultant Directive	0 PR 148 EXTERIOR BOTTLE FILLER & METER - PHASE 1	Outstanding	\$31,834	\$31,834	0 \$31,834	\$0			5/25/2022
1710.0001	Architect/Consultant Directive	0 CCD 433 Additional PV Shutoff Switches - non-electrical trades	Outstanding	\$11,357	\$11,357	0 \$11,357	\$0		NA	9/21/2022
1724	Architect/Consultant Directive	0 CCD 437 Amended Athletic Fields & Site Revisions	Outstanding	-\$383,705	-\$250,000	0 -\$235,519	-\$14,481	1 NA	NA	-
1730	Architect/Consultant Directive	0 RFI 1597 Exterior Scoreboard Coordination	Outstanding	\$10,000	\$10,000	0 \$10,000	\$0	0 NA	NA	5/3/2022
1738	Change Condition	O District Email Revision with Technology	Outstanding	\$8,155	\$8,155	0 \$8,155	\$0	0 NA	NA	5/4/2022
1743	Architect/Consultant Directive	0 RFI 1610 - Blank Off Covers in Field House	Outstanding	\$272	\$272	0 \$272	\$0	0 5/9/2022	5/24/2022	5/9/2022
1744	Architect/Consultant Directive	CCD 439 Removal of Fire Protection for Door XE100B.1 Vestibule	Outstanding	-\$500	\$0	0 \$0	\$0		5/24/2022	5/10/2022
1748	Architect/Consultant Directive	F256 Sliding Door (Millwork Cost)	Outstanding	\$11,009	\$10,570	0 \$10,570	\$0		NA	5/11/2022
1757	Architect/Consultant Directive	CCD 440 Temp. Security Camera for Temp. Locker Rm. Layout	Outstanding	\$1,087	\$1,087	0 \$1,087	\$0	0 7/11/2022	7/25/2022	7/6/2022
1764.0001	Architect/Consultant Directive	0 PR 155 Parapet Handrail and Tie-Offs for Ell1 Roof - Scaffolding Costs	Outstanding	\$8,256	\$8,256	0 \$8,256	\$0	0 6/28/2022	7/11/2022	6/14/2022
1778	Architect/Consultant Directive	0 CCD 445 Bollards at P2 Electrical Switch Gear	Outstanding	\$23,513	\$22,535	0 \$15,535	\$7,000		6/13/2022	6/2/2022
1779	Architect/Consultant Directive	0 ASI 242 Amended Louver Size Clarification per RFI 1651	Outstanding	\$2,802	\$2,802	0 \$2,802		0 6/28/2022	7/11/2022	6/2/2022
1780 1785	Architect/Consultant Directive Owner Directive	0 ASI 243 Mechanical Programming Clarification per Cx 0 RFI 1623 - Installation of Pool Controller	Outstanding Outstanding	\$0 \$2,202	\$0 \$2,202	0 \$0	\$0	0 6/6/2022	6/13/2022	6/2/2022 6/3/2022
1787	Field Condition	0 Vertical Steel Plate Area A Credit (VOID-SEE 2063)	Void	-\$1,500	\$0	\$0 -\$1,500	\$1,500		NA	6/3/2022
1791	Architect/Consultant Directive	0 ASI 244 Radiant Floor Zone Programming Clarifications per Cx	Outstanding	\$0	\$0	0 \$0			NA NA	6/15/2022
1795	Owner Directive	0 Salvage Lockers at White Field House	Outstanding	\$0	\$0	0 \$0			NA	6/13/2022
1798	Architect/Consultant Directive	O CCD 446 Area Drain Clarif. at BBall Courts per RFI 1666	Outstanding	-\$7,147	-\$7,147	0 -\$7,147	\$(0 6/28/2022	7/11/2022	6/23/2022
1801	Owner Directive	0 Vandalism Supervision/Repair	Outstanding	\$7,926	\$6,494	0 \$6,494	\$(0 NA	NA	6/24/2022
1813	Architect/Consultant Directive	0 RFI 1690 Clarifications for Mechanical Enclosure on Area F Roof	Outstanding	-\$2,500	-\$2,500	0 -\$2,500	\$0	0 NA	NA	6/30/2022
1823.0001	Architect/Consultant Directive	PR 163 Amended Relocate Barrel Washer to Exterior Rated Storage Room E112B	Outstanding	\$34,898	\$0	0 \$34,898	-\$34,898	3 11/29/2022	Declined	
1827	Architect/Consultant Directive	0 RFI 1697 Area D Skylight Sprinkler	Outstanding	\$7,707	\$7,707	0 \$7,707	\$0	7/11/2022	7/25/2022	7/8/2022
1831.0001	Architect/Consultant Directive	0 Rework of Finishes to Install Conduit for PV Elec. Panel - T&M	Outstanding	\$3,302	\$3,302	0 \$3,302		0 12/14/2022	Declined	7/18/2022
1833	Architect/Consultant Directive	0 CCD 451 Access Control Revisions at Field House & Loading Dock	Outstanding	\$7,707	\$19,203	0 \$19,203		0 8/23/2022	9/7/2022	8/16/2022
1835	Architect/Consultant Directive	0 RFI 1682 Ceiling Mounted Fire Strobe	Outstanding	\$816	\$816	0 \$816	\$0		7/25/2022	7/11/2022
1846	Architect/Consultant Directive	734 RFI 1650 Support for Bariatric Lifts in Rooms F176A and F176B	Outstanding	\$13,281	\$13,281	0 \$13,281		7/19/2022	7/57	8/15/2022
1847	Architect/Consultant Directive	0 RFI 1703 Media Center Shelving Depth	Outstanding	\$4,074	\$3,074	0 \$3,074	\$0		7/29/2022	7/18/2022
1852	Architect/Consultant Directive	0 CCD 455 Exterior Device Location Coordination	Outstanding	\$3,306	\$3,306	0 \$3,306	\$0		8/4/2022	7/18/2022
1853	Field Condition	0 Field House Fan Conflict with Divider Curtain (RFI 617)	Outstanding	\$1,651	\$2,236	0 \$2,236 0 \$7,612	\$0	7/28/2022 7/28/2022	8/4/2022	7/18/2022 7/19/2022
1854 1860	Field Condition Field Condition	0 RFI 1699 Stair 6 Railing and Wall Conflict 0 RFI 1705 Moving RAD-9 due to conflict with DC-3 Supports	Outstanding Outstanding	\$7,612 \$2,215	\$7,612 \$2,215	0 \$7,612	\$0		0/4/2022	7/19/2022
1868	Unforeseen Condition	0 Sleeving Across Porous Road	Outstanding	\$2,215	\$1,322	0 \$1,322	\$0		NA	7/21/2022
1869	Architect/Consultant Directive	0 CCD 456 F176A & F176B WC Chase per RFI 1712	Outstanding	\$3,303	\$3,303	0 \$3,303	\$1	0 7/28/2022	11/4/2022	7/22/2022
1873	Architect/Consultant Directive	0 Railing Brackets in Auditorium Credit	Outstanding	\$0	\$0	0 \$0	\$0	_	NA	7/27/2022
1877	Architect/Consultant Directive	0 CCD 457 Power for Shot Clocks	Outstanding	\$5,000	\$5,000	0 \$5,000	\$0		-	11/1/2022
1878	Architect/Consultant Directive	O GWB Soffit at B138 Soffit Credit	Outstanding	-\$500	-\$500	0 -\$500	\$0	0 NA	NA	8/2/2022
1879	Architect/Consultant Directive	O Sprinkler Misalignment at Main Entrance MCM Panels	Outstanding	-\$500	-\$500	0 -\$500	\$0	0 NA	NA	8/2/2022
1881	Architect/Consultant Directive	0 ASI 247 FH and Small Gym Floor Graphic in EPS Format	Outstanding	\$0	\$0	0 \$0	\$0	0 NA	NA	8/2/2022
1883	Field Condition	0 FW50 Added Plates for Gap	Void	\$1,000	\$0	0 \$0	\$0	<u> </u>	NA	8/2/2022
1891	Architect/Consultant Directive	0 RFI 1727 Overlength Data Cables	Outstanding	\$0	\$0	0 \$0			NA	8/11/2022
1898	Architect/Consultant Directive	PR 167 Sink Depth Rev. at Robotics & Art Rms. for Plaster Trap Maint.	Outstanding	\$14,231	\$14,231	0 \$14,231		0 10/25/2022	11/10/2022	11/16/2022
1902	Architect/Consultant Directive	0 ASI 249 MS Princ F181D WAP Relocation	Approved	\$0	\$0	0 \$0			NA	8/16/2022
1910	Owner Directive	O Paint plywood around receptacles at wall pad locations in FH and Small Gym	Outstanding	\$6,904	\$5,700	0 \$5,700	\$0	0 NA 0 9/22/2022	NA 0/26/2022	8/24/2022
1918 1920	Field Condition	0 RFI 1728 Brick Shelf at XX Line	Outstanding	\$3,853	\$3,853	0 \$3,853	\$0	0 NA	9/26/2022	8/26/2022
1925	Owner Directive Unforeseen Condition	0 Fire Alarm Commissioning 0 August 2022 TCO Items	Outstanding Outstanding	\$3,200 \$4,000	\$3,200 \$4,000	0 \$3,200	\$0		NA NA	8/26/2022 8/30/2022
1931.0001	Architect/Consultant Directive	0 Electrical Conduit at Bleacher Foundation per PR 169	Outstanding	\$4,734	\$4,734	0 \$0	\$4,734	<u>ļ</u>	107	1/4/2023
1933	Architect/Consultant Directive	0 CCD 458 Switch Gear Revisions for PV	Outstanding	\$54,369	\$54,369	0 \$54,369			11/4/2022	9/28/2022
1940	Architect/Consultant Directive	0 RFI 1694 Area D Arcade Low Point Drain for Dry System	Outstanding	\$2,000	\$2,000	0 \$2,000	\$0		NA	9/8/2022
1944	Architect/Consultant Directive	0 CCD 460 Municipal Supply Tie-in for Irrigation System	Outstanding	-\$92,794	-\$60,455	0 -\$60,455	\$0	0 11/7/2022	11/15/2022	
1962.0001	Architect/Consultant Directive	Door Hardware Revisions at Locker Rooms (CCD 465) - Painting Cost	Outstanding	\$544	\$544	0 \$544	\$(0 NA	NA	10/6/2022
1975	Architect/Consultant Directive	0 RFI 1754 Display case frame adjustment	Outstanding	\$10,183	\$17,458	0 \$9,720	\$7,738	B NA	NA	9/28/2022
1979	Architect/Consultant Directive	0 ASI-250 GRADING CLARIFICATION PER RFI-1759	Outstanding	\$0	\$0	0 \$0	\$0	0 NA	NA	10/3/2022
1980	Architect/Consultant Directive	0 ASI 251 Area F Exterior Light Fixture Locations per RFI 1782	Outstanding	\$0	\$0	0 \$0	\$0	0 NA	NA	10/27/2022
1981	Architect/Consultant Directive	0 Wall Switch Protection in FH & Small Gym	Outstanding	\$5,504	\$5,504	0 \$5,504		0 11/7/2022	Declined	
1989	Field Condition	RFI 1763 Coping Heights along Vx and 17x lines Area E	Outstanding	\$10,458	\$10,458	0 \$10,458		10/26/2022		10/12/2022
1993	Architect/Consultant Directive	0 PR 176 Phase 2 Team Collaboration Space Signage Clarifs	Outstanding	\$3,302	\$3,302	0 \$3,302	\$0			10/13/2022
2002	Field Condition	0 RFI 1762 Expansion Joint Detail at 11x Building E	Outstanding	\$5,505	\$5,505	0 \$5,505	\$0	11/7/2022	11/14/2022	10/18/2022
2004	Unforeseen Condition	0 Demo of Phase 1 Fan-35	Outstanding	\$1,100	\$1,100	0 \$1,100	\$0	•	11/14/2022	10/19/2022
2006	Architect/Consultant Directive	O RFI 1789 Soffit Extension in D384	Outstanding	\$4,302	\$4,302	0 \$4,302	\$0	0 11/7/2022	11/14/2022	10/19/2022
2011	Field Condition Architect/Consultant Directive	0 Rework of Stair 6 Egress Door on Level 2 and Railing Adjustments per Field F 0 RFI 1800 F363 & F364 Bracket Coordination	Outstanding Outstanding	\$8,477 \$1,101	\$8,203 \$1,101	0 \$8,203 0 \$1,101	\$0	0 11/7/2022 0 11/7/2022	11/14/2022 Declined	10/24/2022 10/26/2022
2013	Architect/Consultant Directive	0 RFI 1800 F363 & F364 Bracket Coordination 0 RFI 1607 Mechanical Well Roof Penetration	Outstanding	\$3,853	\$3,369	0 \$1,101	\$0		11/15/2022	10/27/2022
2021	Architect/Consultant Directive	0 RFI 1794 - Exposed SFRM in Media Center	Outstanding	\$2,104	\$2,786	0 \$2,786			11/14/2022	11/3/2022
2028	Architect/Consultant Directive	0 RFI 1813 C388B Eye Wash Conflict	Outstanding	\$1,321	\$0	0 \$0		0 11/29/2022	12/13/202	11/7/2022
2030	Architect/Consultant Directive	0 RFI 1790 Added Light Switch in D487A	Outstanding	\$551	\$529	0 \$529		0 11/29/2022	12/13/202	11/8/2022
2032	Field Condition	0 RFI 1803 Grab Bar Conflict With In-Wall	Outstanding	\$1,651	\$0	0 \$0			NA NA	11/9/2022
2034	Architect/Consultant Directive	0 RFI 1744 Tempered Water Pump Disconnect	Outstanding	\$2,202	\$2,202	0 \$2,202	\$(0 11/29/2022	Declined	11/9/2022
2035	Architect/Consultant Directive	0 RFI 1801 Break Metal Clarification for DC-5A/5B	Outstanding	\$1,101	\$1,101	0 \$1,101		11/29/2022	12/13/202	11/9/2022
2037	Architect/Consultant Directive	0 CCD 467 Glass Detection Film Revisions	Outstanding	\$1,303	\$1,303	0 \$1,321				12/13/2022
2039	Architect/Consultant Directive	0 RFI 1831 Curtainwall and Slab Connection at Media Center and Stairwell Ends	Outstanding	\$11,009	\$11,009	0 \$11,009	\$0			11/17/2022
2040	Field Condition	O Delegated Design of Footings for Batting Cages	Outstanding	\$21,411	\$25,899	0 \$17,411			NA	11/18/2022
2041	Owner Directive	0 Remove 'All Clear' Announcement from Lock Down Sequence	Outstanding	\$1,651	\$440	0 \$440			NA	11/21/2022
2042	Architect/Consultant Directive	O Corridor Wall Tile Prep Work Due to Steel Deflection	Outstanding	\$22,018	\$22,018	0 \$22,018				11/21/2022
2045	Architect/Consultant Directive	O Grading & Drainage Clarification per RFI 1808 (CCD 468)	Outstanding	\$28,622	\$28,622	0 \$28,622			110	12/21/2022
2046	Architect/Consultant Directive	0 Power Revisions for Cafe Commons and Video Production (CCD 469)	Outstanding	\$0	\$0	0 \$0			NA 12/21/2022	12/12/2022
2047	Architect/Consultant Directive	0 Added Power for Faucet Sensors @ F161C & F161D (CCD 470)	Outstanding	\$2,175	\$2,175	0 \$2,175			12/21/2022 NA	12/9/2022
2049	Architect/Consultant Directive	0 CHW Pump Sequence Change	Outstanding Outstanding	\$7,073	\$7,073 -\$5,555	0 \$7,073 0 -\$5,555	\$0 \$0		NA NA	11/28/2022 11/30/2022
2052	Contingency Field Condition	0 Comm-Tract Cost to Remobilize 0 RFI 1849 D300 Corridor Angled Soffit	Outstanding	\$880	-\$5,555 \$880	0 -\$5,555		0 12/14/2022	Declined	12/2/2022
2054	Architect/Consultant Directive	0 RFI 1848 Condensate Drain on FCU-9	Outstanding	\$9,358	\$9,358	0 \$9,358		0 12/20/2022	Desiried	12/6/2022
2057	Architect/Consultant Directive	0 RFI 1847 - D300 Cove Light	Outstanding	\$600	\$0	0 \$0		0 12/14/2022	Declined	12/6/2022
2058	Architect/Consultant Directive	0 RFI 1823 Additional Framing for Shade Box Blocking	Outstanding	\$7,105	\$7,105	0 \$6,605			12/20/2022	12/6/2022
2062	Architect/Consultant Directive	0 CCD 472 MS Ballistic Resistant Partition	Outstanding	\$3,853	\$3,853	0 \$3,853			12/20/2022	12/8/2022
		** *** * * * * * * * * * * * * * * * * *								
2063	Owner Directive	0 Monetized Punch List	Outstanding	-\$1,500	-\$15,106	0 -\$13,606	-\$1,500) NA	NA	12/12/2022
	Owner Directive Architect/Consultant Directive	0 Monetized Punch List 0 RFI 1627 Bottom of Shaft Rated Enclosure	Outstanding Outstanding	-\$1,500 \$8,156	-\$15,106 \$8,156	0 -\$13,606		0 12/14/2022		12/12/2022

Pretty Copy of SKA Exposure Log Amended Ver 2 from 1-11-23 Mtng

		1							1///0000	
2065	Architect/Consultant Directive	0	RFI 1825 Key Switch Locations for Fire Rated Doors	Outstanding	\$2,477	\$2,477	0 \$1,9			12/14/2022
2066	Architect/Consultant Directive	839	RFI 1851 Smoke Detector at Stair 6 level 3	Submitted	\$2,175	\$1,636	0 \$2,1			
2068	Architect/Consultant Directive	ļ	ASI 253 Prevailing Wage Rates Update	Outstanding	\$0	\$0		\$0 \$0		
2071	Architect/Consultant Directive	0	RFI 1850 Phase 2 Non-typical Classrooms MB Clarification	Outstanding	\$3,853	\$3,853	0 \$3,8	_	1/4/2023	12/19/2022
2075	Design Development	0	CCD 473 Curb Radius & Light Pole at Hittenger per RFI 1824	Outstanding	\$10,000	\$10,000	0 \$10,0)	12/23/2022
2079	Field Condition	0	RFI 1786 - Stair Structural Infills	Outstanding	\$7,707	\$7,707	0 \$7,4			12/27/2022
2080	Architect/Consultant Directive	0	Door Lite for Wood Doors - Phase 1 and 2	Outstanding	\$24,660	\$24,660	0 \$24,6			12/27/2022
2085	Architect/Consultant Directive	0	RFI 1865 Metal Trim at Stair 4 Coiling Doors	Outstanding	\$11,961	\$11,961	0 \$11,9	_		1/3/2023
2089	Architect/Consultant Directive	0	RFI 1854 Shades on Round Column at F270 & D385	Outstanding	\$1,981	\$1,981	0	\$0 \$1,98	1/4/2023	1/4/2023
2090	Architect/Consultant Directive	0	RFI 1861 - D100.4 Mullion Detail Conflict	Outstanding	\$3,303	\$3,303	0	\$0 \$3,300	3	1/4/2023
2091	Architect/Consultant Directive	0	RFI1626.1 - Light Fixture in Bathrooms F261A and F361A	Outstanding	\$2,752	\$2,752	0	\$0 \$2,752	2	1/4/2023
2092	Architect/Consultant Directive	0	RFI 1696 Location of Roadway Light Pole	Outstanding	\$3 , 853	\$3,853	0	\$0 \$3,850	3	1/4/2023
2093	Change Condition	0	Field House Stair Floor Paint Prep	Outstanding	\$2,750	\$2 , 750	0	\$0 \$2,750		1/5/2023
			TOTAL OUTSTANDING COST EVENTS			\$129,413	0 \$161,9	57 -\$32,54	1	
			PENDING REVISIONS				#REF!	#REF!		
									1	
								Current Amount		
								vs Last BC		
							Amount from Previou			
CE Number	CE Reason	AR Number	Description	Status Origi	nally Budgeted Amount	Current Budgeted Amount	PCCO# BC Report (1/3/23)	(1/3/23)		
1533	Design Development		ASI 033 POOL & FIELD HOUSE BANNER SYSTEM DETAILS	Outstanding	\$0	\$0	0	\$0 \$0	0	
1536.0003	Design Development		PR 091 AMENDED 2	Outstanding	\$0	\$0	0	\$0 \$0		
1546	Design Development		CCD 369 CONCORD & GODEN ROADWAY DRAINAGE - PERMANENT DESIGN	Outstanding	\$60,000	\$30,000	0 \$60,0	-\$30,000)	
1830	Architect/Consultant Directive	0	PR 162 Amended Additional Landscape & Site Revisions	Outstanding	\$10,000	\$10,000	0 \$10,0	00 \$0	11/29/2022 12/13/2	11/8/2022
1930	Design Development		PR 168 Power for MS Curtain Wall Shades	Outstanding	\$0	\$0	0	\$0 \$0		
1931.0002	Architect/Consultant Directive		PR 169 AMENDED Power Outlets at Phase 2 Athletic Fields	Outstanding	\$10,000	\$10,000	0	\$0 \$10,000)	
1932	Design Development		PR 170 Ceiling Revisions at MS Main Office Duct Conflict	Outstanding	\$0	\$0	0	\$0 \$0	D	
1934	Design Development		CCD 459 Handrail for Stair 10 - Audience Side	Outstanding	\$0	\$0	0	\$0 \$0		
1959	Design Development		PR 173 Security and Damage Protection for Field House A/V Rack	Outstanding	\$50,000	\$0	0 \$50,0	-\$50,000)	
1982	Design Development		PR 174 Campus Wayfinding Signage	Outstanding	\$0	\$10,000	0	\$0 \$10,000		
1984	Design Development		PR 175 Concord Ave Milling and Paving	Outstanding	-\$104,884	-\$93,684	0 -\$89,3			
2055	Design Development		CCD 471 Landscape Grading Revisions at Northeast Corner	Outstanding	\$0	-\$5,000	0	\$0 -\$5,000		
2084	Design Development		PR 178 Phase 2 Egress Stair Landing Stringer Infill at Window Condition	ons per RFOutstanding	\$0	\$10,000	0	\$0 \$10,000	D	
			PENDING REVISIONS TOTAL			-\$28,684	\$30,6	-\$59,302	2	
			POTENTIAL EXPOSURE				#REF!	#REF!		
		1					1	,,,,_,,	1	
								Current Amount	•	
								vs Last BC		
CE Number	CE Reason	AR Number	Description	Status Origi	nally Budgeted Amount	Current Budgeted Amount	Amount from Previou BC Report (1/3/23)			
1491	Forecast	AK Number	LIGHT FIXTURE DETAIL AT APC CEILINGS	Outstanding	so	so	O De Report (1/3/23)	\$0 \$0	d	
1493	Forecast		STEEL COORDINATION AT INTERIORS	Outstanding	90	\$0	0	\$0 \$(1	
1494	Forecast		DECORATIVE METAL PLATES AT EXTERIOR - PHASE 2	Outstanding	\$0	\$0		\$0 \$0	5	
1495	Forecast		DECORATIVE METAL PLATES AT EXTERIOR - PHASE 1	Outstanding	\$0	\$0	0	\$0 \$0	<u> </u>	
1496	Forecast		RADIANT MANIFOLDS	Outstanding	\$10,000	\$0	0	\$0 \$0		
1497	Forecast		MISC HVAC COORDINATION	Outstanding	\$50,000	\$50,000	0 \$50,0	00 \$0	5	
1498	Forecast		MISC MISC METALS COORDINATION	Outstanding	\$14,710	\$14,710	0 \$14,7	10 \$0	<u> </u>	
1500	Forecast		PAINT SCOPE COLOR CLARIFICATIONS	Outstanding	\$0	\$0	0	\$0 \$0	5	
1503	Forecast		PHASE 2 LOCKER DETAILS	Outstanding	\$0	\$0	0	\$0 \$0	<u> </u>	
1505	Forecast		PHASE 2 SLAB EDGE COORIDNATION	Outstanding	\$0	\$0	0	\$0 \$0	5	
1507	Forecast		ELECTRICAL PHASING	Outstanding	\$19,700	\$19,700	0 \$19,7	00 \$0	<u> </u>	
1510	Forecast		MISC. PLUMBING COORDINATION	Outstanding	\$46,238	\$46,238	0 \$46,2	38 \$0	5	
1512	Forecast		Credit PIPING CREDIT PER RFI-1061	Outstanding	\$0	\$0	0	\$0 \$0	<u> </u>	
1509	Forecast		MISC. ELECTRICAL COORIDNATION	Outstanding	\$50,000	\$50,000	0 \$50,0	00 \$0		
1513	Forecast		Credit REMOVED OUTLETS IN MECHANICAL WELLS	Outstanding	\$0	\$0	0	\$0 \$0	<u> </u>	
1514	Forecast		Credit PUMP SKIDS REQUIRE ONLY SINGLE POINT ELECTRICAL	Outstanding	\$0	\$0	0	\$0 \$0		
1515	Forecast		Credit PLUMBING PIPE REDUCTION PER RFI-1037	Outstanding	\$0	\$0	0	\$0 \$0		
1516	Forecast		Credit PLUMBING PIPE REDUCTION PER RFI-1035	Outstanding	\$0	\$0	0	\$0 \$0	D	
1517	Forecast		Credit PLUMBING WORK IN PCO-242 NOT COMPLETED	Outstanding	\$0	\$0	0	\$0)	
1518	Forecast		Credit LEFTOVER MISC METAL STEEL SECTIONS	Outstanding	\$0	\$0		\$0 \$0		
1519	Forecast		Credit FP EXTENDED COVERAGE HEADS IN CLASSROOMS REDUCED	Outstanding	\$0	\$0	0	\$0 \$0		
1520	Forecast		Credit FP PIPE SIZE REDUCTION PER FP SHOPS 210001-36.0	Outstanding	\$0	\$0	0	\$0)	
1521	Forecast		Credit CCD-105 CREDITS FOR PIPE SIZE REDUCTIONS	Outstanding	\$0	\$0	0	\$0		
1522	Forecast		Credit TEMP HVAC UNIT FOR LOCKER ROOM ELIMINATED	Outstanding	\$0	\$0	0	\$0 \$0		
1526	Forecast		ELEVATOR POSITION INDICATORS AND SURROUND	Outstanding	\$0	\$0		\$0 \$0		
1528	Forecast		PHASE 2 SITE EQUIP/WALL DELEGATED DESIGN	Outstanding	\$2,589	\$2,589	0 \$2,5			
1529	Forecast		SHADE HEAD SUPPORT	Outstanding	\$10,000	\$10,000	0 \$10,0			
1532	Forecast		CAMPUS WAYFINDING SIGNAGE	Outstanding	\$0	\$0	0	\$0 \$0		
1776	Forecast		Additional PV Budget	Outstanding	\$232,167	\$0	*	\$0 \$0	<u>4</u>	
			POTENTIAL EXPOSURE TOTAL			\$193,237	\$193,2			
								-\$151,947	'	0.32
PCO #			Description			Total				
4			PCCO 004			-\$362,945				
5			PCCO 005			\$259,500				
6			PCCO 006			\$164,120				
7			PCCO 007	i		\$0				
8			PCCO 008	i		\$881,684				
9		Ī	PCCO 009			\$737,748				
10		1	PCCO 010	 		\$201,003				
11		1	PCC0 011	 		\$730,506				
		1		+ +						
12		 	PCC0 012			\$125,000				
13		 	PCCO 013			\$768,306				
14		1	PCC0 014			\$941,369				
15			PCCO 015			\$1,325,236				
16		<u> </u>	PCCO 016			\$117,796			1	

Pretty Copy of SKA Exposure Log Amended Ver 2 from 1-11-23 Mtng

17 18 19	1				<u> </u>					
			PCC0 017			\$140,000]	
13			PCC0 018			\$428,563				
20			PCCO 019 PCCO 020			\$930,362 \$667,202				
21			PCCO 021			\$0				
22			PCCO 022			\$1,266,280				
23			PCCO 023			\$652,878				
24			PCC0 024			\$0				
25 26			PCCO 025 PCCO 026	+		\$600,407				
27			PCC0 027			\$225,000				
28			PCCO 028			\$141,688				
29			PCCO 029			\$1,350,426				
30			PCCO 030			\$54,674				
31 32			PCC0031 PCC0032			\$183,553 \$412,878				
33			PCC0032			\$1,168,218				
34			PCC0034			\$49,068				
35			PCC0035			\$207,870				
36			PCC0036			\$1,083,823				
37			PCC0037			\$223,785				
38		-	PCCO 038 PCCO 039			-\$2,377,280 \$504,230				
40	 	1	PCC0 040	+		\$454,417				
41		<u> </u>	PCC0 041		<u></u>	\$255,883				
42			PCCO 042			\$250,021				
43			PCCO 043			\$375,291				
44			PCCO 044			\$166,093				
45	L		PCCO 045 APPROVED COST TO DATE THRU PCCO 044			\$247,204 \$15,551,857				
			TOTAL PROJECTED EXPOSURE Orig GMP Final Projected Cost Variance From Base Line (1/3/23)			\$16,231,262 \$240,341,185 \$256,572,447 -\$151,947				
			INSURANCE CLAIMS							
	Field Condition	0	6.15.21 Trench Drain Incident (Insurance Claim)	Outstanding	\$0	\$0				
1152	Field Condition	0 INSUR-001	6.15.21 Trench Drain Incident (Insurance Claim) 6.15.21 Trench Drain Incident	Outstanding	\$0	\$297,160				
1152.0001		0 INSUR-001 INSUR-002	6.15.21 Trench Drain Incident (Insurance Claim)							
	Field Condition		6.15.21 Trench Drain Incident (Insurance Claim) 6.15.21 Trench Drain Incident	Outstanding	\$0	\$297,160				
1152.0001	Field Condition		6.15.21 Trench Drain Incident (Insurance Claim) 6.15.21 Trench Drain Incident Water damage outside snack bar counter on Cl	Outstanding	\$0	\$297,160 \$119,627				
1152.0001 1303	Field Condition Field Condition Field Condition		6.15.21 Trench Drain Incident (Insurance Claim) 6.15.21 Trench Drain Incident Water damage outside snack bar counter on Cl INSURANCE CLAIM TOTAL POTENTIAL CREDIT FOR INSURANCE CLAIMS 6.15.21 Trench Drain Incident - 1056 Recovery	Outstanding Submitted Outstanding	\$0 \$17,614	\$297,160 \$119,627 \$416,787				
1152.0001 1303 1152.0002	Field Condition Field Condition Field Condition Field Condition		6.15.21 Trench Drain Incident (Insurance Claim) 6.15.21 Trench Drain Incident Water damage outside snack bar counter on Cl INSURANCE CLAIM TOTAL POTENTIAL CREDIT FOR INSURANCE CLAIMS 6.15.21 Trench Drain Incident - 1056 Recovery Water damage outside snack bar counter on Cl - 1056 Recovery	Outstanding Submitted Outstanding Outstanding	\$0 \$17,614 \$0 \$0	\$297,160 \$119,627 \$416,787 -\$24,245 -\$12,099	0	50	\$9.247	44700
1152.0001 1303	Field Condition Field Condition Field Condition		6.15.21 Trench Drain Incident (Insurance Claim) 6.15.21 Trench Drain Incident Water damage outside snack bar counter on Cl INSURANCE CLAIM TOTAL POTENTIAL CREDIT FOR INSURANCE CLAIMS 6.15.21 Trench Drain Incident - 1056 Recovery Water damage outside snack bar counter on Cl - 1056 Recovery Standby Power Underground Damage (Insurance Claim)	Outstanding Submitted Outstanding	\$0 \$17,614	\$297,160 \$119,627 \$416,787 -\$24,245 -\$12,099 \$8,247	0	\$0	\$8,247	44788
1152.0001 1303 1152.0002 1303.0001	Field Condition Field Condition Field Condition Field Condition		6.15.21 Trench Drain Incident (Insurance Claim) 6.15.21 Trench Drain Incident Water damage outside snack bar counter on Cl INSURANCE CLAIM TOTAL POTENTIAL CREDIT FOR INSURANCE CLAIMS 6.15.21 Trench Drain Incident - 1056 Recovery Water damage outside snack bar counter on Cl - 1056 Recovery	Outstanding Submitted Outstanding Outstanding	\$0 \$17,614 \$0 \$0	\$297,160 \$119,627 \$416,787 -\$24,245 -\$12,099	0	\$0	\$8,247	44788
1152.0001 1303 1152.0002 1303.0001 1897	Field Condition Field Condition Field Condition Field Condition		6.15.21 Trench Drain Incident (Insurance Claim) 6.15.21 Trench Drain Incident Water damage outside snack bar counter on Cl INSURANCE CLAIM TOTAL POTENTIAL CREDIT FOR INSURANCE CLAIMS 6.15.21 Trench Drain Incident - 1056 Recovery Water damage outside snack bar counter on Cl - 1056 Recovery Standby Power Underground Damage (Insurance Claim) POTENTIAL CREDIT FOR INSURANCE CLAIMS TOTAL	Outstanding Submitted Outstanding Outstanding	\$0 \$17,614 \$0 \$0	\$297,160 \$119,627 \$416,787 -\$24,245 -\$12,099 \$8,247	0	\$0	\$8,247	44788
1152.0001 1303 1152.0002 1303.0001	Field Condition Field Condition Field Condition Field Condition Field Condition		6.15.21 Trench Drain Incident (Insurance Claim) 6.15.21 Trench Drain Incident Water damage outside snack bar counter on Cl INSURANCE CLAIM TOTAL POTENTIAL CREDIT FOR INSURANCE CLAIMS 6.15.21 Trench Drain Incident - 1056 Recovery Water damage outside snack bar counter on Cl - 1056 Recovery Standby Power Underground Damage (Insurance Claim) POTENTIAL CREDIT FOR INSURANCE CLAIMS TOTAL Deferred List Resilient Flooring Heat Welding - Phase 2 (VOID)	Outstanding Submitted Outstanding Outstanding Outstanding	\$0 \$17,614 \$0 \$0 \$4,800	\$297,160 \$119,627 \$416,787 -\$24,245 -\$12,099 \$8,247 -\$28,097	0	\$0	\$8,247	44788
1152.0001 1303 1152.0002 1303.0001 1897	Field Condition Field Condition Field Condition Field Condition Field Condition Field Condition Owner Directive		6.15.21 Trench Drain Incident (Insurance Claim) 6.15.21 Trench Drain Incident Water damage outside snack bar counter on Cl INSURANCE CLAIM TOTAL POTENTIAL CREDIT FOR INSURANCE CLAIMS 6.15.21 Trench Drain Incident - 1056 Recovery Water damage outside snack bar counter on Cl - 1056 Recovery Standby Power Underground Damage (Insurance Claim) POTENTIAL CREDIT FOR INSURANCE CLAIMS TOTAL Deferred List Resilient Flooring Heat Welding - Phase 2 (VOID) School Department Funding	Outstanding Submitted Outstanding Outstanding Outstanding Void	\$0 \$17,614 \$0 \$0 \$4,800	\$297,160 \$119,627 \$416,787 -\$24,245 -\$12,099 \$8,247 -\$28,097	0	\$0	\$8,247	44788
1152.0001 1303 1152.0002 1303.0001 1897	Field Condition Field Condition Field Condition Field Condition Field Condition Field Condition Owner Directive	O	6.15.21 Trench Drain Incident (Insurance Claim) 6.15.21 Trench Drain Incident Water damage outside snack bar counter on Cl INSURANCE CLAIM TOTAL POTENTIAL CREDIT FOR INSURANCE CLAIMS 6.15.21 Trench Drain Incident - 1056 Recovery Water damage outside snack bar counter on Cl - 1056 Recovery Standby Power Underground Damage (Insurance Claim) POTENTIAL CREDIT FOR INSURANCE CLAIMS TOTAL Deferred List Resilient Flooring Heat Welding - Phase 2 (VOID) School Department Funding Damaged Exit Sign Electrical Work	Outstanding Submitted Outstanding Outstanding Outstanding Void	\$0 \$17,614 \$0 \$0 \$4,800 \$1,000	\$297,160 \$119,627 \$416,787 -\$24,245 -\$12,099 \$8,247 -\$28,097	0	\$0	\$8,247	44788
1152.0001 1303 1152.0002 1303.0001 1897	Field Condition Field Condition Field Condition Field Condition Field Condition Field Condition Owner Directive Owner Directive Architect/Consultant Directive	O	6.15.21 Trench Drain Incident (Insurance Claim) 6.15.21 Trench Drain Incident Water damage outside snack bar counter on Cl INSURANCE CLAIM TOTAL POTENTIAL CREDIT FOR INSURANCE CLAIMS 6.15.21 Trench Drain Incident - 1056 Recovery Water damage outside snack bar counter on Cl - 1056 Recovery Standby Power Underground Damage (Insurance Claim) POTENTIAL CREDIT FOR INSURANCE CLAIMS TOTAL Deferred List Resilient Flooring Heat Welding - Phase 2 (VOID) School Department Funding Damaged Exit Sign Electrical Work CCD 442 New Lockers in lieu of Salvaged for Boys Team Rm. Ell1	Outstanding Submitted Outstanding Outstanding Outstanding Void Void Submitted Outstanding	\$0 \$17,614 \$0 \$0 \$0 \$4,800 \$1,000 \$0	\$297,160 \$119,627 \$416,787 -\$24,245 -\$12,099 \$8,247 -\$28,097 \$0	0	\$0	\$8,247	44788
1152.0001 1303 1152.0002 1303.0001 1897	Field Condition Field Condition Field Condition Field Condition Field Condition Field Condition Owner Directive Architect/Consultant Directive Architect/Consultant Directive	O	6.15.21 Trench Drain Incident (Insurance Claim) 6.15.21 Trench Drain Incident Water damage outside snack bar counter on Cl INSURANCE CLAIM TOTAL POTENTIAL CREDIT FOR INSURANCE CLAIMS 6.15.21 Trench Drain Incident - 1056 Recovery Water damage outside snack bar counter on Cl - 1056 Recovery Standby Power Underground Damage (Insurance Claim) POTENTIAL CREDIT FOR INSURANCE CLAIMS TOTAL Deferred List Resilient Flooring Heat Welding - Phase 2 (VOID) School Department Funding Damaged Exit Sign Electrical Work CCD 442 New Lockers in lieu of Salvaged for Boys Team Rm. Ell1 PR 145 Food Service Revisions Requests (VOID-SEE 1679.0002)	Outstanding Submitted Outstanding Outstanding Outstanding Void Submitted Outstanding Void	\$0 \$17,614 \$0 \$0 \$4,800 \$1,000 \$0 \$1,000	\$297,160 \$119,627 \$416,787 -\$24,245 -\$12,099 \$8,247 -\$28,097 \$0	0	\$0	\$8,247	44788
1152.0001 1303 1152.0002 1303.0001 1897 1011.0001	Field Condition Field Condition Field Condition Field Condition Field Condition Field Condition Owner Directive Owner Directive Architect/Consultant Directive	O	6.15.21 Trench Drain Incident (Insurance Claim) 6.15.21 Trench Drain Incident Water damage outside snack bar counter on Cl INSURANCE CLAIM TOTAL POTENTIAL CREDIT FOR INSURANCE CLAIMS 6.15.21 Trench Drain Incident - 1056 Recovery Water damage outside snack bar counter on Cl - 1056 Recovery Standby Power Underground Damage (Insurance Claim) POTENTIAL CREDIT FOR INSURANCE CLAIMS TOTAL Deferred List Resilient Flooring Heat Welding - Phase 2 (VOID) School Department Funding Damaged Exit Sign Electrical Work CCD 442 New Lockers in lieu of Salvaged for Boys Team Rm. Ell1	Outstanding Submitted Outstanding Outstanding Outstanding Void Submitted Outstanding Void	\$0 \$17,614 \$0 \$0 \$0 \$4,800 \$1,000 \$0	\$297,160 \$119,627 \$416,787 -\$24,245 -\$12,099 \$8,247 -\$28,097 \$0	0	\$0	\$8,247	44788
1152.0001 1303 1152.0002 1303.0001 1897 1011.0001	Field Condition Field Condition Field Condition Field Condition Field Condition Field Condition Owner Directive Architect/Consultant Directive Architect/Consultant Directive	O	6.15.21 Trench Drain Incident (Insurance Claim) 6.15.21 Trench Drain Incident Water damage outside snack bar counter on Cl INSURANCE CLAIM TOTAL POTENTIAL CREDIT FOR INSURANCE CLAIMS 6.15.21 Trench Drain Incident - 1056 Recovery Water damage outside snack bar counter on Cl - 1056 Recovery Standby Power Underground Damage (Insurance Claim) POTENTIAL CREDIT FOR INSURANCE CLAIMS TOTAL Deferred List Resilient Flooring Heat Welding - Phase 2 (VOID) School Department Funding Damaged Exit Sign Electrical Work CCD 442 New Lockers in lieu of Salvaged for Boys Team Rm. Ell1 PR 145 Food Service Revisions Requests (VOID-SEE 1679.0002)	Outstanding Submitted Outstanding Outstanding Outstanding Void Submitted Outstanding Void	\$0 \$17,614 \$0 \$0 \$4,800 \$1,000 \$0 \$1,000	\$297,160 \$119,627 \$416,787 -\$24,245 -\$12,099 \$8,247 -\$28,097 \$0	0	\$0 \$0	\$8,247	11/1/2022
1152.0001 1303 1152.0002 1303.0001 1897 1011.0001	Field Condition Field Condition Field Condition Field Condition Field Condition Field Condition Owner Directive Architect/Consultant Directive Architect/Consultant Directive Architect/Consultant Directive	O	6.15.21 Trench Drain Incident (Insurance Claim) 6.15.21 Trench Drain Incident Water damage outside snack bar counter on Cl INSURANCE CLAIM TOTAL POTENTIAL CREDIT FOR INSURANCE CLAIMS 6.15.21 Trench Drain Incident - 1056 Recovery Water damage outside snack bar counter on Cl - 1056 Recovery Standby Power Underground Damage (Insurance Claim) POTENTIAL CREDIT FOR INSURANCE CLAIMS TOTAL Deferred List Resilient Flooring Heat Welding - Phase 2 (VOID) School Department Funding Damaged Exit Sign Electrical Work CCD 442 New Lockers in lieu of Salvaged for Boys Team Rm. E111 PR 145 Food Service Revisions Requests (VOID-SEE 1679.0002) PR 145 Food Service Revisions Requests - Cooler Replacement (VOID-SEE 1	Outstanding Submitted Outstanding Outstanding Outstanding Void Submitted Outstanding Void Submitted Outstanding Void	\$0 \$17,614 \$0 \$0 \$4,800 \$1,000 \$0 \$10,000 \$51,646	\$297,160 \$119,627 \$416,787 -\$24,245 -\$12,099 \$8,247 -\$28,097 \$0 \$217 \$30,000 \$25,083 \$56,856				
1152.0001 1303 1152.0002 1303.0001 1897 1011.0001	Field Condition Field Condition Field Condition Field Condition Field Condition Field Condition Owner Directive Architect/Consultant Directive Architect/Consultant Directive Architect/Consultant Directive	O	6.15.21 Trench Drain Incident (Insurance Claim) 6.15.21 Trench Drain Incident Water damage outside snack bar counter on Cl INSURANCE CLAIM TOTAL POTENTIAL CREDIT FOR INSURANCE CLAIMS 6.15.21 Trench Drain Incident - 1056 Recovery Water damage outside snack bar counter on Cl - 1056 Recovery Standby Power Underground Damage (Insurance Claim) POTENTIAL CREDIT FOR INSURANCE CLAIMS TOTAL Deferred List Resilient Flooring Heat Welding - Phase 2 (VOID) School Department Funding Damaged Exit Sign Electrical Work CCD 442 New Lockers in lieu of Salvaged for Boys Team Rm. Ell1 PR 145 Food Service Revisions Requests (VOID-SEE 1679.0002) PR 145 Food Service Revisions Requests - Cooler Replacement (VOID-SEE 1 PR 145 Amended Food Service Revisions Requests	Outstanding Submitted Outstanding Outstanding Outstanding Void Submitted Outstanding Void Submitted Outstanding Void	\$0 \$17,614 \$0 \$0 \$4,800 \$1,000 \$0 \$10,000 \$51,646	\$297,160 \$119,627 \$416,787 -\$24,245 -\$12,099 \$8,247 -\$28,097 \$0 \$217 \$30,000 \$25,083 \$56,856				
1152.0001 1303 1152.0002 1303.0001 1897 1011.0001 1595 1768 1679 1679.0001 1679.0002	Field Condition Field Condition Field Condition Field Condition Field Condition Field Condition Owner Directive Architect/Consultant Directive Architect/Consultant Directive Architect/Consultant Directive Architect/Consultant Directive	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	6.15.21 Trench Drain Incident (Insurance Claim) 6.15.21 Trench Drain Incident Water damage outside snack bar counter on Cl INSURANCE CLAIM TOTAL POTENTIAL CREDIT FOR INSURANCE CLAIMS 6.15.21 Trench Drain Incident - 1056 Recovery Water damage outside snack bar counter on Cl - 1056 Recovery Standby Power Underground Damage (Insurance Claim) POTENTIAL CREDIT FOR INSURANCE CLAIMS TOTAL Deferred List Resilient Flooring Heat Welding - Phase 2 (VOID) School Department Funding Damaged Exit Sign Electrical Work CCD 442 New Lockers in lieu of Salvaged for Boys Team Rm. E111 PR 145 Food Service Revisions Requests (VOID-SEE 1679.0002) PR 145 Food Service Revisions Requests - Cooler Replacement (VOID-SEE 1 PR 145 Amended Food Service Revisions Requests PV Overage Covid Claims	Outstanding Submitted Outstanding Outstanding Outstanding Outstanding Void Submitted Outstanding Void 679.0002 Void Outstanding	\$0 \$17,614 \$0 \$0 \$4,800 \$1,000 \$0 \$10,000 \$51,646	\$297,160 \$119,627 \$416,787 -\$24,245 -\$12,099 \$8,247 -\$28,097 \$0 \$217 \$30,000 \$25,083 \$56,856		\$0	\$0	11/1/2022
1152.0001 1303 1152.0002 1303.0001 1897 1011.0001	Field Condition Field Condition Field Condition Field Condition Field Condition Field Condition Owner Directive Architect/Consultant Directive Architect/Consultant Directive Architect/Consultant Directive	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	6.15.21 Trench Drain Incident (Insurance Claim) 6.15.21 Trench Drain Incident Water damage outside snack bar counter on Cl INSURANCE CLAIM TOTAL POTENTIAL CREDIT FOR INSURANCE CLAIMS 6.15.21 Trench Drain Incident - 1056 Recovery Water damage outside snack bar counter on Cl - 1056 Recovery Standby Power Underground Damage (Insurance Claim) POTENTIAL CREDIT FOR INSURANCE CLAIMS TOTAL Deferred List Resilient Flooring Heat Welding - Phase 2 (VOID) School Department Funding Damaged Exit Sign Electrical Work CCD 442 New Lockers in lieu of Salvaged for Boys Team Rm. Ell1 PR 145 Food Service Revisions Requests (VOID-SEE 1679.0002) PR 145 Food Service Revisions Requests - Cooler Replacement (VOID-SEE 1 PR 145 Amended Food Service Revisions Requests	Outstanding Submitted Outstanding Outstanding Outstanding Void Submitted Outstanding Void Submitted Outstanding Void	\$0 \$17,614 \$0 \$0 \$4,800 \$1,000 \$0 \$10,000 \$51,646	\$297,160 \$119,627 \$416,787 -\$24,245 -\$12,099 \$8,247 -\$28,097 \$0 \$217 \$30,000 \$25,083 \$56,856				

Pretty Copy of SKA Exposure Log Amended Ver 2 from 1-11-23 Mtng