## THE GALANTE ARCHITECTURE STUDIO

PLANNING BOARD





## TOWN OF BELMONT


## BELMONT RINK & SPORTS FACILITY

September 19, 2023

The Galante Architecture Studio 146 Mount Auburn Street Cambridge, MA 02138

P: (617) 576-2500

galantearchitecture.com














# Proposed

























#### Tree 7

Red Norway Maple, Acer platanoides

Size: 18 Caliper Inches

Observation: Poor condition, bare branching/

signs of distress, invasive species

#### Tree 6

Red Maple, Acer rubrum Size: 16.9 Caliper Inches

Observation: Poor condition, bare branching/


signs of distress

#### Tree 5

Eastern Red Cedar, Juniperus virginiana

Size: 18 Caliper Inches

Observation: Poor condition, bare branching



#### Tree 3

Red Maple, Acer rubrum Size: 27 Caliper Inches

Observation: Poor condition, bare branching/

signs of distress

#### Tree 1

Northern Red Oak, Quercus rubrum

Size: 20 Caliper Inches

Observation: Poor condition, excessive rootball compaction, bare branching/signs of distress


#### Tree 2

Red Norway Maple, Acer platanoides Size: 24 Caliper Inches Observation: Moderate condition, invasive species

#### Tree 4


Northern Red Oak, Quercus rubrum Size: 40 Caliper Inches Observation: Good condition, healthy canopy, intact crown, trunk has grown around/absorbed fence and needs repair

#### Key Plan:











# Proposed Renders
























# Building Removal Site Setup & Logistics







#### Legend




#### Notes





#### Legend




#### Notes





#### Legend



#### Notes







