EXHIBIT # 1
EXISTING AIR CONDITIONER CONDENSER LOCATED IN SAME SPOT BEFORE FIRE. LOSS. PRE-EXISTING

EXHIBIT # 2
EXISTING AIR CONDITIONER LOCATION BEFORE FIRE LOSS.
PRE EXISTING

EXHIBIT # 3
Goodman
REAR VIEW
REPLACEMENT
AIR CONDITIONING
CONDENSER IN
SAME LOCATION
AS BEFORE

EXHIBIT #4
EXACT SAME LOCATION AS BEFORE
CONDENSER UNIT
PRE EXISTING LOCATION

FRONT VIEW
PRE EXISTING
EXHIBIT #3


SIDE VIEW
LEFT
PRE EXISTING
EXHIBIT # 6

EXHIBIT # 7
CURRENT

EXHIBIT # 8
CURRENT

EXHIBIT # 9
CURRENT



HomeWrap
HomeWrap
HomeWrap