



TOWN OF BELMONT, MA

Figure 11
Dye Test Locations
Sub-Catchment Area 10-2 (Winn's Brook)

Illicit Discharge Investigations
November 2017

1 inch = 100 feet



LEGEND

- 2017 Dye Test Locations (Yellow star)
- 2016-2017 Sample Locations (Yellow star)
- Drainage System**
 - Drain - New/Rehabilitated (Blue line with arrow)
 - Drain - Past CCTV but No Past Rehabilitation (Light blue line with arrow)
 - Drain - No past CCTV/Rehabilitation (Cyan line with arrow)
 - Catch Basin Outlet Drain (Light blue line)
 - Drain Manhole (Blue square)
 - Catch Basin (Blue square)
- Sewer System**
 - Sewer - New/Rehabilitated (Red line with arrow)
 - Sewer - Past CCTV but No Past Rehabilitation (Light red line with arrow)
 - Sewer - No Past CCTV/Rehabilitation (Pink line with arrow)
 - Sewer Manhole (Red circle)
- Buildings**
 - Buildings without Sewer Service Rehabilitation (Grey outline)
 - Building with Rehabilitated Sewer Service (Green outline)