





warped boards on garage




Rot on garage





Hot on gauze trim



missing boards on garage







Example of railing style for front steps





side of house drainage issue
- replace w/ brick



unstable & dangerous
path w/ slate

- replace w/ brick
- repurposed slate to use w/ brick
on front steps



Back
walkway