

# TOWN OF BELMONT, MA

Figure 10  
Dye Test Locations  
Sub-Catchment Area 8-5 (Wellington Brook)

Illicit Discharge Investigations  
November 2017

1 inch = 125 feet



## LEGEND

- 2017 Dye Test Locations
- 2016-2017 Sample Locations
- Drainage System
  - Drain - New/Rehabilitated
  - Drain - Past CCTV but No Past Rehabilitation
  - Drain - No Past CCTV/Rehabilitation
  - Catch Basin Outlet Drain
  - Drain Manhole
  - Catch Basin
- Sewer System
  - Sewer - New/Rehabilitated
  - Sewer - Past CCTV but No Past Rehabilitation
  - Sewer - No Past CCTV/Rehabilitation
  - Sewer Manhole
- Buildings
  - Buildings without Sewer Service Rehabilitation
  - Building with Rehabilitated Sewer Service