



WAVERLEY STREET

ORCHARD STREET

GLENDALE ROAD


COMMON STREET

TOWN OF BELMONT, MA

Figure 9
Dye Test Locations
Sub-Catchment Area 8-2 (Wellington Brook)

Illicit Discharge Investigations
November 2017

1 inch = 50 feet



LEGEND

2017 Dye Test Locations

2016-2017 Sample Locations

Drainage System

Drain - New/Rehabilitated

Drain - Past CCTV but No Past Rehabilitation

Drain - No Past CCTV/Rehabilitation

Catch Basin Outlet Drain

Drain Manhole

Catch Basin

Sewer System

Sewer - New/Rehabilitated

Sewer - Past CCTV but No Past Rehabilitation

Sewer - No Past CCTV/Rehabilitation

Sewer Manhole

Buildings

Buildings without Sewer Service Rehabilitation

Building with Rehabilitated Sewer Service

ND

NS

DRY

>20,000

18D047

24D039

25D028

24D017

#323

#165

#169

#171

#315

#177

#185

#185

#193

#181

#178

#185

#182

#187

#150

#150

#14

#14

#22

#22

#30

#30

#34

#34

#156

#156

#164

#164

#10

#16

#24

#30