




BELMONT, MA
STORM WATER SAMPLING AND ANALYSIS PROGRAM
WELLINGTON BROOK TRIBUTARY AREA

JB-209
JULY 2007

FIGURE 3
CCTV INSPECTION FOR SEWER AND STORM DRAIN
OVER 5000 FECAL COLONIES PER 100mL