

BELMONT, MA

STORM WATER SAMPLING AND
ANALYSIS PROGRAM
WELLINGTON BROOK TRIBUTARY AREA

JB-209
JULY 2007

FIGURE 2

CCTV INSPECTION FOR SEWER AND STORM DRAIN
OVER 1000 FECAL COLONIES PER 100mL