

# Belmont Middle & High School Project Update

September 2019



Photo 1 – Demolition Progress of Pool Structure.



Photo 2 – Demolition Progress of Locker-Room Structure / Framing, Insulation and Plywood of Field House Exterior Wall for Weather Protection.





Photo 3 – Completion of Demolition and Installation of Field House Weather Barrier Plywood.



Photo 4 - Mobilization of Pile Driving Equipment.



Photo 5 - Completion of Foundation Removal.





Photo 6 – Installation of Pile's for Foundation Elements.



Photo 7 – Installation of Pile's for Foundation Elements.

# October 2019 Look-Ahead

- Excavation of Foundation Elements – Pile Caps & Grade Beams.
- Cutting and Preparing Piles for Reinforcement.
- Layout, Reinforcing & Forming Foundation Elements – Pile Caps & Grade Beams.
- Installation of Anchor Bolts and Placement of Concrete for Foundation Elements.